TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48017716
Order No. / Reference: 26745046
Inspection date: 8 Oct 2026

Manufacturer: Mercedes-Benz	Model: GLB 200 d 8G-DCT Entry
VIN: W1N4M1CB1RW356372	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLB 200 d 8G-DCT Entry	
Vehicle Identification number	W1N4M1CB1RW356372
Mileage (Read)	118,947 km
First registration	25 Mar 2024
Number of holders	1
Next periodical technical inspection (read from ZBI)	03/2027
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	KOSMOSSCHWARZ
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	109 Tag(e)
Last service on / at	07/2025 at 73,386 km		
Key is / should be	2 / 2	**FZG documents**	ZB#1+2 (B+S) was available (copy)
		Letter No.	HB196649
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / AHY 00185		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,230 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Light alloy	Semperit	6mm / 6mm
2)	215/65 R17 99H	Winter tyres on Light alloy	Semperit	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Summer tyres (Without wheel rim)	Michelin	4mm / 4mm
2)	215/65 R17 99V	Summer tyres (Without wheel rim)	Michelin	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind (The roller blind for the storage compartment in the center console offers you an elegant privacy screen made of high-quality material. This looks good, the interior appears even tidier, and everything important is within easy reach. Typical everyday items such as a smartphone, wallet, or various keys fit into the practical storage compartment.)
- Active Lane Keeping Assist
- Rear armrest
- Automatic passenger airbag deactivation
- Heated exterior mirrors on the left and right, electrically adjustable from the inside (with aspherically curved mirror glass and integrated turn signal light)
- On-board computer
- Chrome trim strip
- Roof rails in polished aluminum
- Double cup holder
- Third brake light in LED technology
- EASY-PACK tailgate (electrically opening and closing tailgate - switch for electrically opening the tailgate in the driver's door - switch for electrically closing the tailgate at the bottom edge of the tailgate - manual cargo cover for covering the cargo area)
- ECO start/stop function
- Door sills with "Mercedes-Benz" lettering
- Electronic Stability Program (ESP)
- Electric window regulators (4)
- Speed Limit Assist (The Speed Limit Assist makes it easy for you to comply with the regulations and avoid unnecessary speeding tickets. The system shows what is permitted: It can detect the current speed limit via the camera and display it in the instrument cluster. Additional restrictive signs for special weather conditions such as wet conditions are also detected.)
- Communication module (LTE) for the use of Mercedes me connect services (communication module with permanently installed SIM card of the mobile communications standard LTE - two mobile communications antennas)
- Cargo area cover (roller blind) (stores under the cargo floor)
- Steering wheel: Multifunction sports steering wheel in leather (The elegant leather covering makes the multifunction sports steering wheel even more premium, turning it into a highlight of the interior. As a driver, you benefit in two ways: What looks good must also feel good. Among other things, the touch control buttons on the left and right operate a variety of functions, from navigation and telephony to entertainment. Last but not least, you can set the speed and distance control: Everything under control without taking your hands off the steering wheel.)
- Hood with power domes
- Navigation accessories: Extended MBUX functions (personalization (profiles) and prediction functions - LINGUATRONIC with natural language understanding - activation via "Hey Mercedes" - Wi-Fi hotspot - internet radio)
- Adaptive Highbeam Assist
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Sidebag for driver and front passenger (combined thorax/ pelvisbag)
- Airbag: Windowbags
- Active Brake Assist
- Anti-lock braking system (ABS)
- ATTENTION ASSIST (can detect typical signs of fatigue via steering behavior and can warn the driver of impending microsleep)
- Basic services (accident and breakdown management, maintenance management, remote diagnostics, remote vehicle diagnostics, software update (model dependent), individual consumption display in the app)
- Diesel particulate filter
- Tachometer
- DYNAMIC SELECT (Simply drive the way you want. At the touch of a button, DYNAMIC SELECT offers various driving programs that predefine, for example, the engine, transmission, suspension, or steering. Sport mode provides a decidedly dynamic driving experience, while the basic Comfort program offers a very balanced ride. ECO mode, on the other hand, prioritizes maximum efficiency, saving fuel and money.)
- Chassis: Comfort chassis
- Velour floor mats
- Transmission: 8G-DCT dual-clutch automatic transmission, 8-speed
- Rear window heated
- rear window wiper
- Interior headliner fabric crystal grey
- Climate: THERMATIC automatic climate control (1-zone climate control - automatically controlled air distribution - recirculation function - tunnel mode in conjunction with navigation system - fine dust filter)
- Headrests (2)
- Rear headrests (3)
- Paint finish: Solid
- LED High Performance Headlights (LED High Performance headlights offer you greater safety at night and a distinctive, striking look. Thanks to LED technology, they illuminate the road better than conventional headlights - with lower energy consumption.)
- Steering column mechanically adjustable lengthwise and heightwise.
- Mercedes-Benz Emergency Call System (The Mercedes-Benz Emergency Call System can provide a crucial time advantage in an emergency. A communication module with its own SIM card automatically triggers an emergency call upon detection of an accident, which can shorten the time until emergency services arrive. The emergency call can also be triggered manually to organize assistance.)

- Package: Light and Sight Package (Overhead control unit with 4 light elements (including glasses compartment) - Interior light/reading light rear in mounting plate (rear/left/right) - Touchpad lighting (front) - Reading lights (front/left/right), console ambient light - Make-up lights (front/left/right) - Signal and ambient light - Exit signal light (front/left/right) - Footwell lighting (front/left/right) - Cupholder/storage compartment lighting - Occasional storage compartment lighting)
- Upholstery: ARTICO leatherette/fabric
- Radio accessories: Digital radio
- Tire pressure monitoring system (TPMS)
- Wheels: 43.2 cm (17") light alloy wheels in 5-twin-spoke design (aerodynamically optimized, painted black and polished with 215/65 R17 tires on 6.5J x 17 ET44)
- Power steering
- Seats: Comfort seats (the comfort seat offers you good long-distance comfort and comprehensive adjustments in length and height. You can also adjust the seat cushion angle and even extend it.)
- Front and rear underride protection (visual underride protection)
- Pre-installation for digital key handover (Share your vehicle with friends and family members more easily than ever before – no matter where you are. You retain full control and decide conveniently via app whether you consent to its use. You can also unlock your vehicle remotely via the mobile application. Only then will a stored key be activated. Service is free of charge for 3 years from activation.)
- Package: Entry (00U Remote Services 873 Heated seats for driver and front passenger 942 Load compartment package B51 TIREFIT PBG MBUX Navigation Premium)
- Package: Seating comfort (height adjustment for passenger seat - seat cushion tilt adjustment for driver and passenger seats - seat cushion depth adjustment for improved seating comfort through a 60 mm wider thigh support area - specific seat design)
- Package: USB Package Plus (1 USB-C port in the storage compartment in the front part of the center console, fast charging and suitable for data transfer; 2 USB-C ports under the front center armrest, fast charging and suitable for data transfer; 2 USB-C ports for the rear seats at the back of the center armrest, fast charging; 12V socket in the storage compartment in the front part of the center console)
- Rear view camera
- Windscreen wipers with rain sensor
- Seats: Rear seat backrests foldable (in a 40/20/40 ratio and adjustable to 7 tilt positions)
- Seats: Rear seat backrests foldable (40/20/40 split ratio)
- 12V power outlet in center console
- Cruise control (Drive relaxed and fuel-efficiently, especially on longer journeys. Simply select your desired speed and your vehicle will regulate it. In addition to the cruising speed, the speed limiter helps you maintain a maximum speed. This increases road safety and protects you from expensive speeding tickets.)
- High-visibility vest for drivers
- Immobiliser
- Decorative elements Star Pattern

Extra equipment

- Active Distance Assist DISTRONIC (radar sensor in the radiator grille - automatically acting assistance system - active up to a speed of 160 km/h - visual and acoustic warning if you as the driver need to intervene - depending on the driving program, the vehicle accelerates faster or slower to the desired speed - detected speed limits can be conveniently adopted by pressing a button on the steering wheel (only in conjunction with Traffic Sign Assist or Speed Limit Assist))
- Package: Entry Advanced (4-way lumbar support - Mirror package (automatically dimming interior mirror, electrically folding exterior mirrors) - Parking package with reversing camera (Active Parking Assist with PARKTRONIC) - EASY-PACK tailgate (electrically opening and closing tailgate, switch for electrically opening the tailgate in the driver's door, switch for electrically closing the tailgate at the bottom edge of the tailgate, manual load compartment cover))
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)
- Climate control: THERMOTRONIC automatic climate control (two zones with individually adjustable temperature for driver and front passenger - automatic control of temperature, air volume and air distribution (Auto button) - sensors maintain the desired climate - fine dust activated carbon filter - dew point sensor prevents window fogging and enables energy-efficient climate control - rear center vents for improved climate comfort in the rear - residual heat button for heating/ventilation when the vehicle is switched off (country-dependent))
- Fully digital instrument display (high-resolution 10.25" display)
- Paint finish: Metallic
- Type designation removed from luggage compartment lid

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were available. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Documents	Service book (letzter Servicenachweis 16.07.25 73386km) - No evidence - No deduction
2	Seat - front	Seat base trim - left side (Netz gerissen) - Broken / torn - Replace
3	Door - front right side	Door - Scratch(es) - Smart repair
4	Rear bumper	Rear bumper - Scratch(es) - Smart repair
5	Wheel / tyres	Alloy rim - front right side - Corrosion - Loss in value
6	Interior	Interior - Soiled - Conditioning
7	Trim / covers	Door trim - rear left side (+ Reifenabdruck) - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Front, Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

-Der montierte Reifensatz ist kein Bestandteil des Auslieferungsumfangs.
-Felgen der Winterräder gehören zu den Sommerreifen.

- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres




Figure 18: Navigation




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Damage 2: Seat - front: Seat base trim - left side (Netz gerissen) - Broken / torn - Replace



Damage 2: Seat - front: Seat base trim - left side (Netz gerissen) - Broken / torn - Replace



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair




Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Wheel / tyres: Alloy rim - front right side - Corrosion - Loss in value




Damage 5: Wheel / tyres: Alloy rim - front right side - Corrosion - Loss in value



Damage 6: Interior: Interior - Soiled - Conditioning




Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 6: Interior: Interior - Soiled - Conditioning



Damage 7: Trim / covers: Door trim - rear left side (+ Reifenabdruck) - Broken / torn - Replace



Damage 7: Trim / covers: Door trim - rear left side (+ Reifenabdruck) - Broken / torn - Replace




Damage 7: Trim / covers: Door trim - rear left side (+ Reifenabdruck) - Broken / torn - Replace



Accident 1: Front, Side right



Accident 1: Front, Side right



Accident 1: Front, Side right



Accident 1: Front, Side right



Accident 1: Front, Side right