SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-DNZ-174

2-DNZ-174 · ST-line 125pk 92kw mHEV M6 5d · 20 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DNZ-174
Manufacturer	FORD
Model	Focus
Model Versions	ST-line 125pk 92kw mHEV M6 5d
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2023
KW	92

Fuel Type	Hybrid Gasoline
VIN	WF0NXXGCHNPL83822
Cylinder Capacity	999 cm3
Transmission Type	Handmatig geschakelde transmissie
First Admission	10-05-2023
Odometer	91.603 Km
Numer Of Keys	2
Interior	Black
Number Headrests	5

Images




























Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel – Heated
Electric rear windows	Windscreen – Heated

Condition

Condition exterior	Adequate	Maintenance Remarks	Bandenspanning controleren
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance Unknown			

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Continental	215 mm	50 mm	17 inch	All Season
Rear Left	5 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	5 mm	Continental	215 mm	50 mm	17 inch	All Season
Rear Right	5 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Small scratch(es)	Touch-up / Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No