AUDI Q4 E-TRON

Vehicle information

Make:	**AUDI**	License:	**2CMZ356**
Gearbox:		Body color:	
Model:	**Q4 E-TRON**	VIN:	**WAUZZZFZXNP056658**
Fuel type:		Power:	**125 kW**
Version:	**BEV 55KWH 35 S LINE AUTO**	First registration	**22/09/2022**
Mileage:	**147470 km**	N° of doors:	


Damage summary

Interior	1
Left	2
Rear	5
Right	3
Roof & others	1

Commercial pictures
































VIN equipment according to manufacturer information

Airbag	Central consol	Distance control	Electric adjustable mirrors
GPS	Isofix	Power steering	Rims alloy
Roof bars	Seats F heated (ECS&B)	Steering wheel leather	Steering wheel multifunctional
Telephone	Windows electric functioning		


Options according to the inspector

GPS	**Yes**

Damages

Alloy rim FL polished
Scratch(es)
Repair and paint (complete)
Left







Alloy rim RL polished
Scratch(es)
Repair and paint (complete)
Left




Alloy rim RR polished
Scratch(es)
Repair and paint (complete)
Right





Bodywork
Damaged
Acceptable
Roof & others












Bumper moulding R
Scratch(es)
Paint
Rear




Charging cable (normal)
Missing
Check
Rear



Compressor
Missing
Replace
Rear



Door FR
Dent(s)
Repair and paint (complete)
Right









Interior
Damaged
Acceptable
Interior








Luggage compartment cover
Missing
Replace
Rear



Tyre repair kit
Missing
Replace
Rear



Wing trim RR
Scratch(es)
Paint
Right





Tyres

Front Left
Summer
Aluminium
235/50/20/104/V
Continental
4.0 mm
Front Right
Summer
Aluminium
235/50/20/104/V
Continental
4.0 mm
Rear Left
Summer
Aluminium
255/45/20/105/W
Continental
7.0 mm
Rear Right
Summer
Aluminium
255/45/20/105/W
Continental
7.0 mm

Checks

Battery level	**40**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**No**
Maintenance	**OK**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**1**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**Yes**
Repair kit	**No**	Reset to factory settings	**No, not possible**
State of Health	**88.0**	Type of Maintenance book	**Digital maintenance**

VIN detail - *If the description in the language of your choice is not available, the French description is shown*

2 ports USB-C à l'avant	ABS	Accoudoir central AV
Acoustic Parking System (APS) à l'arrière	Airbag central à l'avant	Airbag conducteur
Airbag passager	Airbags latéraux intégrés aux sièges à l'avant	Airbags rideaux
Allumage / extinction automatique des feux	Audi Sound System	Boitiers des rétroviseurs extérieur dans la couleur carrosserie
Ciel de toit en tissu gris	Climatisation électronique 3 zones	Contours de fénêtres en aluminium
Désactivation manuelle de l'airbag passager	Direction assistée	Dossier de la banquette arrière rabattable en 2 parties (40:60)
Eclairage intérieur	Encarts décoratifs en noir laqué 'Soft touch'	ESP (système électronique de stabilité)
Feux arrière LED	Feux de jour AV	Fixation pour siège-enfant ISOFIX pour le siège du passager avant
Fixations ISOFIX et Top Tether sièges arrière	Fonction coming home - leaving home	Garantie 3 ans/120.000 km
Gilet de sécurité	Haut-parleurs à l'avant (4)	Hayon à ouverture et fermeture électrique
Interface Bluetooth (téléphonie et audio)	JAV 5 branches design Y 8J/9Jx20''+235/50 R20 100T & 255/45 R20 101T	JAV 5 branches design Y gris graphite 8J/9Jx20''+235/50 R20 100T & 255/45 R20 101T
Kit Navigation: MMI GPS Plus+Virt.cock.+rec.pann.	Limiteur de vitesse	Outillage de bord
Pack Business	Pack Business (convention A/B/C/D/E/F/H/P)	Pack interior Luxury (cuir/similicuir-brun)
Pare-brise en vitrage isolant	Peinture unie	Phares avant LED
Prise 12V à l'arrière	Radio numérique (DAB)	Railing de toit façon aluminium
Reconnaissance des panneaux routiers	Rétroviseur intérieur jour/nuit manuelle	Rétroviseurs extérieurs électriques et chauffants
Sièges avant chauffants	Suspension sport	Système de contrôle de la pression des pneus
Tapis de sol complémentaires avant et arrière	Tissu 'Index'	Transponder (ATR1)
Trousse de secours	Trousse de secours avec triangle présignalisation	Version non-fumeur
Vitrage isolant	Vitres électriques avant et arrière	Vitres latérales (à partir montant B) et lunette arrière assombris
Volant gainé de cuir	Volant multifonctions	Volant multifonctions Plus en cuir à 4 branches avec basculeurs (+/-) aplati en bas et en haut

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.