MACADAM
Renault Arkana '21



Vehicle information

Make:	**Renault**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**Arkana '21**	VIN:	**VF1RJL002UC417094**
Fuel type:	**Hybrid Petrol**	Power:	**107 kW**
Version:	**Arkana E-Tech 145 Techno**	First registration	**10/07/2023**
Mileage:	**194158 km**	N° of doors:	

Damage summary

Front	4
Interior	2
Left	4
Rear	2
Right	3
Roof & others	1

Commercial pictures


























Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Radio multimedia	**Yes**	Rear view camera	**Yes**	Telephone equipment	**Yes**

Damages

Alloy rim FL

Scratch(es)

Repair and paint (complete)

Left





Alloy rim RR

Scratch(es)

Repair and paint (complete)

Right





Boot lid covering R

Scratch(es)

Smart repair

Rear





Bumper F

Scratch(es)

Repair and paint (complete)

Front





Bumper trim F
Scratch(es)
Replace
Front





Bumper trim R
Scratch(es)
Replace
Rear




Door FL
Dent(s) and scratch(es)
Repair and paint (complete)
Left




Door FR
Dent(s) and scratch(es)
Repair and paint (complete)
Right

Door frame RR
Scratch(es)
Repair and paint (partial)
Right




Door RL
Scratch(es)
Repair and paint (complete)
Left





Inner door handle
Missing
Replace
Interior




LED headlight L
Scratch(es)
Replace
Front




Parking sensor F
Missing
Replace
Front




Roof
Deformed / Strained
Repair and paint (complete)
Roof & others




User's manual
Missing
Replace
Interior

Wheel arch cover moulding FL
Scratch(es)
Replace
Left





Tyres

Front Left
Summer
215/55/18/99/V
Michelin
5.2 mm
Front Right
Summer
215/55/18/99/V
Michelin
5.2 mm
Rear Left
Summer
215/55/18/99/V
Michelin
6.1 mm
Rear Right
Summer
215/55/18/99/V
Michelin
5.8 mm

Checks

Certificate of Conformity	**No**	CO2 Emission	**97**
Digital maintenance	**Yes**	GPS storage	**HD**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**0**
Number of keys total	**2**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**N/A**	User's manual	**No**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.