TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 47006999
Order No. / Reference: 26768281
Inspection date: 11 Aug 2026

Manufacturer: Ford	Model: Puma 1.5 EcoBlue ST-LINE
VIN: WF02XXERK2NY65490	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Puma 1.5 EcoBlue ST-LINE	
Vehicle Identification number	WF02XXERK2NY65490
Mileage (Read)	109,207 km
First registration	17 Mar 2022
Number of holders	1
Next periodical technical inspection	04/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Frost-Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	53 %
Last service on / at	11/2025 at 95,191 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH429889
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BUA 00044		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,845 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99H	Winter tyres on Light alloy	Michelin	4mm / 4mm
2)	215/60 R16 99H	Winter tyres on Light alloy	Michelin	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Ambient lighting
- Electrically adjustable, heated and folding exterior mirrors
- Tires: Tire repair kit
- Body styling kit
- third brake light
- Diesel particulate filter
- Tachometer
- Driver information system with on-board computer
- Chassis: Sport-tuned chassis
- Electric windows front and rear
- Ford Easy Fuel
- Ford MegaBox
- FordPass Connect
- Cruise control
- Grab handles for driver and passenger side
- Heated rear window
- Interior lighting front and rear with LED technology
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Front headrests are height-adjustable
- LED fog lights
- Steering column, adjustable in height and reach
- Front center console with integrated armrest
- Fatigue warning
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Pollen and dust filter
- Post-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Selective driving mode switch
- Seats: Driver's seat height adjustable
- Seats: Front sports seats with integrated headrests
- Start-stop system
- Carpet floor mats front and rear
- Variable radiator air intake
- Lashing eyes in the luggage compartment
- Central locking with remote control
- Anti-lock braking system (ABS)
- Passenger airbag deactivation
- Hill start assist
- Brake Assist (EBA)
- Fabric headliner
- 12.3-inch digital instrument panel
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Wrong-way driver warning function
- High Beam Assist
- Ford EcoCoach
- FordPower starting function
- Luggage compartment lighting
- Transmission: 6-speed manual transmission
- Illuminated glove compartment
- Rear window wiper/washer system
- Intelligent Protection System (IPS)
- air conditioning, manual
- Rear headrests (3) height adjustable
- LED taillights
- Steering wheel: ST-Line steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system
- Ford navigation system including Ford SYNC 3 with AppLink and 8" touchscreen
- Rear parking pilot system
- Upholstery: Cloth
- Pre-Collision Assist
- Headlights with LED daytime running lights and LED low beam headlights
- Power steering
- Seats: Rear seat backrest, foldable, 60:40 split
- Sun visors including illuminated makeup mirrors, on driver and passenger side
- Door handles painted in car color
- Traffic sign recognition system
- Immobiliser

Extra equipment

- Electric tailgate, sensor-controlled (opens via foot movement) (incl. Ford Key Free system (keyless locking/unlocking))
- Package: Driver Assistance Package I (Active Parking Assist with parking and exiting function - reversing camera - front parking pilot system)
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Panoramic sliding sunroof, electric (passenger seat, manually height-adjustable with lumbar support)
- Paint finish: Solid color, special color
- Package: Design package (roof spoiler, large - 4 light alloy wheels 7.5 J x 19 with 225/40 R 19 tires, 5-spoke design, in matte black premium paint finish, diamond-turned)
- Package: Comfort (Air conditioning with automatic temperature control, activated carbon filter - Windscreen wipers with rain sensor (sensitivity adjustable) - Interior mirror, automatically dimming - Inductive charging station for mobile devices (according to Qi standard, compatibility depends on the device))
- Side windows from the 2nd row of seats and rear window, dark tinted.

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Trim / covers (Motorraum) - Missing - Replace
2	Door - rear left side	Door seal - Loose - Un- / install
3	Door - rear right side	Door seal - Loose - Un- / install
4	Side panel - rear right side	Wheel well extension - Scratch(es) - Smart repair
5	Mudguard - right side	Wheel well extension - Scratch(es) - Smart repair
6	Engine	Engine cover - Damage caused by marten / rodent - Replace
7	Front bumper	Front bumper - Scratch(es) - Smart repair
8	Wheel / tyres	Tyres - complete set (Original 19 Zoll Radsatz fehlt) - Differs from the original configuration - repair according to calculation

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyre - front - Does not meet the leasing specifications - No deduction
2	Braking system	Brake fluid - No evidence - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Door - rear right side	Door ((Polieren)) - Abrasion - No deduction
5	Interior	Cup holder - centre - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit complete

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Die Montierten Räder sind kein Teil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 1: Trim / covers: Trim / covers (Motorraum) - Missing - Replace



Damage 2: Door - rear left side: Door seal - Loose - Un- / install



Damage 2: Door - rear left side: Door seal - Loose - Un- / install



Damage 3: Door - rear right side: Door seal - Loose - Un- / install



Damage 3: Door - rear right side: Door seal - Loose - Un- / install



Damage 4: Side panel - rear right side: Wheel well extension - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Wheel well extension - Scratch(es) - Smart repair




Damage 5: Mudguard - right side: Wheel well extension - Scratch(es) - Smart repair



Damage 5: Mudguard - right side: Wheel well extension - Scratch(es) - Smart repair



Damage 6: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 6: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 6: Engine: Engine cover - Damage caused by marten / rodent - Replace




Damage 6: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 7: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 7: Front bumper: Front bumper - Scratch(es) - Smart repair



Wear and tear 2: Braking system: Brake fluid - No evidence - No deduction



Wear and tear 4: Door - rear right side: Door ((Polieren)) - Abrasion - No deduction



Wear and tear 4: Door - rear right side: Door ((Polieren)) - Abrasion - No deduction

Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer:	WF02XXERK2NY65490
Hersteller / Modell:	FORD FORD Puma 1.5 EcoBlue ST-LINE

Datum	KM-Stand	Beschreibung
21.11.2025	95.191	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
25.08.2025	83.161	Kupplung ern
01.09.2023	61.377	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
25.11.2022	29.112	Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges