# CITROËN GRAND C4 SPACETOURER


## Vehicle information

| | | | |
|---|---|---|---|
| Brand: | **CITROËN** | License plate: | **2CBR399** |
| Gearbox: | | Body color: | |
| Model: | **GRAND C4 SPACETOURER** | LEVEL: | **VF73AHNS2NJ626185** |
| Fuel type: | | Power: | **96 kW** |
| Version: | **1.2 PURETECH 130 S/S SHINE** | First registration | **24/05/2022** |
| Mileage: | **72635 km** | Number of doors: | |


## Summary of damages

- **Back** 2
- **Before** 3
- **RIGHT** 4
- **LEFT** 3
- **Interior** 1
- **Roof & other** 1

## Commercial photos




























## Options according to the inspector

| | |
|---|---|
| GPS | **Yes** |


## Damages


**Right Wing (**
Right) - Dent(s) and Scratch(es) -
Paint





**Left wing**
dent(s) and scratch(es)
- Paint
left








**Right-hand exterior rocker panel**
deformed/damaged
- Repair and paint (complete
)






**Bodywork**


Damaged -

Acceptable.

Roof & other












Left rear **light**
with claw(s)
E - Replace




**Hood soundproofing**
tear
E - Replace
before





**Hood soundproofing**
tear
package
front



Damaged **Interior**
- Acceptable
Interior

**Polished right-hand side aluminum rim.**
Scratch(es)
to be painted
.






**Polished aluminum**
rim, left side.
Paintable
.










**Polished front right alloy wheel.**
Scratch(es) .
Paint.
Right side.






**Polished front left alloy wheel.**
Scratch(es)
to be painted
. Left



**Rear bumper,**
claw(s)
, paint
the rear





**Front bumper,**
scratch(es),
paint
front









## Tires

**Front Left**
Summer
Aluminum
205/55/17/95/Y
Michelin
6.0 mm

**Front Right**
Summer
Aluminum
205/55/17/95/Y
Michelin
6.0 mm

**Left Back**
Summer
Aluminum
205/55/17/95/Y
Michelin
5.0 mm

**Rear Right**
Summer
Aluminum
205/55/17/95/Y
Michelin
5.0 mm

## Controls

| | | | |
|---|---|---|---|
| Category | **Private vehicle** | Registration certificate - home address section | **No** |
| Vehicle registration certificate | **Yes** | Certificate of Conformity | **Yes** |
| Compressor | **P/A** | Vehicle inspection | **OK** |
| Vehicle inspection | **24/05/2027** | Jack | **Yes** |
| Galette | **Yes** | Repair kit | **P/A** |
| Number of charging cables (220V) | **0** | Number of charging cables (fast charging) | **0** |
| Total number of keys | **2** | Factory reset | **Yes, the vehicle has been reset to factory settings.** |
| Type of maintenance log | **Maintenance logbook present** | | |

**Information on the content and scope of the inspection report:**

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.