TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Expertise

Protocol number: 48101598
Order No. / Reference: 26855049
Inspection date: 13 Oct 2026

Manufacturer: Mercedes-Benz	Model: E 300 de 4Matic T 9G-TRONIC Avantgarde
VIN: W1K2132111A991126	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 300 de 4Matic T 9G-TRONIC Avantgarde	
Vehicle Identification number	W1K2132111A991126
Mileage (Read)	103,834 km
First registration	22 Jun 2021
Number of holders	1
Fuel type	Hybr.D/E ext.aufl
Engine displacement / Cylinder	1,950 ccm / 4
Power	143 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	HIGHTECHSILBER METALLIC-LACKE
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	142 Tag(e)
Last service on / at	03/2026 at 91,441 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC623077
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	short drive on the company premises	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ATL 00013		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,850 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100Y XL	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	275/40 R18 103Y XL	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	275/40 R18 103V	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 45.7 cm (18") alloy wheels in a 5-twin-spoke design
- AdBlue tank with a capacity of 23.5 liters
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Sidebag for driver and front passenger (combined thorax/ pelvisbag)
- Airbag: Windowbags left/right
- Acoustic environmental protection
- 4MATIC all-wheel drive
- Premium ambient lighting with 64 colors and 3 color zones
- Anti-lock braking system (ABS)
- Traction control (ASR)
- ATTENTION ASSIST (can detect typical signs of fatigue through driver behavior and warn the driver of increasing fatigue or inattentiveness)
- Basic services (breakdown management, maintenance management, accident management, telediagnosis, remote vehicle diagnostics)
- Diesel particulate filter
- Tachometer
- Third brake light
- EASY-PACK cargo cover including EASY-PACK safety net
- EASY-PACK tailgate (makes loading and unloading the luggage compartment even more convenient. You can easily start opening and closing with the push of a button and interrupt it at any time by pressing the control again.)
- Electronic Stability Program (ESP) (with traction control (ASR))
- Chassis: AGILITY CONTROL chassis with selective damping system (combines balanced driving comfort and high driving stability. Thanks to the passive damping system, you enjoy a confident driving experience on any road surface: rolling behavior, damping effect and stabilization are continuously and automatically adapted to the current surface.)
- Heated rear window with timer
- Interior headliner in nevagrau fabric
- Climate: Pre-conditioning
- Communication module (LTE) for using Mercedes me connect services (offers you a clear increase in comfort and safety. It constantly connects the vehicle to the internet so you can use helpful services like Mercedes me connect Live Traffic Information. Two mobile antennas and an LTE-enabled SIM card ensure a fast connection.)
- Paint finish: Solid
- Charging cable for household socket, 5m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 2.3 kW (230 V, 1-phase, 10 A) and fits sockets of type E/F CEE 7/7.)
- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Airbag: Automatic passenger airbag deactivation (The system automatically deactivates the passenger airbag as soon as it detects a rear-facing child seat or registers that the passenger seat is unoccupied. A transponder in the child seat is not necessary. If it detects that an adult is taking the seat, the airbag is automatically activated, reducing the risk of incorrect operation.)
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Foldable armrest for driver and front passenger
- Exterior mirrors, left and right, heated and electrically adjustable, painted in car color (with aspherical curved mirror glass and integrated LED turn signal)
- On-board computer
- Brake assist, active (consisting of distance and collision warning, situation-appropriate brake support and autonomous braking function for vehicles ahead and crossing pedestrians)
- DYNAMIC SELECT (The DYNAMIC SELECT driving programs change the driving behavior of your Mercedes at the touch of a button. For example, you can control the characteristics of the engine, transmission, suspension and steering to suit the driving situation: whether dynamic in Sport mode, completely relaxed in Comfort mode or particularly economical in Eco mode. You determine the style of your drive.)
- Chassis: Air suspension on the rear axle with level control
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Velour floor mats (in interior color)
- Transmission: 9-speed automatic, 9G-TRONIC (including DIRECT SELECT gear selector and DIRECT SELECT steering wheel shift paddles)
- rear window wiper
- KEYLESS START
- THERMATIC automatic climate control (with 2 climate zones - separately adjustable temperature for driver and front passenger - fine dust activated carbon filter for dust and odor reduction - recirculation function with comfort function - sun and fog sensor - rear air vents)
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- Charging system: AC charging system 7.4 kW
- LED High Performance headlights (low beam in LED reflection technology - high beam in LED reflection technology - signal light with trifunctional torch for daytime running light, position light and direction indicator in LED technology - adaptive full-LED taillights)
- Steering column mechanically adjustable in height and length

- Steering wheel: Multifunction steering wheel in Nappa leather in a 3-spoke design (spokes in high-gloss black with silver chrome trim - shift paddles in silver chrome - control via touch panels: left: instrument cluster, cruise control and speed limiter or Active Distance Assist DISTRONIC; right: multimedia system (e.g., audio volume and track selection, telephony and navigation); touch sensitivity adjustable via media display)
- Center console piano black finish
- Center console with spontaneous storage (storage compartment under the armrest with 2 USB ports (Type C) and open storage on the back -cupholders front and rear -storage compartments in the door panels with cup holders -lockable, air-conditioned glove compartment -glasses compartment in the overhead control unit (not included with MBUX Interior Assistant))
- Package: Storage (for plug-in hybrid) (Double cup holder in the center console - Map pockets on the back of the front seats)
- Package: AVANTGARDE Exterior (for plug-in hybrid) (Radiator grille with integrated Mercedes star - Hood with pronounced power domes - Front bumper with chrome trim strip, chrome front splitter - Side skirts and window surrounds in polished aluminum - Side sills painted in body color - Roof rails in polished aluminum - Rear bumper with chrome trim strip - Exhaust system with two tailpipe trims)
- Upholstery: ARTICO leatherette/Norwich fabric
- PRE-SAFE system (This system can detect critical driving situations in advance and initiate preventive measures to protect the occupants if an accident is imminent. In addition to reversible seatbelt tensioning and other measures, PRE-SAFE Sound is now also included in its range of functions.)
- Radio: MBUX Multimedia System (Enjoy the beauty and intelligence of a digitized multimedia system. You decide which information it displays. Look forward to a fully digital cockpit consisting of two 10.25-inch displays with touch functionality for the media display. - Bluetooth interface - USB - SD card / SDHC card - Dual tuner radio - Online-enabled multimedia system)
- Tire pressure monitoring system (continuously monitors the inflation pressure of all four tires)
- Windscreen wipers with rain sensor (with 2 sensitivity levels - the electronically controlled rain sensor makes driving more relaxed in adverse weather conditions - the system detects whether the windscreen is wet and, when intermittent wiping is activated, automatically adjusts the wiper frequency to the appropriate level depending on the amount of precipitation)
- Power steering
- Seats: i-Size child seat attachment (on the outer rear seats - The system allows for quick and secure attachment of i-Size and ISOFIX child seats in the rear for the best possible protection of the child in the event of an accident. Top tether attachment points offer additional safety by anchoring the child seat behind the rear headrests.)
- Mercedes-Benz Emergency Call System (can provide a crucial time advantage in an emergency. A communication module with its own SIM card automatically triggers an emergency call in the event of an accident, which can shorten the time until emergency services arrive. The emergency call can also be triggered manually to organize rapid assistance.)
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation: Hard drive navigation (Mercedes-Benz look and feel of navigation, all map data stored on hard drive, fast hard drive navigation, up-to-date map data through 3 years of free map updates (from initial registration, vehicle-specific), destination input via touch function or voice control, route calculation including waypoints, numerous route options (Eco, Trailer, Fast, Short, Automatic, etc.) as well as avoidance options (motorways, ferries, tunnels, toll roads, unpaved roads, car trains, vignette roads))
- Package: Seating comfort (various electric and manual adjustment options for the front seats to adapt to the specific body and comfort requirements of the driver and front passenger - electro-pneumatic 4-way lumbar support with control element on the seat - electric seat cushion tilt adjustment - electric height adjustment - electric backrest adjustment - mechanical seat cushion depth adjustment by 6 cm with leg rest pad - mechanical longitudinal adjustment - mechanical headrest adjustment)
- Radio: Extended MBUX functions (personalization (profiles) and prediction functions - LINGUATRONIC with natural language understanding - activation via Hey Mercedes - Wi-Fi hotspot - internet radio)
- Radio accessories: Digital radio (For the DAB, DMB and DAB+ standards. The digital radio offers noise-free, CD-quality sound via DAB (including DAB+ and DMB) and program-related additional information, e.g., album art, weather maps, news and traffic maps. Three DAB tuners ensure the best possible reception quality for the selected station in the background.)
- Remote Services Plus (Communication module - Mercedes me services: remote vehicle status query, programming of auxiliary heating/ventilation, remote door locking and unlocking, sunroof/ windows with remote locking and opening including ventilation remote control, personalization, vehicle location, vehicle tracking, geographic vehicle monitoring, parking service monitoring, finder function (Remote Vehicle Finder), notification in case of exceeding the driving speed, Send2Car-Fun, accident and breakdown management, maintenance management, telediagnosis, remote vehicle diagnostics, software updates)
- Seats: Rear seat backrests foldable 40/20/40 split (EASY-PACK Quickfold - double cupholder - storage compartment)
- Touchpad (integrated into the center console, including a palm rest - single and multi-finger gestures, swipe movements and zoom gestures by spreading and pinching the fingers - recognizes handwritten characters: letters, special characters and numbers - clear haptic feedback)

- Power outlet: 12V socket in the cargo area (For connecting notebooks, MP3 players, mobile phones, coolers and other electrical devices.)
- High-visibility vest for drivers
- Electronic immobilizer (including locking system with 3-channel radio remote control in the electronic key in chrome look, optical locking feedback and emergency opening (approved by AZT and TÜV))
- Decorative elements: aluminum with longitudinal brushing, light finish
- Green heat-insulating glass all around (including rear window made of single-pane safety glass)
- Central locking

Extra equipment

- Center console wood ash black open pore
- Glazing: Heat-insulating dark tinted glass all around from the B-pillar (the use of heat-insulating dark tinted glass for the rear side windows and rear window protects rear passengers from prying eyes and direct sunlight - the dark tint also emphasizes the sportiness of the vehicle)
- Package: Business (MBUX High-End Package - Connectivity Package Navigation - Traffic Sign Assist - Smartphone Integration - Pre-installation for Car Sharing - Widescreen Cockpit - Wireless Charging System for Mobile Devices - MBUX Augmented Reality for Navigation - Heated Seats for Driver and Front Passenger - Parking Package with Rearview Camera - Fuel Tank with 66 Liter Capacity (916) (60l for Diesel Plug-in Hybrids).)
- Package: Driving Assistance Package Plus (Active Distance Assist DISTRONIC incl. Active Speed Limit Assist, Extended Automatic Restart on Motorways, Route-Based Speed Adaptation with Traffic Jam Function (only when Parking Packages are selected), Active Steering Assist incl. Active Emergency Stop Assist with SOS Function, Emergency Lane Radio, Active Brake Assist incl. Turn and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist incl. Exit Warning, Pedestrian Warning Radio, PRE-SAFE Impulse Side, Active Traffic Jam Assist)
- Power outlet: 2 USB ports in the rear with charging function
- Radio accessories: Burmester surround sound system (13 high-performance speakers - 9-channel DSP amplifier with a total output of 590 W - Frontbass technology with woofers integrated into the body shell for powerful bass reproduction - Sound optimization for the front and rear seats - Noise cancellation (VNC) - Sound preset: Surround function to generate a virtual surround sound - Multi-channel format support for true surround sound)
- Sunroof: Panoramic electric sunroof in glass design (with comfort and automatic rain closing, PRE-SAFE closing function, electric sunshade and anti-pinch protection)
- Upholstery: Leather
- Airbag: Sidebags in the rear, left and right
- Heated windshield washer system (including heated washer fluid reservoir, windshield washer nozzles and washer fluid hoses)
- MULTIBEAM LED (84 individually controllable high-performance LEDs, low beam and high beam in LED projection technology, Adaptive Highbeam Assist Plus (glare-free permanent high beam), ULTRA RANGE high beam, cornering light or cornering light with roundabout and intersection function, active curve illumination (with predictive control with active lane keeping assist or driving assistance packages), extended fog light, city light, country road light, motorway light and bad weather light, adaptive full-LED taillights)
- Package: Mirrors (both exterior mirrors electrically foldable (button in the driver's door control panel) - automatic lowering of the passenger-side mirror glass to parking position when reverse gear is engaged - interior mirror and driver's side exterior mirror automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area)
- Package: Parking package with reversing camera (The parking package with reversing camera makes it easier to find and select parking spaces, as well as to park and exit in parallel and perpendicular parking spaces or garages. The active parking assistant steers the vehicle into parking spaces, including speed control and automatic gear changes.)
- Package: Sun protection package (mechanical sunshade in rear doors left and right - extendable sun visors with make-up mirror for driver and front passenger)
- Paint finish: Metallic
- Seats: Climate control for driver and front passenger (including seat heating and ventilation. Active ventilation quickly cools the seat surface to a comfortable temperature on hot days, creating a balanced seating climate. The switchable seat heating provides cozy warmth as desired during the colder months.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door - dent(s) - Smooth repair work
2	Sill - left side	Sill - dent(s) - Loss in value
3	Side panel - rear right side	Sill - Dent / paintcoat damage - Repair and paint
4	Bonnet	Bonnet - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Sill - right side	Sill - dent(s) - No deduction
3	Side panel - rear left side	Sill - Scratch(es) - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction
5	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
6	Side panel - rear right side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterreifensatz ist kein Bestandteil des Auslieferumfangs.
- Montierter Felgensatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Door - front left side: Door - dent(s) - Smooth repair work



Damage 1: Door - front left side: Door - dent(s) - Smooth repair work




Damage 1: Door - front left side: Door - dent(s) - Smooth repair work



Damage 2: Sill - left side: Sill - dent(s) - Loss in value



Damage 2: Sill - left side: Sill - dent(s) - Loss in value



Damage 2: Sill - left side: Sill - dent(s) - Loss in value




Damage 2: Sill - left side: Sill - dent(s) - Loss in value



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint




Damage 4: Bonnet: Bonnet - Stone chips - Paint



Wear and tear 6: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 6: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 6: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 6: Side panel - rear right side: Side panel - dent(s) - No deduction