TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48270338
Order No. / Reference: 27152779
Inspection date: 23 Oct 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG Selection
VIN: TMBJJ8NX0SY100481	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG Selection	
Vehicle Identification number	TMBJJ8NX0SY100481
Mileage (Read)	54,958 km
First registration	23 Jan 2025
Number of holders	1
Next periodical technical inspection	01/2028
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Candy White (F9E)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	3,400 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HK255740
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AWL 00424		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,990 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91V	Summer tyres on Light alloy	Goodyear	4mm / 4mm
2)	205/55 R17 91V	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment
- Airbag, driver and passenger
- Airbag, head airbags
- Airbag: Center airbag front
- Traction control (ASR)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors and door handles in body color
- Cup holders in the front center console
- Glasses compartment in the headliner
- roof grab handles four
- AERO roof rails in black
- Digital Cockpit
- Ice scraper in the fuel filler flap
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Front radar assistant (Front Assist)
- Luggage compartment lighting with 2 lamps
- Cruise control system (cruise control) including speed limiter
- Heated rear window
- Interior features: Design Selection Loft (fabric seat covers - silver-square and piano-black trim strips)
- Child safety lock for the rear doors and windows
- Climatronic air conditioning (2-zone)
- Fuel tank 45 l
- LED taillights
- Steering wheel: height and reach adjustable
- Reading lights two at the front
- Front center armrest, including storage compartment
- Multi-collision brake
- Front and rear parking sensors
- Radio accessories: 8 speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: Wireless & Wired SmartLink (Apple CarPlay, Android Auto)
- Tire pressure monitoring
- Wheels: 17" Mensa AERO alloy wheels (7J x 17, ET 46 with 205/55 R17 tires)
- Seat belts
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Front seats are height-adjustable
- SKODA Connect (SOS emergency call function (eCall+ including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection option for rapid assistance in case of breakdown) - Information service (connection option to the hotline for all questions relating to vehicle functions) - Free remote vehicle access for 3 years with access to vehicle data and functions via smartphone)
- Immobiliser
- Decorative trim in piano black around the air vents
- Storage compartments
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Evasive steering and turning assistant
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist
- Chrome trim in the front bumper
- Grey headliner
- Diesel particulate filter
- Third brake light
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Removable luggage roller blind
- Transmission: 7-speed dual-clutch transmission (DSG)
- Tinted windows
- Rear window wiper including windshield washer system
- Interior mirror automatically dimming
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Headrests (5) front and rear height adjustable
- Chrome grille surround
- LED headlights with LED daytime running lights
- Steering wheel: Paddle shifters on the steering wheel
- Manual headlight range adjustment
- Engine drag torque control (MSR)
- Fatigue detection
- Radio accessories: 2 x USB charging ports in the rear and USB charging port in the rearview mirror
- Radio accessories: Digital radio reception DAB+
- Umbrella and broom compartments in the front doors
- Rain sensor and driving light assistant (Easy Light Assist)
- Tire mobility kit
- Reflectors in the front side doors
- Electromechanical power steering
- Seats: Heated front seats
- Seats: Pockets on the backs of the front seats including smartphone pockets
- Sun visors on driver and passenger side
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Traffic sign recognition
- Lashing eyes in the trunk
- Preparation for alcohol immobilizer

- Central locking including remote control integrated into the key and EASY Start

Extra equipment

- Package: Infotainment (13" infotainment screen - navigation system - voice control - Digital Cockpit Plus - Infotainment Online (3-year term))
- Luggage net partition
- Paint finish: Special paint finish, solid color

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Rear bumper	Bumper with Parktronic - Scratch(es) - Smart repair

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Damage 2: Rear bumper: Bumper with Parktronic - Scratch(es) - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz



Damage 2: Rear bumper: Bumper with Parktronic - Scratch(es) - Smart repair