TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 47316200
Order No. / Reference: 26708384
Inspection date: 28 Aug 2026

Manufacturer: Mercedes-Benz	Model: GLA 180 d 8G-DCT Entry
VIN: W1N4N1AB0RJ562974	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLA 180 d 8G-DCT Entry	
Vehicle Identification number	W1N4N1AB0RJ562974
Mileage (Read)	74,785 km
First registration	19 Jun 2024
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Mountaingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	160 Tag(e)
Last service on / at	02/2026 at 68,385 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY512261
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ATH 00075		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,160 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	215/65 R17 99V	Summer tyres on Light alloy	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Light alloy	Michelin	5mm / 5mm
2)	215/65 R17 99H	Winter tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Adaptive Highbeam Assist
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Anti-lock braking system (ABS)
- Center console armrest for driver and front passenger with integrated storage compartment
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Roof rails in polished aluminum
- Double cup holder
- Third brake light in LED technology
- ECO start/stop function
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Windscreen laminated glass
- Luggage net on driver and passenger seatbacks
- Transmission: 8G-DCT dual-clutch automatic transmission, 8-speed
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Headrests 5-way
- LED High Performance headlights (low beam in LED projection technology - high beam with LED reflector technology - daytime running lights, position lights and direction indicators in LED technology - automatic adjustment of the light intensity of the rear lights to the surroundings)
- Navigation accessories: Extended MBUX functions
- Navigation: Hard disk navigation
- Navigation: MBUX Navigation Premium
- Package: Cargo area (chrome-look loading sill protector - 12V socket - reversible mat - nets on left and right sides - storage compartment under left net - net on boot floor (not for plug-in hybrid) - tension straps on left and right sides)
- Package: Seating comfort (height adjustment for passenger seat - seat cushion tilt adjustment for driver and passenger seats - seat cushion depth adjustment for driver and passenger seats)
- Package: USB Package Plus (1 USB-C port in the storage compartment in the front part of the center console, fast charging and suitable for data transfer; 2 USB-C ports under the front center armrest, fast charging and suitable for data transfer; 2 USB-C ports for the rear seats at the back of the center armrest, fast charging; 12V socket in the storage compartment in the front part of the center console)
- Radio accessories: CENTRAL MEDIA DISPLAY 10.25" (The high-resolution media display connects you to the car in a large format (10.25"). It responds to your touch inputs. Symbols simplify operation and increase concentration. Aesthetically pleasing: When the media display combines with the enlarged instrument display, a widescreen cockpit is created.)
- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Traction control (ASR)
- ATTENTION ASSIST
- Automatic passenger airbag deactivation
- Outdoor temperature display
- Basic services
- Diesel particulate filter
- Tachometer
- DYNAMIC SELECT
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis with lowered suspension
- electric parking brake
- Velour floor mats
- Speed Limit Assistant
- Rear window wiper with intermittent function
- Heated rear window with timer
- ISOFIX child seat anchorages with Top Tether in the rear
- Communication module (LTE) for the use of Mercedes me connect services
- Steering wheel: Multifunction sports steering wheel in leather
- Steering column mechanically adjustable in height and length
- Steering: Direct steering
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: Entry (00U Remote Services 677 Comfort suspension with lowering 873 Seat heating for driver and front passenger 942 Load compartment package B51 TIREFIT PBG MBUX Navigation Premium)
- Package: Light and Sight Package (roof control unit, 4 light elements, interior light and reading light in the rear in mounting plate, left and right, reading lights in front, left and right and console lighting, sun visor with illuminated make-up mirror, signal exit light in front, left and right, footwell lighting in front, left and right, cupholder and storage compartment lighting, spontaneous storage compartment lighting)
- Upholstery: ARTICO leatherette/fabric
- Radio: MBUX multimedia system (instrument display with 17.78 cm diagonal - media display with 17.78 cm diagonal and touch function - touch control buttons on the steering wheel - radio - USB interface in the center console under the armrest - Bluetooth telephony with contact transfer and audio streaming of music files - display of vehicle functions (driver assistance systems, driving programs and vehicle settings) - favorites storage - smartphone-related voice control - activated by long press on the voice button on the steering wheel)
- Radio accessories: Digital radio
- Remote Services

- Tire pressure monitoring system
- Wheels: 43.2 cm (17") light alloy wheels in 5-twin-spoke design (aerodynamically optimized, painted black and polished with 215/65 R17 tires on 6.5J x 17 ET44)
- Seats: Comfort seats
- Heated seats for driver and front passenger
- TIREFIT with tire inflation compressor
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- Decorative elements Star Pattern
- Rear view camera
- Windscreen wipers with rain sensor
- GLA-Class seat belts
- Seats: Rear seat backrests foldable
- Cruise control
- Pre-installation for digital key handover
- Electronic immobilizer
- Central locking

Extra equipment

- 1 set of WKR 17 inch 5 spoke aluminum wheels
- Fully digital instrument display (high-resolution 10.25" display)
- Package: Entry Advanced (4-way lumbar support - Mirror package (automatically dimming interior mirror, electrically folding exterior mirrors) - Parking package with reversing camera (Active Parking Assist with PARKTRONIC) - EASY-PACK tailgate (electrically opening and closing tailgate, switch for electrically opening the tailgate in the driver's door, switch for electrically closing the tailgate at the bottom edge of the tailgate, manual load compartment cover))
- Paint finish: Metallic (according to sample card)
- Phone accessories: Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)
- Package: Winter Package (heated steering wheel - heated seats for driver and front passenger - heated windshield washer system)
- Traffic Sign Assist (networked system consisting of a camera behind the windshield and navigation maps - display of speed limits, prohibitions and their cancellation in the instrument display or media display as well as in the optionally available head-up display - visual and, if desired, additional acoustic warning when exceeding the permitted maximum speed, whereby the tolerance threshold can be raised to up to 10 km/h - can recognize no-entry signs, providing a visual and acoustic warning)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper (Blende) - Scratch(es) - Replace
2	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Smart repair
3	Front bumper	Front bumper - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smart repair

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Mudguard - left side, Mudguard - right side, Bonnet, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - left side	204 µm	Mudguard - right side	191 µm
Bonnet	165 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Damage 1: Front bumper: Front bumper (Blende) - Scratch(es) - Replace



Damage 1: Front bumper: Front bumper (Blende) - Scratch(es) - Replace



Damage 2: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Smart repair



Damage 2: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Smart repair



Damage 2: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Smart repair



Damage 3: Front bumper: Front bumper - Scratched - Paint



Damage 3: Front bumper: Front bumper - Scratched - Paint



Damage 3: Front bumper: Front bumper - Scratched - Paint



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Mudguard - left side, Mudguard - right side, Bonnet

Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer:	W1N4N1AB0RJ562974
Hersteller / Modell:	MERCEDES-BENZ MERCEDES-BENZ GLA 180 d 8G-DCT Entry

Datum	KM-Stand	Beschreibung
02.02.2026	68.385	Regelwartungsdienst
02.06.2025	44.185	Regelwartungsdienst
20.11.2024	17.103	Regelwartungsdienst