TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48589002
Order No. / Reference: 27114334
Inspection date: 9 Nov 2026

Manufacturer: Opel	Model: Movano 2.3 D (CDTI) L3H2 DPF 2WD HA
VIN: W0VMRY604KB166130	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Movano 2.3 D (CDTI) L3H2 DPF 2WD HA	
Vehicle Identification number	W0VMRY604KB166130
Mileage (Read)	130,432 km
First registration	15 Nov 2018
Number of holders	1
Next periodical technical inspection	12/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	2,299 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Brilliant Silber Metallic
Doors / Seats	4 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	40,000 km
Last service on / at	12/2024 at 90,905 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FB551242
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1844 / AAZ 01281		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 112T	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	225/65 R16 112T	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/65 R16 112T	Summer tyres on Steel	Continental	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment above the windshield
- Driver's side airbag (full-size)
- Tachometer
- Vehicle key (3-button) for selective door unlocking
- Electric front windows
- Rear gullwing doors, 180° opening angle, sheet metal cladding
- Headrests (3) height adjustable
- Paint finish: Solid color paint
- Steering column, height adjustable
- Pollen filter
- Upholstery - Fabric
- Wheels: Spare wheel, steel
- Seat: Double passenger seat
- Seats: Rear bench seat with 4 seats
- Rear step, integrated into the bumper
- Doors: Sliding door, passenger side with fixed window
- Lashing eyes on the loading platform
- Thermal insulation glazing, green tinted
- ABS electronic
- Electrically adjustable and heated exterior mirrors
- ESP, Electronic Stability Program
- Window: Side window in 2nd row of seats, driver's side, fixed
- Transmission: 6-speed transmission
- Seat belts: 3-point safety belts in the front
- Fuel tank 80 l
- Cargo area lighting
- Particulate filter: Soot particle filter for diesel engines with SCR
- Radio R 15 BT USB
- Power steering
- Seat: Driver's seat, 4-way adjustable
- Blind spot mirror in passenger-side sun visor
- Doors: Sheet metal insert with fixed window, driver's side
- Anchoring points in the cargo area
- Immobiliser
- Central locking with remote control

Extra equipment

- Extendable step (mounted)
- Anti-theft alarm system
- External start system installed,
- Heated rear window
- Package: Cool & Sound (Air conditioning with pollen filter - Stereo CD radio CD 16 BT, Bluetooth interface, Aux-In and USB port and jack plug)
- Package: Light 1 (Automatic low beam - Rain sensor - Fog lights)
- Seat cover for driver's seat
- Seat: Comfort driver's seat (with lumbar support, armrest, 4-way adjustable)
- Seat heating for driver and front passenger individual seats
- On-board computer
- Rear gullwing doors, 180° opening angle, glazed
- Rubber mats at the front
- Paint finish: Metallic special color
- Package: Comfort Package (Stereo CD radio 16 BT, Bluetooth interface, Aux-In and USB - Comfort driver's seat, 4-way adjustable, with armrest and lumbar support - Multifunctional double passenger seat with folding center seat, rotating laptop tray on the rear seat and internal storage compartments and fold-forward seat cushion - Partition with sound insulation - Electric front windows with one-touch function, driver's side - Clipboard in dashboard)
- winter tires

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratched - Loss in value
2	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint
3	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint
4	Boot lid / rear door	Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Interior	Interior - Soiled - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Front bumper: Front bumper - Scratched - Loss in value



Damage 1: Front bumper: Front bumper - Scratched - Loss in value



Damage 2: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 2: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 3: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 3: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 3: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 4: Boot lid / rear door: Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint



Damage 4: Boot lid / rear door: Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint



Damage 4: Boot lid / rear door: Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint



Damage 4: Boot lid / rear door: Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint



Damage 4: Boot lid / rear door: Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint



Damage 4: Boot lid / rear door: Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint



Damage 4: Boot lid / rear door: Rear door - right side (+ Links) - Dent / paintcoat damage - Repair and paint



Wear and tear 3: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Rear bumper - Scratch(es) - No deduction