Dacia

1.0 SCE 65 EXPRESSION

VIN: UU1DJF00975701665



Description

Registration number 2HSB778	**First registration date** 20/10/2025	**Odometer** 5855 km
Color TEINTE CAISSE BLANC GLACIER	**Model year** 2025	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 999	**Gearbox type** Manual	**Engine type** Combustion
Number of gears 5	**Drivetrain** Front Wheel Drive (FWD)	**Max power** 67 KW

Vehicle Equipments

Manual air-conditioning

Cruise control

Park Assist

Rear sensors

Active warning lights

Tyre pressure indicator

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 23/10/2026	**Inspection approval date** 26/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction
001	Tyre pressure indicator	Defective	Check
			
002	Interior roof lining / Interior Front Left [1]	Burn mark	Smart repair
	 		

[1] Ovb,vervangen

Loose Items

- [x] Triangle
- [x] Rear parcel shelf
- [x] Spare Key
- [x] First aid kit
- [x] Conformity certificate
- [x] Safety vest
- [x] Registration certificate owner
- [x] Registration certificate

Main set of tyres

Front Left	BRIDGESTONE	185/65/15 Summer	6.5 mm
Front Right	BRIDGESTONE	185/65/15 Summer	6.5 mm
Back Left	BRIDGESTONE	185/65/15 Summer	6 mm
Back Right	BRIDGESTONE	185/65/15 Summer	6 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer


Navigation



Spare Tyre


Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other



Other



Other



Other



Other



Tyre pressure indicator / Defective



Interior roof lining / Interior Front Left / Burn mark



Interior roof lining / Interior Front Left / Burn mark

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.