MACADAM








Seat Ateca (UKL): 2EEB357

Vinnumber:	**VSSZZZ5F0R6500733**	Versionname:	**Ateca Move! Navi 1.0TSi 110pk/cv 5p**
First Registrationdate:	**12/09/2023**	Fiscalpower:	
Expertise Mileage:	**97535**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**over 4600 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/55/17/94 V**			
	Fr.L.	**Goodyear: 1 mm**	Fr.R.	**Goodyear: 1 mm**
	Re.L.	**Michelin: 2 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**1.0**
Tyre profile depth FR	**1.0**
Tyre profile depth RL	**2.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/55 R 17 94 V**
Tyre size FR	**215/55 R 17 94 V**
Tyre size RL	**215/55 R 17 94 V**
Tyre size RR	**215/55 R 17 94 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**261**
Tyre make RR	**259**


Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**


Ignition key, Not functioning (well), Acceptable



Interior, Dirty, Cleaning



Windscreen, Stone chip(s), Acceptable



Bumper F, Scratch(es), Acceptable



Step L, Dent(s) and scratch(es), Spot repair



Tyre FL, Worn, Check




Tyre RL, Not original part, Replace










Door FL, Scratch(es), Acceptable




Wing RL, Dent(s), Acceptable




Internal boot lining L, Scratch(es), Acceptable





Internal boot lining R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable






Bumper R, Scratch(es), Repair and paint (complete)








Bumper trim R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s) and scratch(es), Acceptable



Step R, Dent(s), Acceptable



Tyre FR, Worn, Check



Door RR, Dent(s), Paintless dent repair





Door RR, Scratch(es), Acceptable












Door FR, Scratch(es), Acceptable








Bodywork, Not original part, Remove lettering





Onderhoudshistorie van: VSSZZZ5F0R6500733

ALPHABET

Kenteken	2EEB357
Merk Model	Seat Ateca Move! Navi 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	9/12/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/2/26	94,422	diagnose	Uitvoeren
8/25/26	94,314	foutencodes uitlezen	Uitvoeren
8/25/26	94,314	sleutellezer/kaart- (startsysteem)	Repareren
5/7/26	85,424	klein materiaal	
5/7/26	85,424	koelwatervloeistof	Bijvullen/-laden
5/7/26	85,424	remblokken achter	Vervangen
5/7/26	85,424	remblokken vooraan	Vervangen
5/7/26	85,424	remvloeistof	Bijvullen/-laden
5/7/26	85,424	ruitenwisservloeistof	Bijvullen/-laden
5/7/26	85,424	Tussentijds onderhoud (vast interval)	Uitvoeren
12/19/25	70,313	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
12/19/25	70,313	batterij	Vervangen
12/19/25	70,313	bougie	Vervangen
12/19/25	70,313	klein materiaal	
12/19/25	70,313	luchtfilter interieur	Vervangen
12/19/25	70,313	nummerplaat licht	
12/19/25	70,313	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
12/19/25	70,313	ruitenwisserrubber achter	Vervangen
12/19/25	70,313	ruitenwisserrubber vooraan	Vervangen
12/19/25	70,313	ruitenwisservloeistof	Bijvullen/-laden
12/23/24	34,896	klein materiaal	
12/23/24	34,896	koelwatervloeistof	Bijvullen/-laden
12/23/24	34,896	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
12/23/24	34,896	ruitenwisservloeistof	Bijvullen/-laden
4/26/24	18,448	controle niveaus	Uitvoeren