TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

# Expertise

Protocol number: 48472904
Order No. / Reference: 27156161-1
Inspection date: 28 Oct 2026

| Manufacturer: Volkswagen | Model: Passat Variant 1.4 TSI Plug-In-Hybrid DSG GTE |
|---|---|
| VIN: WVWZZZ3CZNE081191 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Volkswagen Passat Variant 1.4 TSI Plug-In-Hybrid DSG GTE | |
| **Vehicle Identification number** | WVWZZZ3CZNE081191 |
| **Mileage** (Read) | 166,607 km |
| **First registration** | 9 Aug 2022 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** (Report on hand) | 07/2027 |
| **Fuel type** | Hybr.B/E ext.aufl |
| **Engine displacement / Cylinder** | 1,395 ccm / 4 |
| **Power** | 115 kW |
| **Gearbox / Number of gears** | Automatic / 6 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Car station wagon |
| **Colour / colour code** | Aquamarinblau metallic (P5M) |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Leather |
| **Colour of upholstery** | Black |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 7,900 km |
| **Last service on / at** | 08/2026 at 159,411 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GJ248503 |
| **Previous damage / Accident** | Detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 0603 / BAZ 00110 | | |
| **Emission standard** | EURO5 | **fine dust sticker** | |
| **Permitted total weight** | 2,270 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/45 R18 94W | Summer tyres on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 235/45 R18 94W | Summer tyres on Light alloy | Pirelli | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/55 R17 98H | Winter tyres on Light alloy | Bridgestone | 4mm / 4mm |
| 2) | 215/55 R17 98H | Winter tyres on Light alloy | Bridgestone | 6mm / 6mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Adaptive Cruise Control (ACC) "stop & go", including speed limiter
- Cup holders (2) front
- third brake light
- Headliner in Mistral Grey
- Tachometer
- Parking aid - warning signals for obstacles in the front and rear area
- Automatic headlight control
- Windscreen made of laminated safety glass, heat and sound insulating
- Transmission: 6-speed DSG
- Interior mirror automatically dimming
- Cable for AC charging station
- Rear headrests (3)
- Front headrests
- LED headlights with daytime running lights
- Headlight range control
- Front center armrest, height and length adjustable, with storage box
- Navigation system "Discover Media" incl. "Streaming & Internet"
- Non-smoking version
- Emergency call service
- Package: Light and Sight Package "Plus"
- Proactive occupant protection system in conjunction with "Front Assist"
- Rear bench seat, undivided, backrest asymmetrically split and foldable, with center armrest
- Seat belts: Three-point automatic seat belt
- Seats: Lumbar support in the front
- Lane keeping assistant “Lane Assist”
- 12V power outlet on the rear of the center console
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Airbag, head airbag system for front and rear passengers
- App-Connect Wireless
- Electrically adjustable and heated exterior mirrors, ambient lighting
- Hill start assist
- Chrome trim on the side windows
- black roof rails
- e-Sound
- Entry/warning lights in LED technology in the front doors
- Electronic parking brake including auto-hold function
- Remote release for luggage compartment lid
- Pedestrian detection
- Adjustable luggage compartment floor
- Interior lights with delayed shut-off and dimming function
- ISOFIX mounting points
- Air conditioning system "Air Care Climatronic" with 3-zone temperature control and active combination filter
- LED taillights
- Steering wheel: Multifunction sports steering wheel in leather, with paddle shifters
- "Premium" multifunction display with multicolor screen
- Fatigue detection
- Mains charging cable for household socket
- Mesh partition
- Emergency braking assistant "Front Assist" (for automatic distance control ACC up to 210 km/h)
- Upholstery: "Business" fabric
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system (passive)
- Keyless start system without safe locking
- Power steering
- Seats: Comfort seats in the front
- Seats: Front seats are height-adjustable
- Start-stop system
- Bumpers in body color
- Textile floor mats
- Warning tone and light for unfastened seat belts front and rear

### Extra equipment

- Towbar, foldable (with electric release)
- Roof headliner in titanium black
- Roof rails, silver anodized
- Anti-theft alarm system (interior monitoring, backup horn and tow-away protection - illuminated make-up mirror in the sun visors, extendable sun visors)
- Fire extinguisher
- Tailgate with electric opening and closing, electric opening for luggage compartment cover (extendable and removable luggage compartment cover with electric opening - tailgate with electric opening and closing)
- Paint finish: Special metallic paint
- Steering wheel: Multifunction sports steering wheel in leather, heated, with paddle shifters
- Navigation system "Discover Pro" incl. "Streaming & Internet" (4x20 Watt App-Con. Wireless Digital Cockpit. Operation with proximity sensor. Dual tuner with phase differentiation. DAB. Vehicle menu. Speed. Volume adjustment. Gestures. 32 GB SSD hard drive. Map 2D display. Tone control. 3-way TFT display with touchscreen. MP3. Navigation for Europe. Voice control. Telephone contact. Address. Telephone interface. "Comfort" with inductive charging. 2 USB iPod/ iPhone. Traffic sign recognition. "We Connect Plus" incl. "We Connect". Dynamic route guidance. RDS. TMC tuner. Mobile key pre-activation, vehicle via smartphone.)
- Package: R-Line Sport package for DCC (progressive steering - rear side windows and rear window darkened, 65% light-absorbing - electronic differential lock XDS)
- Wheels: Tire Mobility Set omitted
- Keyless start system with safe locking
- Seats: Lumbar support in front, driver's side electric including massage function
- Voice control
- Exterior mirrors with ambient lighting and passenger-side mirror lowering function (foldable and heated - dimming on the driver's side)
- Chassis: Adaptive chassis control DCC including driving profile selection (allows the driver to choose between a comfortable, sporty or normal chassis setting at the touch of a button - reacts continuously to different driving situations and takes braking, steering and acceleration processes into account - body lowered by approx. 10 mm)
- IQ.LIGHT - LED matrix headlights, including dark red LED taillights (GTE) (Dynamic Light Assist high beam control for LED matrix headlights - LED taillights with dynamic turn signals - LED headlights with LED daytime running lights, cornering lights and dynamic turn signals - Dynamic headlight range control with dynamic cornering lights - Rear fog lights on both sides, reversing lights on both sides)
- Package: Ambient lighting "Plus" (multicoloured ambient lighting - LED entry/warning lights in all doors - interior lights with switch-off delay and dimming function, 2 LED reading lights each in the front and rear)
- Package: Leather package "Nappa" with top comfort seats in the front (windscreen washer nozzles automatically heated - seat center panels and inner side bolsters of the front seats and outer rear seats in "Nappa" leather - sport comfort seats in the front - heated front seats)
- Panoramic tilt/slide sunroof (with panoramic roof at the rear)
- Wheels: 4 light alloy wheels 8 J x 18 "Monterey", Volkswagen R, only in conjunction with Aquamarine Blue (in Grey Metallic - AirStop tires 235/45 R 18, optimized for rolling resistance)
- Sunshade roller blind on the rear door windows
- Auxiliary heating and ventilation (with radio remote control and timer)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Wing mirror - left side | Cap - Scratch(es) - Smart repair |
| 2 | Wheel / tyres | Alloy rim - front left side - Scratched - Loss in value |
| 3 | Wheel / tyres | Alloy rim - rear left side - Scratched - Loss in value |
| 4 | Side panel - rear left side | Side panel - Dent / paintcoat damage - Smart repair |
| 5 | Wheel / tyres | Alloy rim - front right side - Scratched - Loss in value |
| 6 | Bonnet | Bonnet - Scratch(es) - Paint |
| 7 | Vehicle glazing | Windscreen - Stone chips - repair according to calculation |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Door - rear left side | Door - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

| Description |
|---|
| Equipment - charging cable (Ladestation) |

## Accident damages

| No. | Accident |
|---|---|
| 1 | Rear, Side right |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

## Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area




**Figure 11:** VIN




**Figure 12:** Mounted tyres





**Figure 13:** Documents



**Figure 14:** Documents





**Figure 15:** Documents



**Figure 16:** Additional tyres





**Figure 17:** Navigation



**Figure 18:** Misc.



**Figure 19:** Misc.




**Figure 20:** Misc.





**Figure 21:** Misc.



**Figure 22:** Misc.




**Figure 23:** Misc.



**Figure 24:** Misc.




**Figure 25:** Misc.



**Figure 26:** Misc.



**Figure 27:** Misc.




**Figure 28:** Misc.



**Figure 29:** Misc.



**Figure 30:** Misc.



**Figure 31:** Misc.



**Figure 32:** Misc.




**Figure 33:** Misc.



**Damage 1:** Wing mirror - left side: Cap - Scratch(es) - Smart repair



**Damage 1:** Wing mirror - left side: Cap - Scratch(es) - Smart repair



**Damage 1:** Wing mirror - left side: Cap - Scratch(es) - Smart repair



**Damage 2:** Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



**Damage 2:** Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



**Damage 2:** Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



**Damage 3:** Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value




**Damage 3:** Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value




**Damage 3:** Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



**Damage 4:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



**Damage 4:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



**Damage 4:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




**Damage 5:** Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



**Damage 5:** Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




**Damage 5:** Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



**Damage 5:** Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



**Damage 6:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 6:** Bonnet: Bonnet - Scratch(es) - Paint




**Damage 6:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 7:** Vehicle glazing: Windscreen - Stone chips - repair according to calculation



**Damage 7:** Vehicle glazing: Windscreen - Stone chips - repair according to calculation




**Damage 7:** Vehicle glazing: Windscreen - Stone chips - repair according to calculation



**Wear and tear 1:** Door - rear left side: Door - Stone chips - No deduction



**Wear and tear 1:** Door - rear left side: Door - Stone chips - No deduction




**Accident 1:** Rear, Side right



**Accident 1:** Rear, Side right



**Accident 1:** Rear, Side right



**Accident 1:** Rear, Side right



**Accident 1:** Rear, Side right



**Accident 1:** Rear, Side right