ARVAL
BNP PARIBAS GROUP

2CKF393

# INSPECTION REPORT

**End of contract**

## GENERAL INFO


| | |
|---|---|
| File | 322513 |
| License plate | 2CKF393 |
| Vehicle identification number | WAUZZZGY5NA086319 |
| Dossier | 2022 202 013 |
| Make | Audi A3 Ber.30 TFSi 81kW Advan |
| Mileage | 75308 |
| First registration | 23/08/2022 |
| | |
| client availability date | 24/09/2026 |
| inspectionDate | 05/10/2026 |











## CHECK POINTS

| Description | Number | Present | Remark |
|---|---|---|---|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | N | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | Y | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |


Datum & tijd
4:41
Maandag
5.10.2026
P


B
2 - CKF - 393
BELCAR

## DAMAGES

| Damages | Type | Acceptable |
|---|---|---|
| 16 | Bumper Front // Polish | Y |
| 18 | Bumper Front / Spoiler / Replace | Y |
| 32 | Front Bonnet // Painting | Y |
| 64 | Wing Front Left // Repair & Painting | N |
| 83 | Door Front Left // Painting | Y |
| 87 | Door Front Left / Trim / Replace | Y |
| 136 | Bumper Rear // Polish | Y |
| 190 | Door Rear Right // Smart Repair Small | Y |
| 236 | Wing Front right // Polish | Y |
| 341 | Wheel Alloy Front Right // Repair | N |


## Damage Pictures





Bumper Rear // Polish-scratch






Front Bonnet // Painting-scratch







Bumper Front / Spoiler / Replace-scratch






Bumper Front // Polish-scratch





Door Front Left // Painting-scratch







Wheel Alloy Front Right // Repair-scratch






Wing Front right // Polish-scratch




Door Rear Right // Smart Repair Small-scratch




Door Front Left / Trim / Replace-scratch




Wing Front Left // Repair & Painting-scratch + dent