TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48493197
Order No. / Reference: 27185395
Inspection date: 4 Nov 2026

Manufacturer: Skoda	Model: Enyaq iV 80x
VIN: TMBLE7NY0PF098315	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Enyaq iV 80x	
Vehicle Identification number	TMBLE7NY0PF098315
Mileage (Read)	116,180 km
First registration	13 Nov 2023
Number of holders	1
Next periodical technical inspection	11/2026
(Report not on hand)	
Fuel type	Electric
Power	77 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Black Magic Pearlescent (F9R)
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black-Grey
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	360 Tag(e)
Last service on / at	10/2025 at 88,961 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV931078
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	8004 / AWT 00048		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,750 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Summer tyres on Light alloy	Bridgestone	0mm / 1mm
2)	255/50 R19 103T	Summer tyres on Light alloy	Bridgestone	1mm / 2mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	255/50 R19 103T	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments - Four roof grab handles, rear with coat hooks - High-visibility vest compartment in the doors - Storage compartments in the front door panels with 1.5L bottle holders - Storage compartments in the rear door panels - Umbrella compartments in the front doors - Ticket holder on the windshield - Ice scraper in the tailgate trim - Coat hooks on the B-pillars - Cup holders in the front center console - Storage compartments in the trunk
- Evasive steering assist including turning assistant: The turning assistant monitors oncoming vehicles when you turn left (for left-hand drive vehicles). If there is an immediate danger, it brings the vehicle to a standstill and a warning signal sounds.
- Design Selection Loft - Seat covers in fabric/faux leather - Decorative trim strips "brushed aluminum" - Headliner in gray - Front center armrest, including storage compartment - Rear center armrest with cup holders and pass-through - Floor mats - Ambient lighting for front door panels, multi-colored - Footwell lighting and illuminated door handle recesses - Umbrella
- Electric windows front and rear including anti-pinch protection and child safety lock
- Cruise control
- Transmission: 1-speed (EV)
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- Automatic interior mirror dimming
- Isofix anchorage on the front passenger seat
- Isofix anchorage on the outer rear seats including top tether
- Climatronic (2-zone) fully automatic air conditioning system, separately adjustable for driver and front passenger, including odor and allergen filter.
- LED headlights with daytime running lights
- LED taillights
- Steering wheel adjustable for height and reach
- Manual headlight range adjustment
- Multi-collision brake
- Package: Chrome - Chrome trim strips on the exterior of the side windows - AERO anodized roof rails
- Rain sensor and driving light assistant with coming and leaving home function
- Tire mobility kit, tire repair spray including compressor
- Tire pressure monitoring
- Wheels: 19" Regulus AERO alloy wheels, anthracite, polished, 8Jx19; tires: 235/55 R19 101T front, 255/50 R19 103T rear
- Seat belts - Height-adjustable three-point seat belts in the front - Three three-point seat belts in the rear - Seat belt reminder indicators on the front and rear seats
- Airbag, center airbag front
- Airbag, driver and passenger - passenger airbag can be deactivated
- Airbag, front and rear head airbags
- Airbag, front side airbags
- acoustic windscreen
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors, including automatic dimming.
- Outdoor temperature display
- Hill start assist
- AERO anodized roof rails
- Digital instrument cluster (Virtual Cockpit)
- Third brake light
- E-Sound external loudspeaker for generating a driving sound
- Electronic parking brake including auto-hold function
- Increased battery charging power max. 125 kW
- ESC Electronic Stability Control
- Front Assist with Pedestrian and Cyclist Detection and City Emergency Braking Function: The Front Assist is a safety system with collision warning. If confronted with an unavoidable collision, it brakes the vehicle to minimize the consequences. It also initiates emergency braking if a pedestrian or cyclist attempts to cross the vehicle's path. The Front Assist recognizes from the way the driver is moving the vehicle that they are attempting to avoid an obstacle and actively intervenes in the steering to maneuver around it.
- Child safety locks on the rear doors
- Removable boot cover
- Front and rear headrests are height-adjustable.
- Charging cable for AC charging stations (Mode 3 charging cable, Type 2, 16A) Fast charging connector (CCS / Combo 2)
- Steering wheel: Leather steering wheel with multifunction buttons
- Navigation system
- Front and rear parking sensors
- Radio: Infotainment system with 13" capacitive color display - 2 x USB ports (Type-C) at the front - DAB+ digital radio reception - Bluetooth hands-free phone system - Voice control - SmartLink (Apple CarPlay, Android Auto) - Wireless SmartLink
- Rear view camera
- Rear seat backrest split 60:40, foldable
- Power steering
- Safety lights in the front side doors
- Seats: Front seats height-adjustable including manually adjustable lumbar support
- Speed limiter
- Lane keeping assistant (Lane Assist)
- 12V socket - in the trunk
- Traffic sign recognition
- Immobiliser
- heat pump

- Skoda Care Connect - SOS emergency call function (eCall including automatic activation in the event of an accident with airbag deployment) - Free remote vehicle access to iV-specific functions for 10 years (iV Remote Services Basic) such as starting and stopping the charging process, creating charging schedules, setting the interior climate control before starting a journey, etc. - Mobility service - Information service - Free remote vehicle access for 3 years (Remote Access) - Skoda Infotainment Online
- Central locking including remote control integrated into the key - EASY START (keyless start-stop system)

Extra equipment

- Luggage net partition
- Paint finish: Pearl effect
- Swiveling trailer hitch including trailer stabilization
- Package: Transport - Cargo net in the trunk including charging cable bag - Variable loading floor in the trunk - Remote release of the rear seat backrests in the trunk - Cargo elements in the trunk

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Instrument panel	Indicator light (Reifendruck) - on - Perform diagnosis
2	Rear bumper	Rear bumper (unpainted) (Polier reste) - Paint defect - Loss in value
3	Front bumper	Spoiler - Scratched - Loss in value
4	Wheel / tyres	Tyre - front - Abrasion - Replace
5	Wheel / tyres	Tyre - right - Abrasion - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Damage 1: Instrument panel: Indicator light (Reifendruck) - on - Perform diagnosis



Damage 2: Rear bumper: Rear bumper (unpainted) (Polier reste) - Paint defect - Loss in value



Damage 2: Rear bumper: Rear bumper (unpainted) (Polier reste) - Paint defect - Loss in value



Damage 2: Rear bumper: Rear bumper (unpainted) (Polier reste) - Paint defect - Loss in value



Damage 2: Rear bumper: Rear bumper (unpainted) (Polier reste) - Paint defect - Loss in value



Damage 2: Rear bumper: Rear bumper (unpainted) (Polier reste) - Paint defect - Loss in value



Damage 2: Rear bumper: Rear bumper (unpainted) (Polier reste) - Paint defect - Loss in value



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Front bumper: Spoiler - Scratched - Loss in value



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 4: Wheel / tyres: Tyre - front - Abrasion - Replace



Damage 5: Wheel / tyres: Tyre - right - Abrasion - Replace



Damage 5: Wheel / tyres: Tyre - right - Abrasion - Replace



Damage 5: Wheel / tyres: Tyre - right - Abrasion - Replace



Damage 5: Wheel / tyres: Tyre - right - Abrasion - Replace



Damage 5: Wheel / tyres: Tyre - right - Abrasion - Replace



Damage 5: Wheel / tyres: Tyre - right - Abrasion - Replace



Damage 5: Wheel / tyres: Tyre - right - Abrasion - Replace