ARVAL
BNP PARIBAS GROUP

1XQQ468

INSPECTION REPORT

End of contract



GENERAL INFO

File	322686
License plate	1XQQ468
Vehicle identification number	WV2ZZZ7HZKH166432
Dossier	2019 148 127
Make	Volkswagen Multi.2.0TDi 150 Hi
Mileage	112744
First registration	12/04/2020
client availability date	25/09/2026
inspectionDate	29/09/2026







CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
1 - XQQ - 468

DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
264	Foglight Front Left // Replace	Y
271	Bumper Front / Trim Left / Replace	Y
214	Door Front Right // Repair & Painting	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	N
540	Interior // Repair 1	Y
549	Interior / Headliner/ Replace	N
801	See External Expertise	Y
883	Key Price Range 2 //	N

Damage Pictures




Trunk Compartment / Side Cover Left / Replace-missing




Door Front Right // Repair & Painting-rust





Wheel Alloy Rear Right // Repair-Chemical reaction





Wheel Alloy Rear Left // Repair-Chemical reaction





Interior // Repair 1-bad position





Interior / Headliner/ Replace-hole








See External Expertise-N comf / out of order





Wheel Alloy Front Left // Repair-scratch





Foglight Front Left // Replace-scratch





Bumper Front / Trim Left / Replace-scratch





Bumper Front // Smart Repair Large-scratch