TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48499270
Order No. / Reference: 27242509
Inspection date: 4 Nov 2026

Manufacturer: Opel	Model: Vivaro 2.0 D Cargo L EHZ Autm. Edition
VIN: VXEVFEHS7MZ111421	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Vivaro 2.0 D Cargo L EHZ Autm. Edition	
Vehicle Identification number	VXEVFEHS7MZ111421
Mileage (Read)	65,365 km
First registration	29 Mar 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	11/2026
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	106 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Quarz Silber Metallic
Doors / Seats	4 / 3
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	11 Monat(e)
Last service on / at	09/2025 at 50,316 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF966927
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3003 / BCD 00335		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,100 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	Summer tyres on Steel	Continental	4mm / 4mm
2)	215/65 R16 109T	Summer tyres on Steel	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Driver and passenger side airbags
- Exterior mirrors, electrically adjustable, heated and manually folding
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- third brake light
- Tachometer
- Electronic Stability Program (ESP Plus)
- Speed controller and limiter
- Grab handle in the first row of seats, passenger side
- Air conditioning, front with particle and odor filter (recirculation mode, manual)
- Parkpilot, rear parking aid
- Wheels: Steel wheels 7 J x 16 with wheel hub cover (tires 215/65 R 16 C 106T)
- Side protection strips
- Visibility equipment
- 12-volt power outlet in the center console
- Daytime running light
- Traction control with engine and brake intervention (TC Plus)
- Doors: Sliding door, passenger side
- Lashing eyes (8) in the cargo area
- Heat-insulating glazing, tinted
- Payload increased by +400 kg
- ABS including brake assist and adaptive brake light
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirror housings in black
- Hill Start Assist
- On-board computer
- Diesel particulate filter, maintenance-free
- Three-point seat belts in all seats
- Electric front windows
- Transmission: 8-speed automatic
- Glove compartment closed at the top
- Steering column, adjustable for reach and height
- Fatigue detection level 1 coffee break
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Side impact protection
- Speed-sensitive power steering
- Sun visors, driver and passenger
- 12V power outlet in the cargo area and in the lower glove compartment
- Partition wall: closed, without windows
- Doors: Rear wing doors, sheet metal with a 180° opening angle
- Electronic immobilizer
- Central locking with remote control
- Ignition key (2), foldable

Extra equipment

- Exterior mirrors, electrically folding, heated and adjustable
- Paint finish: Metallic
- Package: Driver Assistance Package 1 (High Beam Assist - Driver Alert System with Camera Monitoring - Lane Keeping Assist - Traffic Sign Recognition with Intelligent Speed Control - Solar Reflect Windscreen)
- Upholstery: Fabric / faux leather with grey dashboard underside
- Keyless locking and starting system "Keyless Open & Start"
- Seats: Comfort driver's seat and double passenger seat (comfort driver's seat adjustable in 6 ways, with armrest and lumbar support - double passenger seat with storage under the seat - height-adjustable headrests, front)
- Bott assembly according to offer DED025H0001123-01
- Steering wheel: Multifunction leather steering wheel
- Package: INNOVATIONS package (Driver Assistance Package 2 - Head-Up Display - Park Pilot, front and rear parking aid - 180-degree panoramic reversing camera - Blind Spot Warning - Multimedia Navi Pro - Digital radio reception DAB+ - OpelConnect)
- Radio accessories: Digital radio reception DAB+ (Digital Audio Broadcasting) (Offers a wider selection of radio programs. Digitally broadcast radio stations and traffic information can be received.)
- Heated seats for driver and front passenger (in conjunction with double passenger seat, the middle seat is not heated - side and head airbags, 1st row of seats)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Side panel - rear left side	Side panel - Dent / paintcoat damage - Loss in value
3	Door - front right side	Door - Scratch(es) - Smart repair
4	Sliding door, right	Sliding door - Scratch(es) - Smart repair
5	Boot lid / rear door	Rear door - right side - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Dent / paintcoat damage - No deduction
2	Body	Body - Dent / paintcoat damage - No deduction
3	Sill - right side	Sill - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Side panel - rear left side: Side panel - Dent / paintcoat damage - Loss in value



Damage 2: Side panel - rear left side: Side panel - Dent / paintcoat damage - Loss in value




Damage 2: Side panel - rear left side: Side panel - Dent / paintcoat damage - Loss in value



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Sliding door, right: Sliding door - Scratch(es) - Smart repair



Damage 4: Sliding door, right: Sliding door - Scratch(es) - Smart repair



Damage 5: Boot lid / rear door: Rear door - right side - Deformed - Repair and paint



Damage 5: Boot lid / rear door: Rear door - right side - Deformed - Repair and paint