ARVAL
BNP PARIBAS GROUP

2EAJ389

INSPECTION REPORT

End of contract

GENERAL INFO

File	320038
License plate	2EAJ389
Vehicle identification number	WVGZZZE20PP016823
Dossier	2022 313 172
Make	Volkswagen ID.4 77kWh 128kW Pr
Mileage	160957
First registration	04/08/2023
client availability date	12/08/2026
inspectionDate	25/08/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	


D / B
PARK
N
R
160957 km
26 %
117 km


B
2-EAJ-389
BELCAR

DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	Y
81	Door Front Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	N
156	Rear Bonnet // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y


Damage Pictures




Interior // Repair 1-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch

Door Front Left // Smart Repair Medium-scratch

Door Rear Left // Polish-scratch




Door Front Left // Smart Repair Small-scratch




Rear Bonnet // Polish-scratch










Front Bonnet // Polish-scratch







Wing Rear Right // Smart Repair Small-dent





Wing Rear Left // Repair & Painting-scratch + dent