ARVAL
BNP PARIBAS GROUP

2FAW596

INSPECTION REPORT

End of contract


GENERAL INFO

File	319603
License plate	2FAW596
Vehicle identification number	JMZKF6W1A90380348
Dossier	2024060010
Make	Mazda CX-5 2.2D 150 Homura A.
Mileage	88864
First registration	11/03/2024
client availability date	12/08/2026
inspectionDate	10/09/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	




B
2-FAW-596
BELCAR


DAMAGES

Damages	Type	Acceptable
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
801	See External Expertise	N
19	Bumper Front / Lower Cover Not Painted / Replace	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
124	Light / Rear left / Replace	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
331	Wheel Alloy Rear Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures




Light / Rear left / Replace-scratch

Door Rear Left // Painting-scratch





Door Front Left // Painting-scratch




Bumper Front / Lower Cover Not Painted / Replace-scratch







Door Rear Right // Painting-scratch




Wheel Alloy Rear Right // Repair-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rocker Panel Right // Smart Repair Medium-scratch





Door Front Right // Repair & Painting-scratch + dent





Windshield // Repair-glass damage






Front Bonnet / Insulation / Replace-Chemical reaction






Bumper Rear // Polish-scratch




Wing Rear Left // Polish-scratch



See External Expertise-stone chipping