DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	VR1JCYHZ7 RY630052	Registration date	16/12/2024	Exterior Color	Unknown
Brand	DS	Licence Plate	EU-FA 8218	Odometer	63 420 km
Model	DS 7 BlueHDi 130 Performance Line Automa				

Inspection Details

Arrival Date	28/07/2026	Inspection ID	7090087	Inspection date	03/08/2026
Assign Date	28/07/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Zörbig



Generic equipment

Removable element


Spare wheel kit	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Remote key	✓
Service	✓

Tyres

Hankook 235/50/19 W All seasons 7.0 mm	Hankook 235/50/19 W All seasons 7.0 mm
Hankook 235/50/19 W All seasons 5.0 mm	Hankook 235/50/19 W All seasons 4.0 mm





Exception / Damage

1



Part	Service 2	Repair Time	-	Part Cost	300.00€
Position	-	Repair Cost	-	Gross Cost	300.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**300.00€**

2



Part	Tailgate / Boot door	Repair Time	-	Part Cost	-
Position	Down	Repair Cost	-	Gross Cost	126.00€
Damages	Scratched	Paint Time	1.40	Depreciation %	-
Severity	-	Paint cost	126.00€	Depreciation	-
Repair mode	Repair	Flat Rate	-	**Net Cost**	**126.00€**

3



Part	Tailgate / Boot door badge	Repair Time	0.20	Part Cost	42.62€
Position	Back	Repair Cost	14.00€	Gross Cost	56.62€
Damages	Worn out	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**56.62€**

4



Part	Tailgate / Boot door badge	Repair Time	0.20	Part Cost	44.63€
Position	Back	Repair Cost	14.00€	Gross Cost	58.63€
Damages	Worn out	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**58.63€**

5



Part	Diamond Cut rim 19"	Repair Time	0.50	Part Cost	387.73€
Position	Back right	Repair Cost	35.00€	Gross Cost	422.73€
Damages	Rusty	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**422.73€**

Weissrost

6



Part	Diamond Cut rim 19"	Repair Time	0.30	Part Cost	387.73€
Position	Front right	Repair Cost	21.00€	Gross Cost	408.73€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**408.73€**

7

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

8

Part	Bonnet	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

9

Part	Windscreen	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

10		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	**Net Cost**	**-**
11		Part	Engine cover	Repair Time	0.10	Part Cost	139.17€
		Position	Front	Repair Cost	7.00€	Gross Cost	146.17€
		Damages	Broken	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**146.17€**
12		Part	Engine soundproofing	Repair Time	0.20	Part Cost	206.11€
		Position	Front	Repair Cost	14.00€	Gross Cost	220.11€
		Damages	Broken	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**220.11€**

Summary Inspection

Gross Price	1,738.99€	Depreciation	-	Net Price	1,738.99€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	70.00€	1.50	105.00€	-	-	105.00€
Paintwork	90.00€	1.40	126.00€	-	-	126.00€
Paint preparation	90.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	1,507.99€	-	-	1,507.99€
Flat Rate	-300.00€	-	-	-300.00€