DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	VR1JCYHZ6 RY632066	Registration date	16/12/2024	Exterior Color	Unknown
Brand	DS	Licence Plate	EU-FA 8208	Odometer	40 863 km
Model	DS 7 BlueHDi 130 Performance Line Automa				

Inspection Details

Arrival Date	21/08/2026	Inspection ID	7161837	Inspection date	15/09/2026
Assign Date	21/08/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Dortmund



Generic equipment

GPS system	✔
Alloy wheel rims	✔

Removable element

Spare wheel kit	✔
Toolkit	✔
Rear parcel shelf	✔
Floor mat BR	✔
Floor mat BL	✔
Floor mat FR	✔
Floor mat FL	✔


Technical Document

User manual	✔
Warranty booklet	✔
Log books	✔
Spare key	✔
Key	✔
Remote key	✔
Service	✖

Tyres

Hankook 235/50/19 W All seasons 4.0 mm

Hankook 235/50/19 W All seasons 4.0 mm



Hankook 235/50/19 W All seasons 4.0 mm

Hankook 235/50/19 W All seasons 4.0 mm

Exception / Damage

1



Part	Bumper	Repair Time	1.20	Part Cost	-
Position	Front right	Repair Cost	84.00€	Gross Cost	201.00€
Damages	Scratched	Paint Time	1.30	Depreciation %	10.00%
Severity	-	Paint cost	117.00€	Depreciation	- 20.10
Repair mode	Repair	Flat Rate	-	**Net Cost**	**180.90€**

2



Part	Wing	Repair Time	1.00	Part Cost	-
Position	Front right	Repair Cost	70.00€	Gross Cost	223.00€
Damages	Dent & Chips	Paint Time	1.70	Depreciation %	10.00%
Severity	-	Paint cost	153.00€	Depreciation	- 22.30
Repair mode	Repair	Flat Rate	-	**Net Cost**	**200.70€**

übermalt.

3



Part	Door	Repair Time	-	Part Cost	-
Position	Front right	Repair Cost	-	Gross Cost	50.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	50.00€	**Net Cost**	**50.00€**

4



Part	Door sill	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	150.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Lumpsum repair	Flat Rate	150.00€	**Net Cost**	**150.00€**

5



Part	Door	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	50.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	50.00€	**Net Cost**	**50.00€**

6



Part	Diamond Cut rim 19"	Repair Time	0.50	Part Cost	387.73€
Position	Back right	Repair Cost	35.00€	Gross Cost	422.73€
Damages	Scratched	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	- 42.27
Repair mode	Replace	Flat Rate	-	**Net Cost**	**380.46€**

7



Part	Door sill	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	150.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Lumpsum repair	Flat Rate	150.00€	**Net Cost**	**150.00€**

8



Part	Interior tailgate lining	Repair Time	-	Part Cost	-
Position	Back	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

DEKRA Automotive Solutions

Comments

fahrzeug nass u. verschmutzt.

Summary Inspection

Gross Price	1,246.73€	Depreciation	-84.67€	Net Price	1,162.06€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	70.00€	2.70	189.00€	10.00 %	-18.90€	170.10€
Paintwork	90.00€	3.00	270.00€	10.00 %	-27.00€	243.00€
Paint preparation	90.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	387.73€	10.00 %	-38.77€	348.96€
Flat Rate	400.00€	-	-	400.00€