TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 47853745
Order No. / Reference: 27015546
Inspection date: 30 Sept 2026

Manufacturer: Opel	Model: Mokka 1.2 DI Turbo Edition
VIN: VXKUSHNEKNW058927	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Mokka 1.2 DI Turbo Edition	
Vehicle Identification number	VXKUSHNEKNW058927
Mileage (Read)	96,827 km
First registration	26 Sept 2022
Number of holders	1
Fuel type	Petrol
Engine displacement / Cylinder	1,199 ccm / 3
Power	74 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Diamant Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7 Monat(e)
Last service on / at	04/2026 at 96,089 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ699344
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADA 00015		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,700 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Summer tyres on Light alloy	Pirelli	7mm / 7mm
2)	215/65 R16 102H	Summer tyres on Light alloy	Pirelli	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 98H	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/65 R16 98H	Winter tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, one of which has a radio remote control, foldable
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- Headliner, Grey
- Decorative strips, silver
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: 6-speed manual
- Child safety lock in the rear doors, manual
- Headrests (2)
- LED headlights
- Steering column, height and tilt adjustable
- Reading lights, front
- Multi-collision brake
- Otto particulate filter
- Radio accessories: Digital radio reception DAB+
- Wheels: Tire repair kit
- Speed-sensitive power steering
- Seats: Passenger seat 4-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, rear outer
- 12-volt power outlet
- Underride protection look, front and rear, in body color
- Tinted heat-insulating glazing
- Storage compartments
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors in black
- Roof design line in chrome
- Roof spoiler, black
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Rear shelf
- Air conditioning with pollen filter
- Rear headrests (3), height adjustable
- Steering wheel: Leather steering wheel, flattened at the bottom
- Makeup mirror in sun visor, driver and front passenger
- Fatigue detection
- Upholstery: Cloth
- Wheels: Light alloy (4) 5 double spokes 6.5 x 16
- Side impact protection
- Seat belts
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Traffic sign recognition
- Central locking with remote control

Extra equipment

- Radio: Multimedia Navi (with 7" color touchscreen display and fully digital 7" driver information display - Navigation with integrated memory - European road map - 3D map display - Dynamic route guidance via map and/or arrow display - Display of points of interest - Trip plan. - OpelConnect GPS module, including LIVE navigation services: - Map updates. - Voice control for audio, telephone and navigation. - Radio, Bluetooth, DAB+, USB, hands-free.)
- Steering wheel: Heated leather steering wheel
- 2 ignition keys, both foldable
- Paint finish: Metallic
- Parkpilot, rear parking aid with acoustic warning signal when reversing (180-degree panoramic reversing camera)
- Seats: Heated seats, multi-stage, driver and front passenger
- Visibility equipment (front rain sensor - automatic dimming headlights with tunnel detection - interior rearview mirror, automatically dimming)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Gearbox	Gear knob - Damaged - Replace

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 27 Nov 2025	2.607,95 €
2	Side right, Provided by user / customer, from 15 Oct 2022	5.947,11 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Der beiliegende Radsatz ist nicht Bestandteil der vorliegenden Fahrzeugausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Additional tyres



Figure 20: Additional tyres



Figure 21: Navigation



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Gearbox: Gear knob - Damaged - Replace



Damage 2: Gearbox: Gear knob - Damaged - Replace