
APPRAISAL REPORT



VEHICLE IDENTIFICATION

Make:	VOLKSWAGEN
Model / version:	GOLF VIII
Wine:	WVWZZZCD9PW310901
Plate:	2DUA346
Mileage:	83800
SOH:	
First registration:	26/06/2023
Color:	deep black p







ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book	
Number of keys:	2
Original key:	✓


PICTURES









































WINE INFORMATION

Radio	Radio with navigation system	7 speakers
Bluetooth	Sequential transmission	6 reports
Differential lock	Automatic headlights	LED spotlights
Style Equipment	Chrome window surround	Material: alloy
Reference letter (J)	Front diameter 16	Rear diameter 16
Front width 7.0	Rear width 7.0	Front diameter 16
Rear diameter 16	Front height 55	Rear height 55
Forward speed index V	Rear speed index V	Front width 205
Rear width 205	Rear air conditioning	3-zone automatic climate control
Front center armrest	Rear center armrest	Chrome interior finish
Petrol hybrid	1395 cm3	1.40 liters
150 kW	204 hp	Euro 6

Pearlescent varnished effect
Standard maintenance
Front disc brakes
Rear disc brakes
Electrically adjustable left-side mirror
Electrically adjustable right-side mirror
Heated left-side mirror
Heated right-side mirror
Electrically folding mirrors
Rétroviseur intérieur jour/nuit automatique
Siège avant gauche à réglage électrique
Siège avant gauche à réglage mémorisé
Siège avant gauche à réglage lombaire
Sièges avant massants
Fixations Isofix siège passager avant
Garnitures tissu et Alcantara
Volant cuir
Volant multifonction
Aide au stationnement avant
Aide au stationnement arrière
Caméra avant
Caméra arrière de recul
Régulateur automatique de la distance
Affichage lecture des panneaux de signalisation
Carte mains libres
Appel de secours
détecteur de pluie essuie-vitre
Ceintures de sécurité arrière à enrouleur
Témoin d'oubli de ceinture avant
Témoin d'oubli de ceinture arrière
Assistant maintien de la voie
Freinage d'urgence assistée autonome (urbain)
Avertisseur d'angle mort
depuis 04.23
Digital Cockpit Pro
grille de calandre et poignées de portes éclairées
antenne AM/FM
Car2X communication
radio digitale (DAB)
services Online
connexion USB av/ar
boulons de roue avec antivol
garnitures de portes en simili-cuir noir/gris silex
ceintures de sécurité avant avec prétensionneurs et tensionneur final
éclairage d'ambiance
suspension ar à 4 bras
câble de charge pour prise domestique Mode 2 Type 2 E+F (10A) EV3
câble de charge pour station de recharge publique Mode 3 Type 2 3P (16A) 76C
e-Sound avec haut-parleurs av
transmission hybride PHEV
airbag central entre les sièges av
réservoir à charbon actif (EVAP)

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	3 mm		205/55R16 94V	All seasons		?
Front right	3 mm		205/55R16 94V	All seasons		?
Rear left	3 mm		205/55R16 94V	All seasons		?
Rear right	3 mm		205/55R16 94V	All seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
1	Alloy rim FL polished	Grooved
3	Rear window - Remove stickers	Not original part
4	Alloy rim RR polished	Grooved

Total: 3

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Teeth and scratches	✓	✗	✗

Total: 1

DAMAGE DETAILS

1 - Alloy rim FL polished - Grooved





3 - Rear window - Ontstickeren - Not original part





4 - Alloy rim RR polished - Grooved






2 - Bodywork - Dent(s) and scratch(es) - Renta®









SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

01/10/2026 13:42

