DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	VR7ARHNSK PL069554	Registration date	02/08/2024	Exterior Color	Unknown
Brand	CITROEN	Licence Plate	H-KC 8952	Odometer	25 762 km
Model	C5 AIRCROSS PureTech 130 Stop&Start PLUS				

Inspection Details

Arrival Date	30/09/2026	Inspection ID	7202679	Inspection date	05/10/2026
Assign Date	30/09/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys SLC Essen



Generic equipment

GPS system	✔
Alloy wheel rims	✔

Removable element

Spare wheel kit	✔
Toolkit	✔
Rear parcel shelf	✔


Technical Document

User manual	✔
Warranty booklet	✔
Log books	✔
Spare key	✔
Key	✔
Remote key	✔
Service	✔

Tyres

Michelin 225/55/18 V Summer 6.0 mm

Michelin 225/55/18 V Summer 6.0 mm



Michelin 225/55/18 V Summer 6.0 mm

Michelin 225/55/18 V Summer 6.0 mm



Exception / Damage

DEKRA

DEKRA Automotive Solutions

Appraisal Report

1		Part	Diamond Cut rim 18"	Repair Time	0.50	Part Cost	327.60€
		Position	Front right	Repair Cost	70.00€	Gross Cost	397.60€
		Damages	Scratched	Paint Time	-	Depreciation %	15.00%
		Severity	-	Paint cost	-	Depreciation	- 59.64
		Repair mode	Replace	Flat Rate	-	**Net Cost**	**337.96€**

Summary Inspection

Gross Price	397.60€	Depreciation	-59.64€	Net Price	337.96€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.50	70.00€	15.00 %	-10.50€	59.50€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	327.60€	15.00 %	-49.14€	278.46€
Flat Rate	0.00€	-	-	0.00€