MAGADAM

BMW X1

Vehicle information


Make:	**BMW**	License:	**2BWJ263**
Gearbox:		Body color:	
Model:	**X1**	VIN:	**WBA71AB0905V31020**
Fuel type:		Power:	**92 kW**
Version:	**1.5 XDRIVE25E PHEV 162KW)**	First registration	**19/04/2022**
Mileage:	**119332 km**	N° of doors:	


Damage summary


- **Front** 3
- **Interior** 2
- **Left** 6
- **Rear** 4
- **Right** 2
- **Roof & others** 3

Commercial pictures































Options according to the inspector

GPS	**Yes**

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left






Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right
















Bodywork
Damaged
Acceptable
Roof & others


































Bodywork
Lettering
Sticker removal
Roof & others





Boot lid covering R
Scratch(es)
Smart repair
Rear







Bumper moulding F
Missing
Replace
Front





Bumper moulding R
Scratch(es)
Spot repair
Rear







Bumper R
Scratch(es)
Polish
Rear







Bumper trim R
Scratch(es)
Smart repair
Rear




Door FL
Scratch(es)
Touch up
Left




Door FL
Scratch(es)
Paint
Left





Door RL
Scratch(es)
Polish
Left






Door RR
Scratch(es)
Paint
Right





Door seal FL
Deformed / Strained
Replace
Left




Headlight L
Scratch(es)
Polish
Front




Interior
Stain
Acceptable
Interior





Roof
Scratch(es)
Polish
Roof & others





Seat cover FL
Worn
Acceptable
Interior





Windscreen
Stone chip(s)
Windscreen repair
Front


Wing FL
Dent(s)
Paintless dent repair
Left





Tyres

Front Left
All season
225/55/17/101/W
Bridgestone
6.0 mm
Front Right
All season
225/55/17/101/W
Bridgestone
6.0 mm
Rear Left
All season
225/55/17/101/W
Bridgestone
6.0 mm
Rear Right
All season
225/55/17/101/W
Bridgestone
6.0 mm

Checks

Category	**Passenger Car**	Compressor	**Yes**
Maintenance	**OK**	Maintenance	**24000.0**
Number of charging cables (normal)	**1**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**Yes**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Statutory inspection	**OK**
Statutory inspection	**19/04/2028**	Type of Maintenance book	**Digital maintenance**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.