MACADAM








KIA PICANTO: 2CFV439

Vinnumber:	**KNAB351AANT937157**	Versionname:	
First Registrationdate:	**7/07/2022**	Fiscalpower:	
Expertise Mileage:	**67121**	Power Kw:	**61**
Bodytype:		Body colour	**Black**
Gearbox:	**MAN 5 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:	**Front**		
Fueltype:	**Petrol**		
Maintenance	**NOT OK**		
Maintenance	**- 1935km en - 227 dagen**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Board Computer			
Steering wheel multifunctional			
Steering wheel leather			
Type of headlighting	**Headlighting Halogen**		
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining fabrics**		
Type of climate control	**Autom climate control**		
Type of radio	**Multimedia**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**185/55/15/86 H**			
	Fr.L.	**Semperit: 6 mm**	Fr.R.	**Semperit: 6 mm**
	Re.L.	**Semperit: 7 mm**	Re.R.	**Semperit: 6 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**185/55 R 15 86 H**
Tyre size FR	**185/55 R 15 86 H**
Tyre size RL	**185/55 R 15 86 H**
Tyre size RR	**185/55 R 15 86 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**2477**
Tyre make FR	**2477**
Tyre make RL	**2477**
Tyre make RR	**2477**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Total cost ex VAT	**1667,89**
Service, Maintenance, Execute	**0,00**



Instrument panel, complete, Scratch(es), Acceptable	0,00



Door panel FL, Scratch(es), Acceptable	0,00




Door panel RL, Scratch(es), Acceptable	0,00




Seat cover R, Stain, Cleaning	32,07





Interior covering A pillar L, Scratch(es), Smart repair	121,70




Centre console, Scratch(es), Acceptable	0,00




Bonnet, Chemical polution, Repair and paint (complete)	319,09





Alloy rim FL polished, Chemical polution, Acceptable	0,00






Door FL, Dent(s) and scratch(es), Repair and paint (complete)	350,20



Step L, Dent(s), Acceptable	0,00



Door RL, Scratch(es), Acceptable	0,00



Step L, Dent(s) and scratch(es), Spot repair	183,21



Wing RL, Dent(s) and scratch(es), Acceptable	0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)	161,12






Internal boot lining L, Scratch(es), Acceptable	0,00






Internal boot lining R, Scratch(es), Acceptable	0,00





Boot cover, Scratch(es), Acceptable	0,00





Luggage compartment cover, Incomplete, Forfeit	15,00





Boot lid covering R, Scratch(es), Acceptable	0,00




Tailgate / Boot, Dent(s), Paintless dent repair	69,30





Bumper R, Scratch(es), Repair and paint (complete)	232,99









Step R, Dent(s) and scratch(es), Spot repair	183,21





Alloy rim RR polished, Chemical polution, Acceptable	0,00






Wing RR, Scratch(es), Acceptable	0,00





Door RR, Scratch(es), Acceptable	0,00





Door FR, Scratch(es), Acceptable	0,00




Central pillar R, Scratch(es), Acceptable	0,00





Outside rear-view mirror housing R, Scratch(es), Acceptable	0,00




Alloy rim FR polished, Chemical polution, Acceptable	0,00





Roof, Chemical polution, Acceptable	0,00





