TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

# Expertise

Protocol number: 48529419
Order No. / Reference: 27256202
Inspection date: 4 Nov 2026

| Manufacturer: Mercedes-Benz | Model: E 300 e T 9G-TRONIC Exclusive |
|---|---|
| VIN: W1K2132531B041402 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Mercedes-Benz E 300 e T 9G-TRONIC Exclusive | |
| **Vehicle Identification number** | W1K2132531B041402 |
| **Mileage** (Read) | 110,964 km |
| **First registration** | 8 Mar 2022 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 03/2027 |
| (Report not on hand) | |
| **Fuel type** | Hybr.B/E ext.aufl |
| **Engine displacement / Cylinder** | 1,991 ccm / 4 |
| **Power** | 155 kW |
| **Gearbox / Number of gears** | Automatic / 9 |
| **Type of drive** | Rear drive |
| **Type of vehicle** | Station wagon |
| **Colour / colour code** | Black University |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Leather |
| **Colour of upholstery** | Black |
| **Re-import** | no |
| **readiness to drive** | Roadworthy |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 294 Tag(e) |
| **Last service on / at** | 10/2025 at 90,632 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GF791351 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **readiness to drive** | Roadworthy | | |
| **Manufacturer key number/ type code number** | 2222 / ATK 00029 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,755 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 245/45 R18 100V | Winter tyres on Light alloy | Continental | 6mm / 6mm |
| 2) | 275/40 R18 103V | Winter tyres on Light alloy | Continental | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 245/45 R18 100Y | Summer tyres on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 275/40 R18 103Y | Summer tyres on Light alloy | Pirelli | 5mm / 5mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Airbag: Kneebag for driver
- Airbag: Sidebag for driver and front passenger (combined thorax/ pelvisbag)
- Airbag: Windowbags left/right
- Acoustic Surrounding Protection (To ensure that your vehicle does not become a danger to pedestrians and cyclists even when driving purely electrically and almost silently, the Acoustic Surrounding Protection system generates a Mercedes-Benz specific sound outside the vehicle up to a speed of 30 km/h. The so-called Acoustic Vehicle Alerting System (AVAS) cannot be deactivated.)
- Foldable armrest for driver and front passenger
- Exterior mirrors, left and right, heated and electrically adjustable, painted in car color (with aspherical curved mirror glass and integrated LED turn signal)
- Basic services (breakdown management, maintenance management, accident management, telediagnosis, remote vehicle diagnostics)
- On-board computer
- Brake Assist, active (can help you avoid rear-end collisions with vehicles ahead, whether moving or stationary, as well as collisions with moving pedestrians or cyclists. In addition to distance and collision warnings, the system primarily offers situation-appropriate brake boosting – up to and including autonomous emergency braking.)
- EASY-PACK cargo cover including EASY-PACK safety net
- EASY-PACK tailgate (makes loading and unloading the luggage compartment even more convenient. You can easily start opening and closing with the push of a button and interrupt it at any time by pressing the control again.)
- Chassis: AGILITY CONTROL chassis with selective damping system (combines balanced driving comfort and high driving stability. Thanks to the passive damping system, you enjoy a confident driving experience on any road surface: rolling behavior, damping effect and stabilization are continuously and automatically adapted to the current surface.)
- Heated rear window with timer
- Instrument panel and door sills in ARTICO man-made leather
- THERMATIC automatic climate control (2-zone automatic climate control: allows individually adjustable temperature for driver and front passenger - climate settings can be controlled via the multimedia system or the climate control unit in the center console - automatic recirculation (only in conjunction with navigation) - fine dust activated carbon filter for filtering dust, soot and pollen as well as reducing pollutants and odors - dew point sensor, continuous defrost nozzle under the windshield and central defrost outlet)
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation (The system automatically deactivates the passenger airbag as soon as it detects a rear-facing child seat or registers that the passenger seat is unoccupied. A transponder in the child seat is not necessary. If it detects that an adult is taking the seat, the airbag is automatically activated, reducing the risk of incorrect operation.)
- Premium ambient lighting with 64 colors and 3 color zones
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Attention Assist (can detect typical signs of fatigue based on driver behavior and warn the driver of increasing tiredness or inattentiveness. This system can increase driving safety, especially on long journeys and at night. ATTENTION ASSIST detects typical signs of fatigue and severe inattentiveness based on steering behavior and warns the driver visually and audibly of impending microsleep.)
- Tachometer
- Third brake light
- DYNAMIC SELECT (The DYNAMIC SELECT driving programs change the driving behavior of your Mercedes at the touch of a button. For example, you can control the characteristics of the engine, transmission, suspension and steering to suit the driving situation: whether dynamic in Sport mode, completely relaxed in Comfort mode or particularly economical in Eco mode. You determine the style of your drive.)
- Electronic Stability Program (ESP) (with traction control (ASR))
- Chassis: Air suspension on the rear axle with level control
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Velour floor mats (in interior color)
- Transmission: 9-speed automatic, 9G-TRONIC (including DIRECT SELECT gear selector and DIRECT SELECT steering wheel shift paddles)
- rear window wiper
- KEYLESS START
- Climate: Pre-conditioning
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- Paint finish: Solid
- Charging cable for household socket, 5m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 1.8 kW (230 V, 1-phase, 8A) and fits sockets of type E/F CEE 7/7)
- Charging system: AC charging system 7.4 kW

- LED High Performance headlights (low beam in LED reflection technology - high beam in LED reflection technology - signal light with trifunctional torch for daytime running light, position light and direction indicator in LED technology - adaptive full-LED taillights)
- Steering column mechanically adjustable in height and length
- Mercedes-Benz Emergency Call System (can provide a crucial time advantage in an emergency. A communication module with its own SIM card automatically triggers an emergency call in the event of an accident, which can shorten the time until emergency services arrive. The emergency call can also be triggered manually to organize rapid assistance.)
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: Storage (for plug-in hybrid) (Double cup holder in the center console - Map pockets on the back of the front seats)
- Package: Public Charging (charging cable for wallbox and public charging stations, 5m, smooth (charging the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A)) - Remote and Charging Services Plus)
- Package: Seating comfort (various electric and manual adjustment options for the front seats to adapt to the specific body and comfort requirements of the driver and front passenger - electro-pneumatic 4-way lumbar support with control element on the seat - electric seat cushion tilt adjustment - electric height adjustment - electric backrest adjustment - mechanical seat cushion depth adjustment by 6 cm with leg rest pad - mechanical longitudinal adjustment - mechanical headrest adjustment)
- Radio: MBUX Multimedia System (Enjoy the beauty and intelligence of a digitized multimedia system. You decide which information it displays. Look forward to a fully digital cockpit consisting of two 10.25-inch displays with touch functionality for the media display. - Bluetooth interface - USB - SD card / SDHC card - Dual tuner radio - Online-enabled multimedia system)
- Radio accessory: Communication module (LTE) for using Mercedes me connect services (The communication module (LTE) offers you a clear increase in comfort and safety. It constantly connects the vehicle to the internet – so that you can use helpful services such as the Live Traffic Information from Mercedes me connect. Two mobile antennas and an LTE-enabled SIM card ensure a fast connection.)
- Windscreen wipers with rain sensor (with 2 sensitivity levels - the electronically controlled rain sensor makes driving more relaxed in adverse weather conditions - the system detects whether the windscreen is wet and, when intermittent wiping is activated, automatically adjusts the wiper frequency to the appropriate level depending on the amount of precipitation)
- Power steering
- Seats: i-Size child seat attachment (on the outer rear seats - The system allows for quick and secure attachment of i-Size and ISOFIX child seats in the rear for the best possible protection of the child in the event of an accident. Top tether attachment points offer additional safety by anchoring the child seat behind the rear headrests.)
- Steering wheel: Multifunction steering wheel in Nappa leather in a 3-spoke design (spokes in high-gloss black with silver chrome trim - shift paddles in silver chrome - control via touch panels: left: instrument cluster, cruise control and speed limiter or Active Distance Assist DISTRONIC; right: multimedia system (e.g., audio volume and track selection, telephony and navigation); touch sensitivity adjustable via media display)
- Center console with spontaneous storage (storage compartment under the armrest with 2 USB ports (Type C) and open storage on the back -cupholders front and rear -storage compartments in the door panels with cup holders -lockable, air-conditioned glove compartment -glasses compartment in the overhead control unit (not included with MBUX Interior Assistant))
- Navigation: Hard drive navigation (Mercedes-Benz look and feel of navigation, all map data stored on hard drive, fast hard drive navigation, up-to-date map data through 3 years of free map updates (from initial registration, vehicle-specific), destination input via touch function or voice control, route calculation including waypoints, numerous route options (Eco, Trailer, Fast, Short, Automatic, etc.) as well as avoidance options (motorways, ferries, tunnels, toll roads, unpaved roads, car trains, vignette roads))
- Upholstery: ARTICO man-made leather
- PRE-SAFE system (This system can detect critical driving situations in advance and initiate preventive measures to protect the occupants if an accident is imminent. In addition to reversible seatbelt tensioning and other measures, PRE-SAFE Sound is now also included in its range of functions.)
- Radio: Extended MBUX functions (personalization (profiles) and prediction functions - LINGUATRONIC with natural language understanding - activation via Hey Mercedes - Wi-Fi hotspot - internet radio)
- Radio accessories: Digital radio (For the DAB, DMB and DAB+ standards. The digital radio offers noise-free, CD-quality sound via DAB (including DAB+ and DMB) and program-related additional information, e.g., album art, weather maps, news and traffic maps. Three DAB tuners ensure the best possible reception quality for the selected station in the background.)
- Tire pressure monitoring system (continuously monitors the inflation pressure of all four tires)
- Remote Services Plus (Communication module - Mercedes me services: remote vehicle status query, programming of auxiliary heating/ventilation, remote door locking and unlocking, sunroof/ windows with remote locking and opening including ventilation remote control, personalization, vehicle location, vehicle tracking, geographic vehicle monitoring, parking service monitoring, finder function (Remote Vehicle Finder), notification in case of exceeding the driving speed, Send2Car-Fun, accident and breakdown management, maintenance management, telediagnosis, remote vehicle diagnostics, software updates)
- Seats: Rear seat backrests foldable 40/20/40 split (EASY-PACK Quickfold - double cupholder - storage compartment)

- Touchpad (integrated into the center console, including a palm rest - single and multi-finger gestures, swipe movements and zoom gestures by spreading and pinching the fingers - recognizes handwritten characters: letters, special characters and numbers - clear haptic feedback)
- Green heat-insulating glass all around (including rear window made of single-pane safety glass)
- Power outlet: 12V socket in the cargo area (For connecting notebooks, MP3 players, mobile phones, coolers and other electrical devices.)
- High-visibility vest for drivers
- Electronic immobilizer (including locking system with 3-channel radio remote control in the electronic key in chrome look, optical locking feedback and emergency opening (approved by AZT and TÜV))
- Central locking

### Extra equipment

- Adaptive High Beam Assist (You activate the system with one operation and then benefit from the long beam range.)
- EXCLUSIVE Interior
- Discount code for MBUX Augmented Reality removal
- Package: Business (MBUX High-End Package - Connectivity Package Navigation - Traffic Sign Assist - Smartphone Integration (Apple CarPlay and Android Auto) - Preparation for Digital Key Handover - Widescreen Cockpit - Wireless Charging System for Mobile Devices - MBUX Augmented Reality for Navigation - Heated Seats for Driver and Front Passenger - Parking Package with Rearview Camera - Fuel Tank with 66 Liter Capacity (916) (60l for Diesel Plug-in Hybrids).)
- Package: Mirrors (both exterior mirrors electrically foldable (button in the driver's door control panel) - automatic lowering of the passenger-side mirror glass to parking position when reverse gear is engaged - interior mirror and driver's side exterior mirror automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area)
- Decorative elements, wood, ash, grey, open-pore
- Towbar with ESP trailer stabilization (fully electrically foldable and retractable)
- Black fabric headliner
- Center console wood ash grey open pore
- Package: Night for AVANTGARDE exterior (for hybrid vehicles) (45.7 cm (18") 5-spoke light-alloy wheels, painted high-gloss black and polished with front axle 245/45 R 18 on 8 J x 18 ET 43, rear axle 275/40 R 18 on 9 J x 18 ET 53 - front bumper with trim element in high-gloss black - beltline trim strip, window surround and trim strip in the rear bumper in high-gloss black - exterior mirror housings in high-gloss black - roof rails in black - heat-insulating dark tinted glass from the B-pillar)
- Radio accessories: Burmester surround sound system (13 high-performance speakers - 9-channel DSP amplifier with a total output of 590 W - Frontbass technology with woofers integrated into the body shell for powerful bass reproduction - Sound optimization for the front and rear seats - Noise cancellation (VNC) - Sound preset: Surround function to generate a virtual surround sound - Multi-channel format support for true surround sound)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |
| readiness to drive | The vehicle was roadworthy at the time of inspection. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Door - front left side | Door - dent(s) - Smooth repair work |
| 2 | Roof | Roof rail - left side - Scratch(es) - Smart repair |
| 3 | Rear bumper | Rear bumper - Scratch(es) - Smart repair |
| 4 | Side panel - rear right side | Side panel - Scratch(es) - Smart repair |
| 5 | 2nd wheel set | 1 alloy rim - Scratch(es) - Loss in value |
| 6 | 2nd wheel set | 1 alloy rim - Scratch(es) - Loss in value |
| 7 | Bonnet | Bonnet - Dent / paintcoat damage - Loss in value |
| 8 | Seat - front | Seat cover - left side (Lehnenabdeckung) - Holes - Replace |
| 9 | Door - rear left side | Door - Scratch(es) - Paint |
| 10 | Door - front right side | Door - Scratch(es) - Paint |
| 11 | Front bumper | Front bumper - Dent / paintcoat damage - Repair and paint |
| 12 | Vehicle glazing | Windscreen - Stone chips - Replace |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Boot lid / rear door | Boot lid - Scratch(es) - No deduction |
| 2 | Side panel - rear left side | Side panel - Scratch(es) - No deduction |
| 3 | Body | A-pillar - left side - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN




**Figure 12:** Mounted tyres





**Figure 13:** Documents



**Figure 14:** Additional tyres



**Figure 15:** Additional tyres




**Figure 16:** Navigation



**Figure 17:** Misc.



**Figure 18:** Misc.




**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.





**Figure 22:** Misc.




**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.




**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.



**Figure 29:** Misc.




**Figure 30:** Misc.



**Figure 31:** Misc.



**Damage 1:** Door - front left side: Door - dent(s) - Smooth repair work




**Damage 1:** Door - front left side: Door - dent(s) - Smooth repair work



**Damage 2:** Roof: Roof rail - left side - Scratch(es) - Smart repair



**Damage 2:** Roof: Roof rail - left side - Scratch(es) - Smart repair



**Damage 3:** Rear bumper: Rear bumper - Scratch(es) - Smart repair




**Damage 3:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 3:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 3:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Smart repair



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Smart repair



**Damage 5:** 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




**Damage 5:** 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



**Damage 6:** 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value





**Damage 6:** 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



**Damage 6:** 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



**Damage 7:** Bonnet: Bonnet - Dent / paintcoat damage - Loss in value



**Damage 7:** Bonnet: Bonnet - Dent / paintcoat damage - Loss in value



**Damage 7:** Bonnet: Bonnet - Dent / paintcoat damage - Loss in value



**Damage 7:** Bonnet: Bonnet - Dent / paintcoat damage - Loss in value



**Damage 8:** Seat - front: Seat cover - left side (Lehnenabdeckung) - Holes - Replace



**Damage 8:** Seat - front: Seat cover - left side (Lehnenabdeckung) - Holes - Replace



**Damage 9:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 9:** Door - rear left side: Door - Scratch(es) - Paint




**Damage 10:** Door - front right side: Door - Scratch(es) - Paint



**Damage 10:** Door - front right side: Door - Scratch(es) - Paint




**Damage 10:** Door - front right side: Door - Scratch(es) - Paint




**Damage 11:** Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint




**Damage 11:** Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



**Damage 11:** Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint




**Damage 12:** Vehicle glazing: Windscreen - Stone chips - Replace



**Damage 12:** Vehicle glazing: Windscreen - Stone chips - Replace



**Damage 12:** Vehicle glazing: Windscreen - Stone chips - Replace



**Damage 12:** Vehicle glazing: Windscreen - Stone chips - Replace



**Wear and tear 2:** Side panel - rear left side: Side panel - Scratch(es) - No deduction