MACADAM

TESLA MODEL Y


Vehicle information

Make:	**TESLA**	License:	**R980HR**
Gearbox:	**Automatic**	Body color:	
Model:	**MODEL Y**	VIN:	**LRWYGCEK3NC462937**
Fuel type:	**Electric**	Power:	
Version:	**.**	First registration	**24/09/2022**
Mileage:	**97244 km**	N° of doors:	

Damage summary

Front	2
Left	3
Rear	1
Right	3

Commercial pictures


Bediening
Dynamiek
Opladen
Self-Driving
Vergrendeling
Verlichting
Stoelen
Scherm
Planning
Veiligheid
Service
Software
MODEL Y
LONG RANGE
DUAL MOTOR
17.244 km
VIN LRWYGCEK3NC462937
AI-computer: Full Self-Driving computer 3
Traffic-Aware Cruise Control en Automatisch sturen


MODEL 3
MODEL Y


LRWYGCEK3NC462937


245/40 R20 XL







SportContact 6










Batterijcertificaat
Datum van diagnose: 26/10/2026
93,8%
Status van de gezondheid (SOH)*
Tesla Model Y Long Range Dual Motor
VIN : LRWYGCEK3NC462937
Kilometerstand : 97.244 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA





Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Panoramic roof	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**

Damages

Alloy rim FL

Scratch(es)

Repair and paint (complete)

Left









Alloy rim FR

Scratch(es)

Repair and paint (complete)

Right







Alloy rim RL

Scratch(es)

Repair and paint (complete)

Left






Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right






Bonnet
Stone chip(s)
Repair and paint (complete)
Front





Door RL
Scratch(es)
Repair and paint (partial)
Left






Tailgate / Boot
Chemical polution
Repair and paint (complete)
Rear






Windscreen
Stone chip(s)
Windscreen repair
Front





Wing RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right





Tyres

Front Left
Summer
255/40/20/101/Y
Continental
5.7 mm
Front Right
Summer
255/40/20/101/Y
Continental
5.8 mm
Rear Left
Summer
255/40/20/101/Y
Continental
6.2 mm
Rear Right
Summer
255/40/20/101/Y
Continental
6.4 mm

Checks

Certificate of Conformity	**No**	CO2 Emission	**0**
Digital maintenance	**Yes**	GPS storage	**Yes**
GPS storage	**HD**	Luggage cover	**Yes**
Number head rests	**1**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Reset to factory settings	**No, not possible**
Service book	**N/A**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.