TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48443415
Order No. / Reference: 27124774
Inspection date: 2 Nov 2026

Manufacturer: Mercedes-Benz	Model: EQA 250+
VIN: W1N9N0CB0SJ133319	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz EQA 250+	
Vehicle Identification number	W1N9N0CB0SJ133319
Mileage (Read)	31,774 km
First registration	7 Aug 2024
Number of holders	1
Next periodical technical inspection	08/2027
(Report not on hand)	
Fuel type	Electric
Power	95 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	KOSMOSSCHWARZ - METALLICLACK
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	313 km
Last service on / at	08/2026 at 30,715 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD762261
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / BEE 00018		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,475 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 104T	Summer tyres on Light alloy	Michelin	3mm / 3mm
2)	235/55 R18 104T	Summer tyres on Light alloy	Michelin	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R18 102T	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	215/60 R18 102T	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Airbag: Driver and passenger side
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Acoustic environmental protection
- Rear armrest
- Double cup holder
- DYNAMIC SELECT
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis with lowered suspension
- Pedestrian protection with active hood
- Luggage net on driver and passenger seatbacks
- Transmission: Direct drive
- Rear window wiper/washer system
- Climate: THERMATIC automatic climate control
- Adjustable headrests (5)
- Paint finish: Solid
- Chrome-look loading sill protector
- Charging system: Direct current charging system (DC charging)
- LED High Performance Headlights
- Steering wheel: Multifunction sports steering wheel in leather
- Navigation accessories: Extended MBUX functions
- Navigation accessories: Pre-installation for remote and navigation services
- Package: Cargo space
- Package: Progressive
- Package: Seating comfort
- Radio accessories: CENTRAL MEDIA DISPLAY
- Radio accessories: GPS antenna
- Tire pressure monitoring system
- Wheels: 45.7 cm (18") alloy wheels, 4-spoke design
- Windscreen wipers with rain sensor
- Seats: i-Size child seat attachment in the rear
- Seats: Rear seat backrests foldable
- Sun visor with illuminated makeup mirror
- Power outlet: 12V socket in the luggage compartment
- TIREFIT
- High-visibility vest for drivers
- heat pump
- Decorative elements Star Pattern
- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Ambient lighting
- Automatic passenger airbag deactivation
- Third brake light in LED technology
- EASY-PACK tailgate
- Elimination of roof rails
- Electric windows (4-way)
- Velour floor mats
- Speed Limit Assistant
- Rear window heated
- Black fabric headliner
- Communication module (LTE) for the use of Mercedes me connect services
- Charging cable for wallboxes and public charging stations, 5m, smooth
- Charging system: Alternating current charging system (AC charging) up to 11 kW
- LED light strip (function: tail light and rear fog light) between the LED tail lights
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation: MBUX Navigation Premium
- Package: Light and Visibility Package
- Package: Progressive Line
- Upholstery: ARTICO leatherette/fabric
- Radio accessories: Digital radio
- Radio accessories: Additional USB ports
- Remote and Charging Services Premium
- Rear view camera
- Seats: 4-way lumbar support for driver
- Seats: Comfort seats
- Heated seats for driver and front passenger
- 12V power outlet in center console
- Cruise control
- Pre-installation for digital key handover
- Immobiliser
- Central locking with remote control

Extra equipment

- Towbar with ESP trailer stabilization (Foldable towbar - operating button with LED light in the boot or tailgate - ESP trailer stabilization)
- Paint finish: Metallic
- Package: Driving Assistance Package (Active Distance Assist DISTRONIC - Active Speed Limit Assist - Extended Automatic Restart on Highways - Route-Based Speed Adaptation - Active Steering Assist - Active Emergency Stop Assist with SOS Function - Active Brake Assist - Turning Function with Vehicle, Pedestrian and Cyclist Detection - Evasive Steering Assist - Active Lane Keeping Assist - Blind Spot Assist - Exit Warning Function - Traffic Sign Assist - PRE-SAFE System)
- Package: Progressive Advanced (Charging cable for household socket, 5m, smooth; Advanced package - Fully digital instrument display with 10.25" screen diagonal - Parking package with reversing camera - Blind spot assist - Individualization package - Mirror package - Illuminated door sill trims with model-specific lettering and interchangeable cover)
- Seats: Front right seat electrically adjustable with memory function (memory programming with seat adjustment options such as height and longitudinal direction, seat cushion tilt and backrest tilt - Motion Seating with three programs and two speeds)
- Phone accessories: Smartphone integration (Smartphone integration connects your mobile phone wirelessly to the multimedia system via Apple CarPlay and Android Auto. This gives you convenient access to your smartphone's most important applications. You can also use third-party apps such as Spotify quickly and easily.)
- Removal of emblem on the front fenders
- Climate control: THERMOTRONIC automatic climate control (two zones with individually adjustable temperature for driver and front passenger; automatic control of temperature, air volume and air distribution (Auto button); sensors maintain the desired climate; continuous monitoring of the intake air for harmful gases with automatic recirculation; a fine dust activated carbon filter improves the air quality in the vehicle, filtering dust, soot and pollen from the air and additionally reducing pollutants and odors; dew point sensor prevents)
- Package: Parking package with reversing camera (12 ultrasonic sensors: 6 each in the front and rear bumpers - reversing camera: integrated into the trunk lid, display in the central display, trailer mode - Active Parking Assist PARKTRONIC: detects parking spaces, assisted parking, visual and acoustic warning of detected obstacles, display of camera and ultrasonic data in the central display, button for Active Parking Assist with PARKTRONIC - cross traffic warning - maneuvering braking - drive-away assist)
- Seats: Electrically adjustable driver's seat with memory function (the memory programming includes all seat adjustment options such as seat height and fore/aft position, seat cushion tilt, and backrest tilt – exterior mirrors and the optional head-up display are also integrated – dynamic seating while driving. Small movements of the seat cushion and backrest in three programs and two speeds)
- Traffic Sign Assist (Evaluates the currently driven route with regard to traffic signs using a camera behind the windshield and navigation data - Early detection of speed limits and display of prohibitions as well as their cancellation in the driver's or central display as well as in the optionally available head-up display - Can recognize no-entry signs, a visual and acoustic warning is given - Pedestrian warning function in the area of zebra crossings)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
2	Door - front left side	Door edge - Scratch(es) - Smart repair
3	Rear bumper	Rear bumper - Scratch(es) - Smart repair

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair