TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48515265
Order No. / Reference: 27236500
Inspection date: 3 Nov 2026

Manufacturer: Ford	Model: Grand Tourneo Connect 1.5 EcoBlue Start/Stop Trend
VIN: WF0UXXWPGUMP17247	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Grand Tourneo Connect 1.5 EcoBlue Start/Stop Trend	
Vehicle Identification number	WF0UXXWPGUMP17247
Mileage (Read)	87,400 km
First registration	25 Oct 2021
Number of holders	1
Next periodical technical inspection	08/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	77 %
Last service on / at	08/2024 at 54,782 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD575053
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BLK 00410		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,380 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	205/60 R16 96V	Summer tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96H	Summer tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Tires: 6.5 J x 16 alloy wheels (4) with 205/60 R 16 tires and wheel lock
- Front overhead storage compartment
- Third brake light
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Ford EcoSelect: a selectable driving mode
- FordPass Connect including live traffic information and Wi-Fi hotspot
- Glove compartment with lid
- Interior lighting for passenger/cargo compartment
- Interior lighting front and rear with delay function
- Intelligent security system
- Front air conditioning, manual, with semi-electronic recirculation function
- Radiator grille with 5 crossbars, black plastic
- Steering wheel: Multifunction leather steering wheel, 4 spokes
- Fog light
- Pollen and dust filter
- Pre-Collision Assist
- Tire pressure monitoring system
- Sliding door, right and left
- Electromechanical power steering
- Bench seat (in the 2nd row, 3 seats). 60:40 split, foldable.
- Front spoiler lip
- Start-stop system
- 12-volt socket in storage compartment on dashboard (driver's side)
- Rear bumper, black plastic
- Daytime running light
- Child safety lock on sliding doors
- Warning system for unfastened driver and front passenger seat belts
- Electrically adjustable and heated exterior mirrors
- Black exterior mirror caps (plastic)
- Hill start assist
- On-board computer
- Diesel particulate filter (DPF)
- Electronic Safety and Stability Program (ESP)
- Rear power windows, right and left, electric
- Front electric windows with one-touch down function for the driver's side
- Cruise control
- Transmission: 6-speed manual transmission
- Rear swing door including heated rear window and wiper/washer system
- Intelligent battery management system
- Isofix mount
- Rear headrests (3)
- Headrests 2 front, height adjustable
- Paint finish: Solid
- Adjustable steering column
- Front center console, open, with storage area
- Emergency brake light
- Pollen filter and dust filter
- Radio equipment: Ford Audio System 2
- Windscreen wipers with rain sensor
- Black plastic side protection strips
- Safety Brake Assist (EBA)
- Sun visor with mirror on driver and passenger side (for drivers with ticket holder)
- Concealed storage compartment on dashboard
- Power outlet: 12-volt connection on the center console, front and rear
- Front bumper painted in body color
- Carpet floor mats for the front (2-piece set)
- Traffic sign recognition system
- Immobilizer EPATS
- Central locking with remote control (door lock only on driver's door)

Extra equipment

- Fixed towbar (including ESP trailer stabilization and continuous power supply)
- Navigation: Ford Audio System 9 navigation systems, including Ford SYNC 3 with AppLink, touchscreen, and reversing camera (Ford SYNC 3 communication and entertainment system with voice control, 6" color touchscreen, high resolution, 15.2 cm screen diagonal, radio (FM/AM), 2 USB ports, 6 speakers, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, premium center console, reversing camera including rear parking assist system, phase-differentiated antenna, DAB/DAB+, voice control for audio and telephone, support for Android Auto and Apple CarPlay, dynamic navigation TMCpro, live traffic, 3D display)
- Tires: Spare wheel, steel wheel (6.5 J x 16)
- Heated windshield
- Package: Seat Package 6 (fabric, Capitol/City in Ebony (black) - driver's seat, 3-way manually adjustable (forward/backward, height, backrest), with lumbar support - single passenger seat, 2-way manually adjustable (forward/backward, backrest) and foldable - map pocket for driver's seat - seat heating for driver and single passenger seats)
- Safety partition net for separating passenger and luggage compartments (including attachment points)
- Heat-insulating glazing, tinted (from the B-pillar)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - rear right side (Nabendeckel) - Missing - Replace
2	Side panel - rear left side	Sill - Scratch(es) - Smart repair
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Mudguard - left side	Mudguard - left side - Stone chips - Smart repair
5	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
6	Body	B-pillar - left side - Scratch(es) - Smart repair
7	Misc.	Main inspection - Due - Perform
8	Sill - right side	Trim - Scratch(es) - Replace
9	Sill - left side	Trim - Scratch(es) - Replace
10	Front bumper	Front bumper (+ Steinschläge) - Scratch(es) - Paint
11	Bonnet	Bonnet (Rostansatz) - Scratch(es) - Repair and paint
12	Sliding door, right	Sliding door with glass panel (+ Kratzer) - Corrosion - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Underbody panelling - Scratched - No deduction
2	Rear bumper	Rear bumper (unpainted) (+ Delle) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent
2	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
3	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	366 µm	Door - rear left side	288 µm
Door - front left side	407 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Wheel / tyres: Wheel cover - rear right side (Nabendeckel) - Missing - Replace



Damage 2: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



Damage 4: Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 6: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 7: Misc.: Main inspection - Due - Perform



Damage 8: Sill - right side: Trim - Scratch(es) - Replace



Damage 8: Sill - right side: Trim - Scratch(es) - Replace



Damage 8: Sill - right side: Trim - Scratch(es) - Replace




Damage 9: Sill - left side: Trim - Scratch(es) - Replace



Damage 9: Sill - left side: Trim - Scratch(es) - Replace



Damage 9: Sill - left side: Trim - Scratch(es) - Replace



Damage 10: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 10: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 10: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 10: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint




Damage 10: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 11: Bonnet: Bonnet (Rostansatz) - Scratch(es) - Repair and paint



Damage 11: Bonnet: Bonnet (Rostansatz) - Scratch(es) - Repair and paint



Damage 11: Bonnet: Bonnet (Rostansatz) - Scratch(es) - Repair and paint



Damage 11: Bonnet: Bonnet (Rostansatz) - Scratch(es) - Repair and paint



Damage 12: Sliding door, right: Sliding door with glass panel (+ Kratzer) - Corrosion - Repair and paint



Damage 12: Sliding door, right: Sliding door with glass panel (+ Kratzer) - Corrosion - Repair and paint



Damage 12: Sliding door, right: Sliding door with glass panel (+ Kratzer) - Corrosion - Repair and paint



Wear and tear 1: Body: Underbody panelling - Scratched - No deduction



Wear and tear 1: Body: Underbody panelling - Scratched - No deduction



Wear and tear 2: Rear bumper: Rear bumper (unpainted) (+ Delle) - Scratch(es) - No deduction



Wear and tear 2: Rear bumper: Rear bumper (unpainted) (+ Delle) - Scratch(es) - No deduction



Wear and tear 2: Rear bumper: Rear bumper (unpainted) (+ Delle) - Scratch(es) - No deduction



Repainting 1: Boot lid / rear door



Repainting 1: Boot lid / rear door



Repainting 2: Door - rear left side



Repainting 2: Door - rear left side



Repainting 3: Door - front left side



Repainting 3: Door - front left side