TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 47736020
Order No. / Reference: 27026545
Inspection date: 23 Sept 2026

Manufacturer: Audi	Model: S6 Avant TDI quattro tiptronic
VIN: WAUZZZF20RN015685	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi S6 Avant TDI quattro tiptronic	
Vehicle Identification number	WAUZZZF20RN015685
Mileage (Read)	184,701 km
First registration	3 Nov 2023
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	2,967 ccm / 6
Power	253 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Gletscherweiss Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	4,800 km
Last service on / at	03/2026 at 167,398 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY305229
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BWV 00231		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,655 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/35 R21 98Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	255/35 R21 98Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R19 102V	Winter tyres on Light alloy	Pirelli	6mm / 5mm
2)	245/45 R19 102V	Winter tyres on Light alloy	Pirelli	4mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect remote & control
- Audi virtual cockpit plus
- Exterior mirror housings in aluminum
- Control buttons, matte black
- third brake light
- Aluminum roof rails
- Anti-theft alarm system
- Tachometer
- Parking aid plus with surround view
- Electronic Stability Control (ESC)
- Window trim strips, aluminum look
- Luggage compartment lid, electrically opening and closing
- Transmission: 8-speed automatic transmission tiptronic
- Interior mirror dimming
- 4-zone automatic climate control
- Comfort center armrest in front
- Fuel tank (73 liters)
- Steering wheel: Leather steering wheel, 3-spoke, with multifunction and paddle shifters
- Non-smoking version
- Pedals and footrest in stainless steel
- Wheel: Tire pressure monitoring system
- Radio: MMI Radio plus with MMI touch response
- Rail system with fixing set
- Seats: 4-way lumbar support
- Seats: Split-folding rear seat backrest Avant
- Seats: Electrically adjustable front seats including memory function for the driver's seat
- Start-stop system
- First aid kit including warning triangle and high-visibility vests
- Camera-based traffic sign recognition
- Electronic immobilizer
- Central locking
- Airbag for driver and front passenger
- All-wheel drive "quattro" with self-locking center differential
- Audi connect navigation & infotainment
- Audi drive select
- Audi pre sense front
- Electrically adjustable, heated and folding exterior mirrors with memory function
- Vehicle tool kit
- Fabric headliner
- Decorative inlays: Dark brushed matt aluminum
- Diesel particulate filter (DPF) with nitrogen oxide catalyst and AdBlue tank
- Door sills with aluminum inlay, front and rear, illuminated
- Chassis: S sport suspension with damper control
- key fob
- Cruise control system with speed limiter
- Interior lighting
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Headrests (4)
- LED headlights
- Manual steering wheel adjustment
- MMI navigation with MMI touch response
- Package: Filing package
- Progressive steering
- Wheel: Tire repair kit
- Radio accessories: Audi sound system
- Seat covers in Dinamica microfiber frequency/leather combination with S-embossing
- Seats: Front sports seats
- Sun visor on driver and passenger side
- Lane Departure Warning
- Phone: Application Store and Smartphone Interface
- Glazing: Windscreen in heat-insulating glazing
- Glazing: Rear window, rear door and side windows in clear glass
- Thermal insulation glazing on the sides and rear

Extra equipment

- Adaptive windscreen wipers with integrated washer nozzles (adaptive windscreen wiping system for best possible visibility in all weather conditions, even during the wiping process - cleaning fluid is sprayed directly in front of the wiper blades and wiped away almost without delay - heated)
- Audi connect key (The smartphone takes over the functions of the vehicle key: opening and closing the vehicle and starting the engine. Up to 5 digital vehicle keys can be given to other people via the myAudi app on the smartphone. In addition, temporary access and/or driving authorization can be granted via the Audi connect key card, thus it is not necessary to give the vehicle key or the smartphone to third parties (e.g., valet parking services).)
- Exterior mirror housings in black
- Deletion of model designation and performance/technology lettering
- Chassis: adaptive air suspension (The adaptive air suspension is an electronically controlled air suspension with continuously adaptive damping at all four wheels. Load-dependent and automatic control of vehicle level and damping simultaneously achieves a very high level of ride comfort and increased driving dynamics. A lower ride height setting reduces air resistance. Various modes can be selected via Audi drive select: auto, comfort, dynamic, lift)
- Automatically dimming, frameless interior mirror (can increase safety, as reduced glare improves the perception of following traffic at night - less glare at night, among other factors, can help to recognize other vehicles in the interior mirror more quickly and better - reduced glare can help to prevent eye fatigue)
- Instrument panel and door trim, two-piece, single/multi-color
- Comfort key with sensor-controlled luggage compartment unlocking including anti-theft alarm system (The vehicle can be opened by operating the door handle without actively using the key. To lock the vehicle from the outside, simply touch one of the sensor buttons on the door handles. The drive authorization is also activated without actively using the comfort key. The driver must be inside the vehicle and have the comfort key with them. The engine is started and stopped using the engine start/stop button in the center console.)
- Steering wheel: Leather steering wheel, 3-spoke with multifunction, paddle shifters and steering wheel heating (paddle shifters allow manual changing of the driving modes. The steering wheel rim is also heated.)
- Assistance Package Tour (Adaptive Driving Assistant, Adaptive Speed Assistant provides support within system limits for acceleration, braking, and maintaining speed and distance with Lane Keeping Assist - Efficiency Assistant - Turning Assistant, monitors the oncoming lane using data from the radar sensor and front camera as soon as the turn signal is activated - Evasive Steering Assist, helps the driver steer the vehicle around an obstacle in a critical situation - Emergency Assist)
- Wheel: Audi Sport 5-double-arm design alloy wheels (8.5 J x 21 with 255/35 R 21 tires)
- AdBlue tank with increased filling volume (AdBlue tank with 22 liter filling volume - for diesel vehicles with SCR technology, to reduce nitrogen oxides in the exhaust gas)
- Swiveling towbar with electric release (with swiveling ball head, trailer stabilization via electronic stability control (ESC), release via button in the luggage compartment, the integrated swiveling system socket allows continuous operation of electrical devices in the trailer or caravan while driving)
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides, with memory function (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb.)
- High beam assist (within the system's limits, it automatically detects oncoming headlights, taillights of other road users, and built-up areas. Depending on the traffic situation, the high beam is automatically switched on or off.)
- Garage door opener (The control and transmitter unit, which is permanently integrated into the operating concept, is freely programmable. Touchscreen fields for operation can be individually named. A total of up to eight different systems can be saved. The radio technology used ensures reliability and security. External access to the control system via the internet is not possible. A corresponding notification appears when approaching the saved location.)
- Interior elements in synthetic leather (top and bottom) (instrument panel and door sills in black synthetic leather with contrast stitching in steel grey. Armrest in the doors and center console trim optionally in: - Black with contrast stitching in rock grey - Okapi brown with contrast stitching in steel grey - Sarder brown with contrast stitching in steel grey - Pearl beige with contrast stitching in agate grey - Rotor grey with contrast stitching in anthracite. Audi S6: - Black with contrast stitching in rock grey - Rotor grey with contrast stitching in anthracite - Arras red with contrast stitching in agate grey)
- Paint finish: Metallic
- Electric steering wheel adjustment (adjustable in height and distance, with automatic entry and exit)
- Ambient lighting package (in addition to the standard interior lighting: - Ambient fabric lighting in the front/rear doors - Approach lighting from the outer door handles, front/rear - Ambient lighting of the instrument panel - Entry lights on the underside of the rear doors)
- Black Optics Package Plus (Includes: - black accents in the area of the Audi Singleframe, the trim strips on the side windows, the front and rear bumpers, between the taillights and in the area of the tailpipe optics - Audi rings front and rear and model designation on the rear in black)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)

- Reversing camera (The reversing camera displays the area behind the vehicle on the upper display. Dynamic display elements such as a steering angle-dependent lane calculation assist with parking or maneuvering.)
- Front seat heating (heats seat and backrest center panels; with leather upholstery, sport seats and sport seats plus also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via the climate control unit)
- Telephone: Audi phone box (The smartphone can be paired with the vehicle via Bluetooth to either make calls or play music in the vehicle; emails and SMS messages can also be displayed in the MMI via Bluetooth - the telephone holder in the front center armrest area is connected to the vehicle's antenna, which improves reception and call quality - inductive charging function (Qi standard) via USB port or wireless charging. Charging status is displayed in the MMI)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Wheel: Winter alloy wheels, 10-spoke dynamic design (8 J x 19 with tires 245/45 R19)
- Headlight cleaning system
- Rail system with fixing set (telescopic pole and strap for individual partitioning of the luggage compartment and secure fixing of objects, stowable under the loading floor)
- Sun visor on driver and passenger side, extendable
- Lane change warning including Audi pre sense rear, exit warning and rear cross-traffic assist (Lane change warning helps the driver monitor the blind spot and traffic behind the vehicle. Exit warning warns of a possible collision when opening a door while the vehicle is stationary. Rear cross-traffic assist (Audi pre sense rear) uses data from the radar sensors.
- Glazing: Acoustic glazing for the side windows (improved external noise insulation through double glazing)
- Glazing: Windscreen in climate comfort/acoustic glazing, wirelessly heated (heated windscreen made of climate comfort/acoustic glass, facilitates rapid defrosting and ensures fog-free operation through surface heating without obstructing heating wires; with heated wiper blade rest; with viewing window for telepass devices)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair
2	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
3	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
4	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	2nd wheel set	1 tyre (4,5 mm restprofil) - No deduction
2	Interior	Interior - Scratch(es) - No deduction
3	Sill - left side	Sill - Scratch(es) - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 11 Mar 2025	3.306,55 €

Repainting

No.	Repainting
1	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - front right side	162 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig und eingeschränkt möglich.
- Mehrkosten möglich .



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN




Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.




Figure 41: Misc.




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Repainting 1: Door - front right side



Repainting 1: Door - front right side