APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	BMW
Model / version:	X3
Vin:	WBAUZ15090N100698
Plate:	2ASL795
Mileage:	160091
First registration:	30/06/2021
Color:	BLACK SAPPHI

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES



























































VIN INFORMATION

Transmission automatique	8 rapports	Equipement Advantage
Matière : alliage	Lettre repère (J)	Diamètre avant 20
Diamètre arrière 20	Largeur avant 8,0	Largeur arrière 9,5
Diamètre avant 20	Diamètre arrière 20	Hauteur avant 45
Hauteur arrière 40	Indice de vitesse avant W	Indice de vitesse arrière W
Largeur avant 245	Largeur arrière 275	Pneus roulage à plat
Climatisation automatique 2 zones	Climatisation réfrigérant 1234YF	Diesel
1995 cm3	2.00 litres	110 kw
150 ch	Métallisée vernissée	Rétroviseur gauche jour/nuit automatique
Rétroviseur droit jour/nuit automatique	Rétroviseurs rabattables électriques	Rétroviseur intérieur jour/nuit automatique
Siège avant gauche chauffant	Sièges avant chauffants	Garnitures cuir

Aide au stationnement avant	Aide au stationnement arrière	Assistance au parking
Caméra avant	Caméra arrière de recul	Alarme
Appel de secours	Attelage avec boule rétractable électrique	Fixotoit aluminium satiné
Protection piéton	Freinage d'urgence assistée autonome (urbain)	Avertisseur de collision avant
Contrôle pression des pneus	depuis 04.21	réservoir carburant de grande capacité
pack de rangement	système de récupération	mesures CO2 étendues
tuner DAB	filet de séparation coffre	BMW Live Cockpit Pro
boulons antivol de roue	spécifique Europe	

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		245/45R20 103W	Summer		?
Front right	5 mm		245/45R20 103W	Summer		?
Rear left	5 mm		245/45R20 103W	Summer		?
Rear right	5 mm		245/45R20 103W	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key - Boordcomputer resetten	Not original part
2	Bumper F	Grooved
4	Door RL	Dent(s) and scratch(es)
5	Roof	Chemical polution
6	Bumper R	Scratch(es)
7	Inner door sill RR	Scratch(es)

Total: 6

ACCEPTABLE / NOT TO BE INVOICED


#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Contact key - Boordcomputer resetten - Not original part





2 - Bumper F - Grooved





4 - Door RL - Dent(s) and scratch(es)







5 - Roof - Chemical polution





6 - Bumper R - Scratch(es)






7 - Inner door sill RR - Scratch(es)




3 - Bodywork - Dent(s) and scratch(es) - Renta®








SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

16/10/2026 12:13