APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	VOLVO
Model / version:	XC40
Vin:	YV1XZBWVFN2768585
Plate:	2BUS842
Mileage:	211486
SOH:	
First registration:	30/03/2022
Color:	Pebble Grey

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





























































VIN INFORMATION

Radio	Système navigation	12 haut-parleurs
Téléphone	Transmission automatique	7 rapports

Pommeau de levier de vitesses cuir
Projecteurs à LED
Diamètre avant 19
Largeur arrière 8,5
1477 cm3
156 ch
Rétroviseur gauche à réglage mémorisé
Rétroviseur droit jour/nuit automatique

Aide au stationnement avant
Ouverture du coffre électriquement
Vitres portes arrière teintées foncées
Toit ouvrant électrique
Airbag de genoux
Keyless Entry
airbag passager désactivable
poignées de portes éclairées

1477 CC 95/60 KW
7,5 J x 19 Alu 5 branches Diamond cut noir
CAB CHARG SCHUKO 10A
système "Plug-in"

Traction avant
Matière : alliage
Diamètre arrière 19
Climatisation automatique 2 zones
1.50 litre
Mica vernissée
Rétroviseur droit à réglage mémorisé
Rétroviseurs carbone

Aide au stationnement arrière
Pare-brise chauffant
Vitres de custode teintées foncées
Toit ouvrant vitré panoramique
depuis n°châssis 763 999
sièges baquet av
ceintures de sécurité de type B
grille de calandre "Type R-Design"

T125/70 R 19 .. V
avant 235/50 R 19 .. V arrière 255/45 R 19 .. V
sortie d'échappement double cachée

Projecteurs directionnels
Lettre repère (J)
Largeur arrière 7,5
Essence
115 kw
Freins avant à disques
Rétroviseur gauche jour/nuit automatique
Rétroviseur intérieur jour/nuit automatique
Caméra arrière de recul
Lunette arrière teintée foncée
détecteur de pluie essuie-vitre
Fixotoit
rétroviseurs électrique "8D06"
grille de calandre active Shutter-System
pack éclairage intérieur
attache-remorque semi-électrique rabattable avec prise à 13 broches
235/50 R 19 .. H
galerie de pavillon noir
Thaïlande

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		235/50R19 103Y	Summer		?
Front right	5 mm		235/50R19 103Y	Summer		?
Rear left	5 mm		235/50R19 103Y	Summer		?
Rear right	5 mm		235/50R19 103Y	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Seat cover FR	Stain
3	Windscreen	Crack
4	Door FL	Grooved
5	Inner door sill RL	Dent(s) and scratch(es)
6	Wing RL	Dent(s) and scratch(es)
7	Tailgate / Boot	Dent(s) and scratch(es)
8	Inner door sill RR	Dent(s) and scratch(es)
9	Alloy rim FR polished	Grooved
10	Door seal FR	Dent(s) and scratch(es)

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Seat cover FR - Stain




3 - Windscreen - Crack





4 - Door FL - Grooved




5 - Inner door sill RL - Dent(s) and scratch(es)






6 - Wing RL - Dent(s) and scratch(es)










7 - Tailgate / Boot - Dent(s) and scratch(es)





8 - Inner door sill RR - Dent(s) and scratch(es)


9 - Alloy rim FR polished - Grooved




10 - Door seal FR - Dent(s) and scratch(es)




2 - Bodywork - Dent(s) and scratch(es) - Renta®








SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

21/10/2026 08:44

