Audi

BEV 95KWH 55 QUATTRO

VIN: WAUZZZGE4NB006508



Description

Registration number 2BBA391	**First registration date** 15/09/2021	**Odometer** 73496 km
Color Mythos Black metallic	**Model year** 2021	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Gearbox type Automatic	**Engine type** Electric	**Number of gears** 1
Max power 300 KW		

Vehicle Equipments

Rear-view camera	Automatic headlights	Cruise control
Electrically adjustable seats	Hydraulic tail board	Alloy wheel rims
Rain-sensitive wipers	SATNAV	Front sensors
Rear sensors	Heated seats	

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 27/10/2026	**Inspection approval date** 28/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		


Defects & corrections

#	Element	Defect	Correction

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

001	Roof / - Sunroof : No	Paint etching	Polishing





002	Bonnet / -	Paint etching	Polishing





003	Door / Front Left	Dent	Acceptable



004	Door handles / Front Left	Scratched	Acceptable



005	Wing / Back Left [1]	Paint etching	Polishing




006	Bumper / Back Painted : Yes	Scratched	Acceptable



007	Door sill / Back Right	Dent	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



008	Exterior door mirror shell / Right	Scratched	Painting




009	Door / Back Right	Dent	Acceptable



[1] + deuk aanvaardbaar

Loose Items

- [x] Quick charging cable (Type 2, Mode 3)
- [x] Triangle
- [x] Rear parcel shelf
- [x] Registration certificate
- [x] Safety vest
- [x] Tyre repair kit complete
- [x] First aid kit
- [x] Refill tyre repair kit
- [x] Spare Key
- [x] Compressor tyre repair kit
- [x] Registration certificate owner
- [x] Conformity certificate
- [x] Slow charging cable (Type 2, Mode 2)

Main set of tyres

Front Left	CONTINENTAL	255/55/19 Summer	4 mm
Front Right	CONTINENTAL	255/55/19 Summer	4 mm
Back Left	BRIDGESTONE	255/55/19 Summer	4 mm
Back Right	BRIDGESTONE	255/55/19 Summer	4 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer




Navigation



Spare Tyre


Cable


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Cable




Vin



Other



Other



Other



Other




Other



Roof / - / Paint etching



Roof / - / Paint etching



Roof / - / Paint etching



Bonnet / - / Paint etching



Bonnet / - / Paint etching



Bonnet / - / Paint etching



Door / Front Left / Dent



Door handles / Front Left / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Wing / Back Left / Paint etching



Wing / Back Left / Paint etching



Bumper / Back / Scratched



Door sill / Back Right / Dent



Exterior door mirror shell / Right / Scratched



Exterior door mirror shell / Right / Scratched



Door / Back Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Appendices : SOH Report



All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.