ARVAL
BNP PARIBAS GROUP

2CLX250

INSPECTION REPORT

End of contract

GENERAL INFO

File	315496
License plate	2CLX250
Vehicle identification number	YV1ZWH1V7P1525781
Dossier	2021 301 105
Make	Volvo V60 T6 PHEV Inscription
Mileage	135983
First registration	09/09/2022
client availability date	31/08/2026
inspectionDate	14/08/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






B
2-CLX-250
BELCAR

DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
78	Side View Mirror Left / Direction Indicator / Replace	Y
80	Door Front Left // Smart Repair Small	Y
114	Wing Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	Y
136	Bumper Rear // Polish	Y
150	Rear Bonnet // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
193	Door Rear Right // Painting	Y
216	Door Front Right // Polish	Y
225	Side View Mirror Right // Polish	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N


Damage Pictures

Rear Bonnet / Rear Window / Replace-scratch




Bumper Front // Painting-scratch

Side View Mirror Left / Direction Indicator / Replace-scratch




Door Front Left // Smart Repair Small-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Light / Rear left / Replace-scratch




Bumper Rear // Polish-scratch





Wheel Two Tone Rear Right // Repair-scratch




Door Rear Right // Painting-scratch




Side View Mirror Right // Polish-scratch

Door Front Right // Polish-scratch






Wheel Two Tone Front Right // Repair-scratch





Rear Bonnet // Smart Repair Small-dent

Wing Rear Right // Repair & Painting-scratch + dent






Wing Rear Left // Repair & Painting-bad repair