TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48442999
Order No. / Reference: 27138416
Inspection date: 2 Nov 2026

Manufacturer: Audi	Model: A5 Sportback 45 TFSI quattro S tronic advanced
VIN: WAUZZZF53PA001357	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A5 Sportback 45 TFSI quattro S tronic advanced	
Vehicle Identification number	WAUZZZF53PA001357
Mileage (Read)	97,765 km
First registration	2 Aug 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	09/2027
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,984 ccm / 4
Power	195 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Manhattangrau Metallic (X7L)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	16,300 km
Last service on / at	05/2026 at 89,391 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM595846
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0588 / BVE 00275		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,175 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/35 R19 96Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	255/35 R19 96Y	Summer tyres on Light alloy	Bridgestone	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/40 R18 97V	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	245/40 R18 97V	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- Airbag for driver and front passenger
- Accent areas matte black
- Anti-lock braking system (ABS)
- Audi connect emergency call & service including vehicle control
- Electrically adjustable/heated exterior mirrors
- Outdoor temperature display
- Fabric headliner
- Tachometer
- Door sill trims with aluminum inlay
- Electronic Stability Control (ESC)
- Chassis: Standard chassis
- Remote key, without safe lock
- Luggage compartment lid, electrically opening and closing
- Transmission: S tronic (7-speed)
- Interior mirror dimming
- ISOFIX and Top Tether child seat anchors for the outer rear seats
- Headrests (4)
- LED taillights
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction
- Non-smoking version
- Package Gloss
- Wheel: Alloy wheels "5-V-spoke Y-design"
- Wheel: Tire repair kit
- Radio: MMI Radio Plus
- Radio accessories: Data module Europe
- Electromechanical power steering
- Front seats (standard seats)
- Phone: Bluetooth interface
- Glazing: Windscreen in heat-insulating and acoustic glazing
- Airbag: Front side airbags and head airbag system
- "quattro" all-wheel drive with ultra technology
- Drive slip control
- Audi drive select
- Audi pre sense city
- Exterior mirror housings in body color
- third brake light
- Decorative inlays diamond lacquer silver grey
- Rear parking sensors
- Electromechanical parking brake
- Driver information system
- Electric front windows
- front and rear floor mats
- Cruise control system with adjustable speed limiter
- Interior lighting
- Manual child lock
- Automatic air conditioning
- boot floor mat
- Fuel tank (58 liters)
- LED headlights
- Mild hybrid
- front center armrest
- Otto particulate filter
- Upholstery: Fabric finish Index
- Wheel: Tire pressure monitoring system
- Wheel: Tires optimized for rolling resistance, speed-limited
- Radio accessories: 8 speakers
- Rear seat backrest foldable
- Seat belts: Three-point automatic seat belts for all seats
- Start-stop system
- First aid kit with warning triangle
- Electronic immobilizer
- Green thermal insulation glazing

Extra equipment

- Airbag: Rear side airbags
- Audi virtual cockpit with 12.3" color display (Innovative, fully digital instrument cluster for flexible and needs-based display of relevant information according to driver requirements: speed/RPM, map display, Audi connect services, radio/media information, etc.; the VIEW button on the multifunction steering wheel allows switching between two different-sized displays of the round instruments. The display with smaller instruments enables large, clear graphics of the on-board computer and MMI content)
- Decorative inlays in matt brushed aluminum (for dashboard, door panels and center console)
- Deletion of model designation and performance/technology lettering
- Head-up display (projects driver-relevant information from assistance systems, navigation or warning messages onto the windshield in the driver's direct field of vision. The height-adjustable head-up display enables a high-contrast, multi-colored display within the driver's field of vision.)
- Comfort key with sensor-controlled luggage compartment unlocking (wireless communication between the key and the vehicle allows opening the doors and luggage compartment lid, and locking via the sensors on the door handles. The comfort key simply needs to be carried with the vehicle. The engine is started and stopped using the engine start/stop button. The luggage compartment lid can also be conveniently unlocked with a foot gesture by kicking the rear of the vehicle if your hands are full.)
- LED matrix headlights with dynamic turn signals front and rear (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, static curve lighting (supplementing lateral illumination in tight curves and when turning), all-weather light (to reduce glare in poor visibility conditions), maneuvering light (illuminating the swivel area when reversing), motorway light (extended beam range from a speed of 110 km/h), automatic dynamic headlight range control)
- Driving Assistance Package (Audi active lane assist - Audi adaptive cruise control - Audi pre sense rear and basic - Traffic jam assist - Predictive efficiency assist - Evasive steering assist - Left turn assist - High beam assist - Driver information system with color display - Camera-based traffic sign recognition - Lane change warning)
- Parking Assistance Package (Parking Aid Plus - Parking Assist - Rearview Camera)
- S line interior package (sports seats in front - S line seat covers in black fabric/leather combination with S embossing on the backrests of the front seats - 3-spoke leather steering wheel with multifunction plus including steering wheel grips in perforated leather and S emblem; steering wheel and gearshift boot with contrast stitching, color-coordinated - headliner in black fabric - decorative inlays in matt brushed aluminum with accent surfaces in gloss black - pedals and footrest in stainless steel - floor mats front and rear with contrast stitching)
- Black glass-look accent surfaces (for dashboard, door trim panels and center console insert; in conjunction with automatic transmission including cover for storage compartment in the center console)
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides with memory function (with integrated LED turn signals and curb view function for the passenger-side exterior mirror; aspherical mirror glass, including heated windshield washer nozzles. The passenger-side exterior mirror tilts downwards when reverse gear is engaged, providing the driver with a better view of the curb).
- Chassis (sports chassis) (with firmer spring and damping for more direct road contact and sporty handling)
- Interior elements in synthetic leather (lower center console and armrest in the doors in synthetic leather, color-matched to the interior color).
- Comfort automatic climate control 3-zone (in addition to the automatic climate control: - climate control unit with large TFT display and capacitive rocker switches - electronically regulates the air temperature and distribution individually for driver and front passenger - additional climate control unit for setting the rear passenger compartment temperature in the rear center console - automatic recirculation control via air quality sensor, with dust and odor-removing allergen filter - ventilated glove compartment - dust and odor-removing cabin air filter - residual heat utilization)
- Paint finish: Metallic
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus (height and reach of the leather steering wheel are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with 12 multifunction buttons. Includes a leather gearshift/selector lever knob and a leatherette handbrake grip.)
- Storage and luggage compartment package (Sportback) (flexible transport of items and comfort on journeys; consisting of: - storage net on the back of the front seat backrests - cupholder in the rear center armrest - storage compartment on the driver's side - lockable glove compartment in the luggage compartment: - luggage compartment net - net in recesses on the left and right - tension strap on the right)
- Business package (front seat heating - comfort package mirrors - infotainment package smartphone - navigation package - leather steering wheel in 3-spoke design with multifunction plus)
- Comfort package seats (variable headrests for the front seats - 4-way lumbar support for the front seats, electrically adjustable horizontally and vertically - comfort center armrest in the front, longitudinally adjustable and tiltable; additional storage option in the integrated storage compartment)

- Package: Black Optics Package (adds black accents to the exterior in the area of the Audi Singleframe grille, the trim strips on the side windows, and the front and rear bumpers. Design varies depending on model and equipment.)
- Wheel: Light alloy wheels in multi-spoke design, graphite grey, polished (8.5 J x 19 with tires 255/35 R 19)
- Wheel: Alloy wheels, 10-parallel spoke design (8.0 J x 18 with winter tires 245/40 R 18 - suitable for snow chains, maximum permissible speed 240 km/h)
- Three-seater rear seating system (distinctive outer rear seats, visually adapted to the front seats and an additional middle seat - 3 rear L-shaped headrests, manually height-adjustable for better rear visibility; rear seat backrest split in a 40:20:40 ratio or fully foldable)
- Seats: Sport seats plus front (electric adjustment of seat height, seat fore/aft position, seat and backrest tilt; manual adjustment of belt height - pronounced seat side bolsters for better lateral support in curves - extendable thigh support - pneumatic backrest bolster adjustment - pneumatic lumbar support with massage function - integrated front headrests - L-shaped headrests for 3 rear seats - S-embossing in the backrests of the front seats - with diamond stitching)
- Telephone: Smartphone interface with USB at the rear in V with navigation package (Audi Smartphone Interface - Bluetooth interface)
- Package: Ambient Lighting Package Plus (in addition to the Ambient Lighting Package: interactive and individual color profile. The interactive color profile is controlled by the Audi drive select modes. The individual color profile offers a choice of 30 colors. The color adjustments apply to the following contour and ambient lighting elements: - Rear footwell lighting - Front cupholders (multicolor) - Front/rear ambient door lighting (multicolor) - Front/rear door contour lighting (multicolor))
- Radio accessories: Audi sound system (10 speakers including center speaker and subwoofer - 6-channel amplifier - total output of 180 watts)
- Seat covers in Dinamica microfiber/leather combination with S embossing (seat center panels of the front seats and the two outer seats in the rear in Dinamica microfiber black or rotor grey with diamond quilting - seat side bolsters and headrest center panels front in leather black or rotor grey with contrast stitching - with S embossing in the backrests of the front seats)
- Seats: Electrically adjustable front seats with memory function for the driver's seat (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt; with memory function for the driver's side: 2 memory locations for the electrically adjustable front seats and the exterior mirrors, storable and recallable via the memory buttons in the door trim)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Side panel - rear right side	Side panel - Paint defect - Smart repair
4	Front bumper	Front bumper (Unterhalb) - Scratch(es) - Smart repair
5	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Door - front right side	Door handle - outside - Scratch(es) - Cover / polish
2	Roof	Roof - dent(s) - No deduction
3	Side panel - rear left side	Side panel - dent(s) - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 22 Nov 2023	794,07 €
2	Rear, Side right, Provided by user / customer, from 6 Nov 2022	1.828,60 €

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	247 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Additional tyres



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 3: Side panel - rear right side: Side panel - Paint defect - Smart repair



Damage 3: Side panel - rear right side: Side panel - Paint defect - Smart repair



Damage 3: Side panel - rear right side: Side panel - Paint defect - Smart repair




Damage 4: Front bumper: Front bumper (Unterhalb) - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper (Unterhalb) - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper (Unterhalb) - Scratch(es) - Smart repair



Damage 5: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Replace



Damage 5: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Replace




Wear and tear 1: Door - front right side: Door handle - outside - Scratch(es) - Cover / polish



Wear and tear 2: Roof: Roof - dent(s) - No deduction




Wear and tear 2: Roof: Roof - dent(s) - No deduction



Wear and tear 3: Side panel - rear left side: Side panel - dent(s) - No deduction




Wear and tear 3: Side panel - rear left side: Side panel - dent(s) - No deduction



Previous damage 1: Front



Previous damage 1: Front



Previous damage 2: Rear, Side right




Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Previous damage 2: Rear, Side right



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side