ARVAL
BNP PARIBAS GROUP


2CVM106


INSPECTION REPORT



End of contract

GENERAL INFO

File	325180
License plate	2CVM106
Vehicle identification number	WAUZZZF39P1063490
Dossier	2022279135
Make	Audi Q3 SB 45 TFSie PHEV S tro
Mileage	58911
First registration	12/12/2022
client availability date	14/10/2026
inspectionDate	21/10/2026







CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	




B
2-CVM-106
KEURING


DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
272	Bumper Front / Trim Right / Replace	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
283	Bumper Rear / Trim Right / Replace	N
18	Bumper Front / Spoiler / Replace	Y
64	Wing Front Left // Repair & Painting	Y
80	Door Front Left // Smart Repair Small	N
106	Door Rear Left // Polish	Y
153	Rear Bonnet // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
181	Wing Rear Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
271	Bumper Front / Trim Left / Replace	Y
421	Seat Front Right // Repair	Y

Damage Pictures




Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch + dent




Wing Front Left // Repair & Painting-scratch + dent






Seat Front Right // Repair-scratch





Door Front Right // Painting-scratch

Rear Bonnet / Rear Window / Replace-scratch




Rear Bonnet // Painting-scratch





Wing Rear Right // Smart Repair Medium-bad repair




Bumper Front / Trim Left / Replace-scratch





Bumper Front / Spoiler / Replace-scratch








Bumper Front // Painting-scratch




Bumper Front / Trim Right / Replace-scratch + dent




Bumper Rear / Lower Cover Not Painted / Replace-scratch




Bumper Rear / Trim Right / Replace-scratch







Bumper Rear // Painting-scratch