TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48092823
Order No. / Reference: 27089788
Inspection date: 13 Oct 2026

Manufacturer: Audi	Model: A3 35 TDI Sportback S tronic S line
VIN: WAUZZZGY7RA128141	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A3 35 TDI Sportback S tronic S line	
Vehicle Identification number	WAUZZZGY7RA128141
Mileage (Read)	71,581 km
First registration	29 Apr 2024
Number of holders	1
Next periodical technical inspection	04/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	Daytonagrau Perleffekt
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	15,700 km
Last service on / at	07/2026 at 64,936 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB026023
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BZO 02069		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,965 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	225/45 R17 91V	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/50 R17 93H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/50 R17 93H	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Traction control ASR
- Audi pre sense front
- Evasive steering assist and turning assist
- Exterior mirror housings in body color
- Headliner in steel grey fabric
- Decorative inlays in silk-effect lacquer, platinum grey
- Additive-free diesel particulate filter (DPF)
- Rear parking sensors
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Electronic Differential Lock (EDS)
- Chassis: Sport chassis
- Remote key (without Safe-Lock)
- Removable luggage compartment cover
- Transmission: S tronic 7-speed
- rear window wiper
- Electrically operated child safety lock
- Manual air conditioning
- Rear headrests (3)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction and paddle shifters
- Wheel: Alloy wheels - 17 inch - 5-spoke
- Tire pressure monitoring system
- Headlight
- 3-point automatic seat belts
- Seats: Standard front seats
- Lane Departure Warning
- 12-volt power outlet in the rear
- Glazing: Green tinted thermal insulation glazing
- Central locking with remote control
- Airbag: Front side airbags with head airbag system and front interaction airbag
- Audi connect emergency call & service m.connect remote & control
- Electrically adjustable and heated exterior mirrors
- third brake light
- Roof edge spoiler S
- Decorative strips in black glass look
- Digital instrument cluster - fully digital instrument cluster in 10.25 inches
- Electric auxiliary air heater
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Electric windows front and rear
- front and rear floor mats
- Speed limiter
- Heated rear window
- Interior lighting
- i-Size child seat attachment and top tether for the outer rear seats
- Front headrests
- Light and rain sensor
- Non-smoking version
- Radio: MMI Radio plus
- Tire repair kit
- Electromechanical power steering
- Seat covers in fabric
- Seats: Rear seat backrest foldable
- Start-stop system
- 12V socket
- Electronic immobilizer

Extra equipment

- 2-zone automatic climate control (electronically regulates air temperature, volume and distribution - separate temperature distribution for driver and front passenger side - with sun position-dependent control - automatic recirculation control - dust and odor separating allergen filter - air vents in the rear center console - separate defroster button for faster defrosting of the front and side windows)
- Adaptive cruise control (assists with acceleration, braking, and maintaining speed and distance. The adjustable speed limiter helps, for example, to prevent exceeding a preset maximum speed within built-up areas from approximately 30 km/h. Audi pre sense front uses a front radar to detect the area in front of the vehicle within the system's limits and warns of potential hazards with visual and audible signals.)
- Business package (USB ports with charging function in the rear - Audi connect Navigation & Infotainment plus - Audi phone box - Audi virtual cockpit plus - Smartphone interface (Android Auto and Apple CarPlay) - MMI Navigation plus with MMI touch - Cruise control)
- Seats: 4-way lumbar support (electrically adjustable, horizontally and vertically)
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with twelve multifunction buttons. Shift paddles allow manual gear changes.)
- Telephone: Audi Phone Box (universal Bluetooth interface - convenient, integrated hands-free system - coupling antenna for connecting the mobile phone to the external antenna for improved reception quality - reduced radiation in the vehicle interior - LTE support - charging option via USB port or wireless charging (Qi standard) - forget-to-use warning - charging status indicator in the MMI touch display - connection of a second mobile phone)
- Telephone: Smartphone interface in conjunction with MMI Navigation plus with MMI touch (The smartphone interface (Android Auto and Apple CarPlay) connects your smartphone to your Audi and seamlessly displays your smartphone content directly on the MMI display. Navigation, telephony, music, and selected third-party apps can be conveniently controlled via the MMI touch display and voice control. The connection can be established either using a suitable USB cable or wirelessly.)
- Wheel: Alloy wheels - 17 inch - 5-W spokes (8.0 J × 17, tire 225/45 R 17)
- Wheel: Winter wheels with 4 light alloy wheels, 5 parallel spokes (6.5 J x 17, winter tires 205/50 R17)
- Aluminum roof rails
- Auxiliary heating and ventilation (The auxiliary heater warms the interior and defrosts the windows without starting the engine. The auxiliary ventilation supplies fresh air and lowers the interior temperature. Both functions can be activated using a timer and a separate remote control. An intelligent control system with timer and departure time programming calculates the heating duration efficiently in terms of time and energy. Two heating modes are selectable: "defrost" (for the windows) and "warm" (for additional preheating of the interior).)
- Camera-based traffic sign recognition (Supports the driver by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions, which are within the detection range of the front camera. The traffic sign recognition is displayed automatically in the digital instrument cluster or in the optional Audi virtual cockpit.)
- LED headlights and LED taillights with dynamic turn signals (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, all-weather lights (to reduce glare in poor visibility conditions), motorway lights, static cornering lights, maneuvering lights (illumination of the maneuvering area at the front and sides when reversing), automatic dynamic headlight range control, intersection lights (in conjunction with MMI Nav. plus), dynamic rear turn signals, brake lights, tail lights, rear license plate lights, reversing lights)
- Paint finish: Daytona Gray Pearl Effect
- Parking assistant with parking aid plus (Using ultrasonic sensors, the system searches for suitable parallel or perpendicular parking spaces. For perpendicular spaces, the system calculates the parking path (forwards and backwards); for parallel spaces, it calculates the entry and exit paths. The driver must accelerate, shift gears, and brake, as well as monitor the parking process. The system handles the steering. Within the system's limits, the surround view displays warnings of obstacles around the vehicle, depending on the driving path. Multi-stage parking maneuvers are supported.)
- Phone: LTE support for Audi phone box
- Towbar (removable and lockable; ball rod and head made of forged steel, the 13-pin socket can be swivelled invisibly behind the bumper apron, the removed towbar fits in the spare wheel well; including trailer stabilization via the electronic stability control (ESC))
- Wheel: On-board tools and jack (in the luggage compartment)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair
2	Bonnet	Bonnet - Stone chips - Paint
3	Front bumper	Front bumper - Broken / torn - Replace

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 12 Jun 2025	1.045,76 €
2	Front, Provided by user / customer, from 12 Jun 2025	1.171,27 €
3	Side right, Provided by user / customer, from 11 Dec 2024	4.141,85 €

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
5	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	203 µm	Door - rear left side	172 µm
Door - rear right side	157 µm	Door - front left side	178 µm
Door - front right side	197 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Bonnet: Bonnet - Stone chips - Paint



Damage 2: Bonnet: Bonnet - Stone chips - Paint



Damage 2: Bonnet: Bonnet - Stone chips - Paint



Damage 2: Bonnet: Bonnet - Stone chips - Paint




Damage 2: Bonnet: Bonnet - Stone chips - Paint



Damage 2: Bonnet: Bonnet - Stone chips - Paint



Damage 2: Bonnet: Bonnet - Stone chips - Paint



Damage 3: Front bumper: Front bumper - Broken / torn - Replace



Damage 3: Front bumper: Front bumper - Broken / torn - Replace



Damage 3: Front bumper: Front bumper - Broken / torn - Replace



Damage 3: Front bumper: Front bumper - Broken / torn - Replace




Damage 3: Front bumper: Front bumper - Broken / torn - Replace



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Repainting 2: Door - rear left side



Repainting 2: Door - rear left side



Repainting 3: Door - rear right side




Repainting 3: Door - rear right side



Repainting 4: Door - front left side



Repainting 4: Door - front left side



Repainting 5: Door - front right side



Repainting 5: Door - front right side