TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 47858165
Order No. / Reference: 26956572
Inspection date: 30 Sept 2026

Manufacturer: Mercedes-Benz	Model: GLA 180 d 8G-DCT Entry
VIN: W1N4N1AB3RJ542864	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLA 180 d 8G-DCT Entry	
Vehicle Identification number	W1N4N1AB3RJ542864
Mileage (Read)	10,750 km
First registration	25 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Mountaingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	47 Tag(e)
Last service on / at	11/2025 at 5,844 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV724690
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	Conditional: Light/moisture/dirt	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ATH 00073		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,160 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	215/65 R17 99V	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Light alloy	Michelin	7mm / 6mm
2)	215/65 R17 99H	Winter tyres on Light alloy	Michelin	6mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Adaptive Highbeam Assist
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Anti-lock braking system (ABS)
- Center console armrest for driver and front passenger with integrated storage compartment
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Roof rails in polished aluminum
- Double cup holder
- Third brake light in LED technology
- ECO start/stop function
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Windscreen laminated glass
- Luggage net on driver and passenger seatbacks
- Transmission: 8G-DCT dual-clutch automatic transmission, 8-speed
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Communication module (LTE) for the use of Mercedes me connect services
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: Entry
- Package: Light and Visibility Package
- Package: USB Package Plus
- Radio: MBUX multimedia system
- Radio accessories: Digital radio
- Remote Services
- Rear view camera
- Windscreen wipers with rain sensor
- Seats: Comfort seats
- Heated seats for driver and front passenger
- TIREFIT with tire inflation compressor
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- Decorative elements Star Pattern
- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Traction control (ASR)
- ATTENTION ASSIST
- Automatic passenger airbag deactivation
- Outdoor temperature display
- Basic services
- Diesel particulate filter
- Tachometer
- DYNAMIC SELECT
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis with lowered suspension
- electric parking brake
- Velour floor mats
- Speed Limit Assistant
- Rear window wiper with intermittent function
- Heated rear window with timer
- ISOFIX child seat anchorages with Top Tether in the rear
- Climate: THERMATIC automatic climate control
- Headrests 5-way
- Paint finish: Solid
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Direct steering
- Navigation accessories: Extended MBUX functions
- Navigation: Hard disk navigation
- Navigation: MBUX Navigation Premium
- Package: Cargo space
- Package: Seating comfort
- Upholstery: ARTICO leatherette/fabric
- Radio accessories: CENTRAL MEDIA DISPLAY 10.25"
- Tire pressure monitoring system
- Wheels: 43.2 cm (17") light alloy wheels in a 5-twin-spoke design
- Seat belts GLA-Class
- Seats: Rear seat backrests foldable
- Cruise control
- Pre-installation for digital key handover
- Electronic immobilizer
- Central locking

Extra equipment

- 1 set of WKR 17 inch 5 spoke aluminum wheels
- Paint finish: Metallic (according to sample card)
- Package: Entry Advanced (4-way lumbar support - Mirror package (automatically dimming interior mirror, electrically folding exterior mirrors) - Parking package with reversing camera (Active Parking Assist with PARKTRONIC) - EASY-PACK tailgate (electrically opening and closing tailgate, switch for electrically opening the tailgate in the driver's door, switch for electrically closing the tailgate at the bottom edge of the tailgate, manual load compartment cover))
- Phone accessories: Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Fully digital instrument display (high-resolution 10.25" display)
- Active Distance Assist DISTRONIC (radar sensor in the radiator grille - automatically acting assistance system - active up to a speed of 160 km/h - visual and acoustic warning if you as the driver need to intervene - depending on the driving program, the vehicle accelerates faster or slower to the desired speed - detected speed limits can be conveniently adopted by pressing a button on the steering wheel (only in conjunction with Traffic Sign Assist or Speed Limit Assist))
- Package: Winter Package (heated steering wheel - heated seats for driver and front passenger - heated windshield washer system)
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Wear and tear

No.	Component group	Description
1	Documents	Service book (Digital) - Missing - No deduction
2	Instrument panel	Indicator light - on - No deduction
3	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
4	Trim / covers	Boot lining - Scratch(es) - No deduction
5	Headlight	Headlight - right side - Stone chips - No deduction
6	Headlight	Headlight - left side - Stone chips - No deduction
7	Front bumper	Front bumper - Stone chips - No deduction
8	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction
9	Door - front right side	Door handle - outside - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

360° Kamara nicht vorhanden.

Zum Besichtigungszeitpunkt waren keine ausreichenden Lichtverhältnissen vorhanden, das Fahrzeug war verschmutzt. Folgekosten können entstehen.

Das Fahrzeug weist dem Alter und der Laufleistung entsprechende Gebrauchsspuren auf.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Additional tyres



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Wear and tear 2: Instrument panel: Indicator light - on - No deduction



Wear and tear 9: Door - front right side: Door handle - outside - Scratch(es) - Cover / polish



Wear and tear 9: Door - front right side: Door handle - outside - Scratch(es) - Cover / polish