TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48003031
Order No. / Reference: 27114723
Inspection date: 7 Oct 2026

Manufacturer: Peugeot	Model: 308 SW BlueHDi 130 EAT8 Stop & Start Allure
VIN: VF3LCYHZKLS261156	





Vehicle details

Manufacturer / Type / Model / Equipment	
Peugeot 308 SW BlueHDi 130 EAT8 Stop & Start Allure	
Vehicle Identification number	VF3LCYHZKLS261156
Mileage (Read)	96,851 km
First registration	7 Dec 2020
Number of holders	1
Next periodical technical inspection (Report on hand)	04/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Perlmutt Weiß Perleffekt
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	22,600 km
Last service on / at	07/2026 at 89,549 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FU421926
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3003 / AYV 00135		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,890 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	205/55 R16 91H	Summer tyres on Light alloy	Michelin	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Dunlop	7mm / 7mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Dunlop	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbags (6)
- Electrically folding exterior mirrors
- Exterior mirrors with mirror caps in car color
- On-board computer
- Tachometer
- pass-through flap
- Rear parking aid (acoustic and visual)
- FAP diesel particulate filter
- Misfueling protection
- Electric windows, front
- Follow-me-home function (automatic)
- Cruise control system with speed limiter
- Basic equipment 308
- LED taillights
- Interior mirror automatically dimming
- Map pockets on the front seatbacks
- Child safety locks on the rear doors
- Front headrests (2)
- Rear headrests (3)
- Steering wheel adjustable for height and reach
- light sensor
- front center armrest
- Fog light
- Package: City Package
- Package: Dynamic Package
- Package: View
- Pollen filter
- Rain sensor
- Tire pressure monitoring system
- Wheels: Tire repair kit (compressor + spray)
- Front and rear windscreen wipers with intermittent function
- Seats: Passenger seat height adjustable
- Seats: Manual lumbar support for driver
- 12-volt socket, row 1
- Stop&Start system
- Pre-installation for WEBASTO auxiliary heater
- thermal insulation glazing
- Anti-lock braking system
- Electrically adjustable and heated exterior mirrors
- Hill start assist
- Roof rails in aluminum look
- Third brake light
- EBV (Electronic Brakeforce Distribution)
- ESP (Electronic Stability Program) with ASR (Anti-Slip Regulation)
- Electric rear windows
- electric parking brake
- luggage compartment roller blind
- Transmission: 8-speed automatic transmission EAT8
- Seat belts: 3-point safety belts in all seats
- Heated rear window
- ISOFIX - 2 child seat anchor points on the rear seat
- Keyless system
- Automatic climate control (2-zone) including activated carbon filter
- Paint finish: Solid
- Steering wheel: Multifunction leather steering wheel, black
- Rear center armrest including 2 cup holders
- Multimedia: Mirror Screen
- Emergency brake assist with automatic activation of the hazard warning lights
- Package: Comfort Package
- Peugeot Connect Box
- Radio: Multifunctional touchscreen with 9.7" color display including audio system
- Wheels: Alloy wheels "Rubis" 7J x 17"
- paddle shifters on the steering wheel
- Electric, speed-sensitive power steering
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat and backrest 40/60 split folding
- 12-volt socket, row 2
- Daytime running lights: LED daytime running lights
- Immobiliser
- Central locking can be activated from inside, with remote control

Extra equipment

- luggage compartment partition net
- Paint finish: Special paint finish "Pearl White"
- Package: Safety Package Plus (Active Safety Brake - High Beam Assist - Front Collision Warning - Color Dot Matrix Instrument Cluster - Driver Alert System - Lane Keeping Assist with Steering Intervention - Traffic Sign Recognition with Speed Limit Display in Instrument Cluster - incl. Visibility Package)
- Rear window and rear side windows are more heavily tinted.
- Radio accessories: Digital radio reception DAB (Digital Audio Broadcasting)
- Reversing camera with 180° surround view
- Seats: Heated front seats, adjustable in three stages

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Front bumper	Front bumper - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Interior	Interior - Soiled - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Front bumper: Front bumper - Scratched - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Damage 2: Front bumper: Front bumper - Scratched - Smart repair