APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	RENAULT
Model / version:	MASTER
Vin:	VF1MA000672976358
Plate:	2GFK547
Mileage:	75550
First registration:	25/11/2024
Color:	

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?



DOCUMENTS


Certificate of conformity:	✗
Registration certificate:	✗
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	1
Original key:	✓

PICTURES



















VIN INFORMATION

Radio	Radio avec lecteur CD	Système navigation
Pilotée / robotisée	6 rapports	Traction avant
Porte latérale droite coulissante	Porte latérale droite tôlée	Fourgon tôlé
Portes de chargement arrière tôlées	3 682 mm	3 500 kg
Pavillon surélevé	Usine de production : début de numéro B...	Projecteurs antibrouillard
Bavettes avant	Bavettes arrière	Code équipement E2
Matière : tôle	Lettre repère (J)	Diamètre avant 16
Diamètre arrière 16	Largeur avant 5,5	Largeur arrière 5,5
Diamètre avant 16	Diamètre arrière 16	Hauteur avant 75
Hauteur arrière 75	Indice de vitesse avant C	Indice de vitesse arrière C
Largeur avant 195	Largeur arrière 195	Roue de secours tôle
Climatisation	Climatisation réfrigérant 1234YF	Cloison de séparation tôlée
Filtre à particules	Nacrée vernissée	Rétroviseur gauche à réglage électrique
Rétroviseur droit à réglage électrique	Garnitures tissu	Aide au stationnement avant
Aide au stationnement arrière	Caméra arrière de recul	Régulateur et limiteur de vitesse
Verrouillage centralisé	Lève-vitres avant électrique à impulsion	détecteur de pluie essuie-vitre
Programme électronique de stabilité ESP	Assistant maintien de la voie	Avertisseur d'angle mort
depuis 06.24	banquette passager double et multifonctions (Type 3,4)	marchepied ar
2299 cc (2,3 L) 99 KW FV00/JV00	2299 cc (2,3 L) 81 KW FV1U/JV1U	réduction d'émissions par catalyse (AVSCR1)
réduction de puissance gaz d'échappement (PREM02)	grands enjoliveurs de roue	série supplémentaire SAN913
pack chrome extérieur et intérieur (PRCHR3)		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?

Rear parking sensor:	?	**Repair kit:**	✗
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	2 mm		225/65R16	All-seasons		?
Front right	2 mm		225/65R16	All-seasons		?
Rear left	2 mm		225/65R16	All-seasons		?
Rear right	2 mm		225/65R16	All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot carpet - Leeghalen koffer	Not original part
2	Interior	Dirty
3	Certificate of conformity	Missing
4	Certificate of registration 1	Missing
5	Contact key	Missing
6	Windscreen	Crack
8	Side wall RL	Scratch(es)
9	Boot door panel RL	Scratch(es)
10	Wing RR	Dent(s) and scratch(es)
11	Wing trim RR	Missing
12	Sliding door R	Dent(s) and scratch(es)
13	Outer sill R	Deformed / Strained
14	Central pillar R	Dent(s) and scratch(es)
15	Wheel cover FR	Grooved
16	Wheel cover RR	Grooved

Total: 15


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
7	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Boot carpet - Leeghalen koffer - Not original part






2 - Interior - Dirty







3 - Certificate of conformity - Missing



4 - Certificate of registration 1 - Missing



5 - Contact key - Missing



6 - Windscreen - Crack




8 - Side wall RL - Scratch(es)










9 - Boot door panel RL - Scratch(es)






10 - Wing RR - Dent(s) and scratch(es)





11 - Wing trim RR - Missing





12 - Sliding door R - Dent(s) and scratch(es)




13 - Outer sill R - Deformed / Strained





14 - Central pillar R - Dent(s) and scratch(es)




15 - Wheel cover FR - Grooved






16 - Wheel cover RR - Grooved





7 - Bodywork - Dent(s) and scratch(es) - Renta®









SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

01/07/2026 11:15

