TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

# Expertise

Protocol number: 48240689
Order No. / Reference: 27144341
Inspection date: 21 Oct 2026

| Manufacturer: Ford | Model: Kuga 2.5 Duratec PHEV VIGNALE |
|---|---|
| VIN: WF0FXXWPMHNL51767 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Ford Kuga 2.5 Duratec PHEV VIGNALE | |
| **Vehicle Identification number** | WF0FXXWPMHNL51767 |
| **Mileage** (Read) | 69,807 km |
| **First registration** | 30 Jun 2022 |
| **Number of holders** | 1 |
| **Fuel type** | Hybr.B/E ext.aufl |
| **Engine displacement / Cylinder** | 2,488 ccm / 4 |
| **Power** | 112 kW |
| **Gearbox / Number of gears** | Automatic / 1 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Multipurpose vehicle |
| **Colour / colour code** | Magnetic-Grau Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Leather |
| **Colour of upholstery** | Anthracite-Black |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital evidence / incomplete | **Next maintenance in** | 0 % |
| **Last service on / at** | 11/2025 at 54,014 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GH422487 |
| **Previous damage / Accident** | None detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 8566 / BTM 00016 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,320 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/60 R18 100V | Winter tyres on Light alloy | Goodyear | 6mm / 6mm |
| 2) | 225/60 R18 104V | Summer tyres on Light alloy | Continental | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/65 R17 102H | Winter tyres on Light alloy | Goodyear | 5mm / 5mm |
| 2) | 225/65 R17 102H | Winter tyres on Light alloy | Goodyear | 5mm / 5mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 08/2030 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: 7.5 J x 18 alloy wheels (4) in 5x4 spoke design, Luster Nickel premium paint finish
- Fabric headliner
- Roof spoiler
- Dual exhaust system
- Front door sill trims, Vignale design
- Driving mode switch selective
- Electric windows front and rear
- Ford Easy Fuel
- Ford Power Start Function & Ford Key Free System
- Luggage compartment cover, roller blind, removable
- Cruise control
- Illuminated glove compartment
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- charging cable
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- Front center console with integrated armrest
- Navigation system: Ford navigation system including Ford SYNC 3
- Package: Winter II
- Pedal assembly with aluminum surface
- Post-Collision Assist
- Pre-Collision Assist
- Wheel arch trim painted in vehicle color
- Rear view camera
- Headlights with delayed shut-off
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Power outlet: 12-volt connection in the luggage compartment
- Central locking with remote control and remote luggage compartment release
- Ambient lighting
- Electrically adjustable, heated and folding exterior mirrors (VIGNALE)
- Tires: Tire repair kit
- third brake light
- Roof rails, silver-colored
- 12.3-inch digital instrument panel
- Tachometer
- Electronic Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission
- Heated rear window
- rear window wiper
- Intelligent Protection System (IPS)
- Air conditioning with automatic temperature control
- Front and rear headrests (5) height adjustable
- LED taillights
- Steering column, adjustable in height and reach
- Rear center armrest with cup holder
- MyKey key system
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Front and rear parking pilot system
- Upholstery: Premium Sensico upholstery in leather look with leather seat center panels
- Radio accessories: B&O Sound System
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Power steering
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front seats, individually and variably heated
- Static LED headlights
- Carpet floor mats front and rear
- Immobiliser

### Extra equipment

- Package: Driver Assistance Package (Automatic Transmission) (Intelligent Adaptive Cruise Control with Traffic Sign Recognition System - Traffic Jam Assist with Stop&Go Function and Lane Keeping Assist - Wrong-Way Driver Warning System - Evasive Steering Assist - Driver Drowsiness Detection - Pre-Collision Assist including Forward Collision Warning System with Cross Traffic Alert - Blind Spot Assist with Emergency Braking Function and Trailer Detection - Active Park Assist with Parking Assist and Semi-Autonomous Vehicle Steering - Front Camera with Split View - Door Edge Protectors - Intelligent Speed Limiter with Speed Limit Display)
- Detachable towbar (including ESP trailer stabilization)
- Package: Technology (Adaptive LED headlights with glare-free high beam assist and dynamic cornering lights, automatic headlight range control and LED fog lights - Head-up display)
- Paint finish: Special metallic paint finish
- Panoramic sliding sunroof, electric, including roof console with glasses storage compartment

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Wheel / tyres | Tyre - front - Differs from the original configuration - Replace |
| 2 | Misc. | Inspection / maintenance - Due - Perform |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Door - front right side | Door - dent(s) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Repainting

| No. | Repainting |
|---|---|
| 1 | Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

| | |
|---|---|
| Boot lid / rear door | 242 µm |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)




**Figure 5:** Interior - front




**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres



**Figure 13:** Documents





**Figure 14:** Documents



**Figure 15:** Additional tyres





**Figure 16:** Navigation





**Figure 17:** Misc.




**Figure 18:** Misc.




**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.




**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.



**Figure 29:** Misc.



**Figure 30:** Misc.




**Figure 31:** Misc.



**Damage 1:** Wheel / tyres: Tyre - front - Differs from the original configuration - Replace




**Damage 2:** Misc.: Inspection / maintenance - Due - Perform



**Repainting 1:** Boot lid / rear door