TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

# Expertise

Protocol number: 48117038
Order No. / Reference: 27108731
Inspection date: 14 Oct 2026

| Manufacturer: Ford | Model: Galaxy 2.0 EcoBlue S&S Aut. TITANIUM |
|---|---|
| VIN: WF0KXXWPCKNS15877 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Ford Galaxy 2.0 EcoBlue S&S Aut. TITANIUM | |
| **Vehicle Identification number** | WF0KXXWPCKNS15877 |
| **Mileage** (Read) | 175,797 km |
| **First registration** | 29 Apr 2022 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** (Report on hand) | 04/2027 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,995 ccm / 4 |
| **Power** | 140 kW |
| **Gearbox / Number of gears** | Automatic / 8 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Car station wagon |
| **Colour / colour code** | Obsidian-Schwarz Metallic |
| **Doors / Seats** | 5 / 7 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Anthracite-Black |
| **Vehicle with smoke odor** | no |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 19,000 km |
| **Last service on / at** | 04/2026 at 164,000 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GK810991 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 8566 / BQR 00347 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,605 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/55 R17 103Y | Summer tyres on Light alloy | Pirelli | 4mm / 4mm |
| 2) | 235/55 R17 103Y | Summer tyres on Light alloy | Pirelli | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/55 R17 103V | Winter tyres on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 235/55 R17 103V | Winter tyres on Light alloy | Pirelli | 5mm / 5mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 04/2026 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

## Standard equipment

- Airbag: Passenger airbag deactivation
- Anti-lock braking system (ABS) (with Electronic Stability Program (ESP), Roll Stability Control (RSC) and Traction Control System (TCS))
- Attachment points for safety partition grilles (attachment points 1st row of seats)
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires (in 5x2-spoke design)
- Hill start assist
- Roof rails "aluminum look"
- Tachometer
- Lane Assist including Lane Keeping Assist and Driver Alert (warns the driver of an unintentional lane change via short steering wheel vibrations (without activation of the turn signal) - additionally, active steering support assists in returning to the lane)
- Ford Key Free System (keyless locking/unlocking)
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot (information about the current status or location of the vehicle as well as control of selected vehicle functions via smartphone with the FordPass app - eCall emergency call system to send an emergency call in the event of an accident or when manually activated - Real-time traffic information - Wi-Fi hotspot (up to 4G/ LTE7, for up to 10 mobile devices))
- Intelligent Protection System (IPS) including: - Front airbags for driver and front passenger - Knee airbag for driver - Head and shoulder airbags in the front and for the 2nd and 3rd rows of seats - Side airbags for driver and front passenger - Side airbags on the outer seats of the 2nd row - Seat belt tensioners and belt force limiters in the front - 3-point seat belts in all seats, height-adjustable in the front)
- Steering wheel: Multifunction leather steering wheel
- Steering wheel: Paddle shifters on the steering wheel
- Front center console with padded armrest (storage compartment and 2 cup holders)
- Ford navigation system including Ford SYNC 3 with AppLink, touchscreen, DAB/DAB+ and FordPass Connect (communication and entertainment with voice control - Android Auto, Apple CarPlay - Bluetooth hands-free system and audio streaming - eCall emergency call system - live traffic - Wi-Fi hotspot - radio/CD player, 2 USB ports, 8 speakers, steering wheel controls - 20.3 cm screen - DAB/ DAB+ - acoustic and visual route guidance, dynamic navigation, lane keeping assist, road map for Europe - extended voice control and voice output - Michelin travel guide for Europe - quick address search)
- Upholstery: Cloth
- Tire Pressure Monitoring System (TMPS)
- Headlight assistant with day/night sensor (high beam assistant - interior mirror, automatically dimming)
- Ambient lighting in the front with LED technology (including lighting of the front door handles, audio system console, cup holders and footwell)
- Exterior mirrors painted in body color, electrically adjustable and heated (with integrated turn signals and ambient lighting)
- Tires: Tire repair kit ((maximum speed of 80 km/h when used))
- third brake light
- Diesel particulate filter (DPF)
- Driver information system display 25.4 cm color (on-board computer with fuel consumption and mileage information as well as outside temperature display)
- Electric front and rear windows (with all-around closing function)
- Electronic parking brake
- Ford Power Start function (keyless start, including two passive keys with remote control)
- Cruise control system with intelligent speed limiter (interior mirror, automatically dimming - traffic sign recognition system)
- Transmission: 8-speed automatic transmission
- Back window, heater
- rear window wiper
- Interior lighting with delay circuit
- Isofix mounting (on all seats in the 2nd row)
- Electric child safety lock
- Air conditioning with automatic temperature control, CFC-free (separately adjustable for driver and front passenger side as well as rear (3-zone automatic climate control))
- Paint finish: Solid
- Steering wheel: Steering column, adjustable in height and reach
- Front and rear reading lights (with LED technology)
- MyKey key system (individually programmable second key) (setting options include: limiting the maximum speed and radio volume, speed warning (when the set speed limit is exceeded), safety assistance systems cannot be deactivated, extended warning system for unfastened seat belts)
- Fog lights with LED technology
- Emergency brake light (pulsating illumination of the brake lights during hard braking)
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Front and rear parking pilot system
- Rain sensor
- Headlight dipped beam with switch-off delay including "greeting function"
- Electro-mechanical power steering (EPAS - Electric Power Assisted Steering)
- Seats: 3rd row of seats with 2 individual seats (FoldFlatSystem) (3rd row of seats can be folded down individually at the touch of a button and folded up electrically - headrests can be lowered)
- Seats: Comfort seats, front
- Start-stop system

- Seats: 2nd row of seats with 3 individual seats (FoldFlat System) (adjustable longitudinally - seat backrests individually foldable - headrests retractable - easy entry to the 3rd row of seats (Easy Entry))
- Seats: Driver and front passenger seats, 4-way manually adjustable (including manually adjustable lumbar support)
- Seats: Trays on the front seat backrests
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- LED daytime running lights
- Velour carpet floor mats (for the 1st, 2nd and 3rd row of seats)
- thermal insulation glazing
- Cigarette lighter (and ashtray in the center console)
- Power outlet: 230-volt connection (150 watts)
- Front bumper painted in body color (rear bumper top painted in body color, bottom painted black)
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control (remote luggage compartment release - second folding vehicle key)

### Extra equipment

- Package: Business III (Automatic) (Sony Navigation incl. Ford SYNC 3, AppLink, Touchscreen, Voice Control, Radio/CD Player, MP3-compatible, 2 USB ports, 390-watt premium sound system, 12 speakers, steering wheel remote control, Bluetooth hands-free system, FordPass Connect, eCall, DAB/DAB+, Adaptive LED headlights with glare-free high beam, ACC, Traffic Jam Assist, Pre-Collision Assist, Forward Collision Warning, Emergency Brake Assist, Front and Rear View Camera, Blind Spot Assist, Cross Traffic Alert, Dynamic Distance Control, Power Tailgate with Sensors, Ford Key Free System, Park Assist)
- Paint finish: Metallic
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Swiveling towbar (incl. ESP trailer stabilization)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Equipment | Tirefit filler - Expired - Replace |
| 2 | Boot lid / rear door | Boot lid - Glued / labelled - De-glue / neutralise |
| 3 | Door - rear left side | Door - Dent / paintcoat damage - Smart repair |
| 4 | Rear bumper | Rear bumper (Ladekante) - Scratch(es) - Smart repair |
| 5 | Door - rear right side | Door (unterhalb) - Scratch(es) - Paint |
| 6 | Side panel - rear left side | Side panel (unterhalb) - Paint defect - Paint |
| 7 | Side panel - rear right side | Side panel (unterhalb) - Scratch(es) - Paint |
| 8 | Bonnet | Bonnet (Sandstrahleffekt) - Stone chips - Paint |
| 9 | Front bumper | Front bumper (Sandstrahleffekt) - Stone chips - Paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Vehicle glazing | Windscreen with lane departure assistant - Stone chips - No deduction |
| 2 | Mudguard - right side | Mudguard - right side - Stone chips - Cover / polish |
| 3 | Door - front left side | Door - Scratch(es) - Cover / polish |
| 4 | Door - front right side | Door edge - Scratch(es) - Cover / polish |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

Serviceintervall nicht abrufbar




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)




**Figure 10:** Cargo area




**Figure 11:** VIN




**Figure 12:** Mounted tyres




**Figure 13:** Documents





**Figure 14:** Documents





**Figure 15:** Documents




**Figure 16:** Documents




**Figure 17:** Documents




**Figure 18:** Documents



**Figure 19:** Additional tyres




**Figure 20:** Navigation



**Figure 21:** Misc.




**Figure 22:** Misc.




**Figure 23:** Misc.



**Figure 24:** Misc.




**Figure 25:** Misc.





**Figure 26:** Misc.




**Figure 27:** Misc.



**Figure 28:** Misc.




**Figure 29:** Misc.




**Figure 30:** Misc.




**Figure 31:** Misc.



**Figure 32:** Misc.



**Figure 33:** Misc.



**Figure 34:** Misc.



**Figure 35:** Misc.



**Figure 36:** Misc.



**Figure 37:** Misc.



**Figure 38:** Misc.



**Figure 39:** Misc.



**Damage 1:** Equipment: Tirefit filler - Expired - Replace





**Damage 1:** Equipment: Tirefit filler - Expired - Replace




**Damage 2:** Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




**Damage 2:** Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair



**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair




**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair



**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair



**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair



**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair




**Damage 4:** Rear bumper: Rear bumper (Ladekante) - Scratch(es) - Smart repair




**Damage 4:** Rear bumper: Rear bumper (Ladekante) - Scratch(es) - Smart repair



**Damage 4:** Rear bumper: Rear bumper (Ladekante) - Scratch(es) - Smart repair



**Damage 5:** Door - rear right side: Door (unterhalb) - Scratch(es) - Paint




**Damage 5:** Door - rear right side: Door (unterhalb) - Scratch(es) - Paint



**Damage 5:** Door - rear right side: Door (unterhalb) - Scratch(es) - Paint




**Damage 5:** Door - rear right side: Door (unterhalb) - Scratch(es) - Paint



**Damage 6:** Side panel - rear left side: Side panel (unterhalb) - Paint defect - Paint




**Damage 6:** Side panel - rear left side: Side panel (unterhalb) - Paint defect - Paint



**Damage 6:** Side panel - rear left side: Side panel (unterhalb) - Paint defect - Paint




**Damage 6:** Side panel - rear left side: Side panel (unterhalb) - Paint defect - Paint



**Damage 6:** Side panel - rear left side: Side panel (unterhalb) - Paint defect - Paint




**Damage 6:** Side panel - rear left side: Side panel (unterhalb) - Paint defect - Paint




**Damage 7:** Side panel - rear right side: Side panel (unterhalb) - Scratch(es) - Paint




**Damage 7:** Side panel - rear right side: Side panel (unterhalb) - Scratch(es) - Paint



**Damage 7:** Side panel - rear right side: Side panel (unterhalb) - Scratch(es) - Paint



**Damage 7:** Side panel - rear right side: Side panel (unterhalb) - Scratch(es) - Paint




**Damage 8:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



**Damage 8:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




**Damage 8:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




**Damage 8:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



**Damage 8:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



**Damage 8:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




**Damage 9:** Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



**Damage 9:** Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



**Damage 9:** Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



**Damage 9:** Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint




**Damage 9:** Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint




**Damage 9:** Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint




**Damage 9:** Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



**Wear and tear 1:** Vehicle glazing: Windscreen with lane departure assistant - Stone chips - No deduction



**Wear and tear 1:** Vehicle glazing: Windscreen with lane departure assistant - Stone chips - No deduction




**Wear and tear 2:** Mudguard - right side: Mudguard - right side - Stone chips - Cover / polish




**Wear and tear 2:** Mudguard - right side: Mudguard - right side - Stone chips - Cover / polish




**Wear and tear 2:** Mudguard - right side: Mudguard - right side - Stone chips - Cover / polish



**Wear and tear 2:** Mudguard - right side: Mudguard - right side - Stone chips - Cover / polish



**Wear and tear 3:** Door - front left side: Door - Scratch(es) - Cover / polish




**Wear and tear 3:** Door - front left side: Door - Scratch(es) - Cover / polish




**Wear and tear 3:** Door - front left side: Door - Scratch(es) - Cover / polish



**Wear and tear 3:** Door - front left side: Door - Scratch(es) - Cover / polish




**Wear and tear 4:** Door - front right side: Door edge - Scratch(es) - Cover / polish



**Wear and tear 4:** Door - front right side: Door edge - Scratch(es) - Cover / polish



**Wear and tear 4:** Door - front right side: Door edge - Scratch(es) - Cover / polish



**Wear and tear 4:** Door - front right side: Door edge - Scratch(es) - Cover / polish