Skoda

VIN: TMBJW8NX9RY071283

Estimated repair cost

75.00 EUR
TOTAL



Description

Registration number 2GRW310	**Registration date** -	**Odometer** 79482 km
Color -	**Year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction	net cost
001	Door sill / Front Left	Scratched	Acceptable	-




Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
002	Seat / Front Left Trim material : Fabric	Stained	Cleaning	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

#	Element	Defect	Correction	net cost
003	Seat / Back Right	Stained	Cleaning	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

Loose Items

- ☑ Slow charging cable (Type 2, Mode 2)
- ☑ Registration certificate
- ☑ Spare Key
- ☑ Document holder
- ☑ First aid kit
- ☑ Quick charging cable (Type 3, Mode 3)
- ☑ Registration certificate owner
- ☑ Tyre repair kit complete
- ☑ Refill tyre repair kit
- ☑ Load cover
- ☑ Compressor tyre repair kit
- ☑ User manual
- ☑ Triangle

Main set of tyres

Front Left	HANKOOK	205/55/17 95 V All-season	4 mm
Front Right	HANKOOK	205/55/17 95 V All-season	4 mm
Back Left	HANKOOK	205/55/17 95 V All-season	4 mm
Back Right	HANKOOK	205/55/17 95 V All-season	4 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer




Navigation



Spare Tyre


Cable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Vin



Other


Door sill / Front Left / Scratched



Door sill / Front Left / Scratched


Seat / Front Left / Stained



Seat / Front Left / Stained


Seat / Back Right / Stained


Seat / Back Right / Stained

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.