Ford

VIN: WF0FXXWPMHMR40311

Estimated repair cost

561.00 EUR
TOTAL



Description

Registration number 2EDR689	**First registration date** -	**Odometer** 67084 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Rim / Front Right Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	
-	-	-	Lumpsum
Bodywork cost	**Paint cost**	**MaterialCost**	**165.00 EUR**
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

002	Rim / Back Right Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Front face / -	Chip	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

004	Bumper / Front Painted : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

005	Door / Front Left	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

006	Door sill / Front Left	Dent	Repair	80.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	**0.50 h**	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	**42.50 EUR**	-	

007	Door / Back Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

008	Roof post A/B/C / Back Left	Dent	Acceptable	-

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

009	Bumper / Back Painted : No		Scratched	Repair	190.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**190.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

010	Bumper / Back Painted : Yes		Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

011	Bumper moulding / Back Painted : Yes / Material : Plastic / Chromed : No		Scratched	Painting	88.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	**0.60 h**	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	**51.00 EUR**	-	

012	Wing / Back Right		Scratched	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

013	Door / Back Right		Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

014	Door / Front Right		Dent	Acceptable	-

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

015	Exterior door mirror shell / Right	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

Loose Items

- [x] Quick charging cable (Type 2, Mode 3)
- [x] Tyre repair kit complete
- [x] User manual
- [x] Service book
- [x] Spare Key
- [x] Slow charging cable (Type 2, Mode 2)

Main set of tyres

Front Left	UNIROYAL	225/65/17 106 V All-season	7 mm
Front Right	UNIROYAL	225/65/17 106 V All-season	7 mm
Back Left	UNIROYAL	225/65/17 106 V All-season	5 mm
Back Right	UNIROYAL	225/65/17 106 V All-season	5 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat



Front passenger compartment


Front right




Odometer


Spare Tyre



Vin


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Front face / - / Chip



Bumper / Front / Scratched



Bumper / Front / Scratched



Door / Front Left / Dent



Door / Front Left / Dent



Door sill / Front Left / Dent



Door sill / Front Left / Dent



Door sill / Front Left / Dent



Door / Back Left / Scratched



Door / Back Left / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Roof post A/B/C / Back Left / Dent



Roof post A/B/C / Back Left / Dent



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper moulding / Back / Scratched



Bumper moulding / Back / Scratched



Bumper moulding / Back / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Door / Back Right / Scratched



Door / Back Right / Scratched



Door / Front Right / Dent



Door / Front Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Front Right / Dent



Exterior door mirror shell / Right / Scratched



Exterior door mirror shell / Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.