TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48203905
Order No. / Reference: 27173550
Inspection date: 15 Oct 2026

Manufacturer: Audi	Model: Q5 50 TFSIe quattro S tronic advanced
VIN: WAUZZZFY8P2171184	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi Q5 50 TFSIe quattro S tronic advanced	
Vehicle Identification number	WAUZZZFY8P2171184
Mileage (Read)	149,235 km
First registration	8 Sept 2023
Number of holders	Unknown
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,984 ccm / 4
Power	195 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Florettsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Brown
Re-import	yes

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	5,000 km
Last service on / at	07/2026 at 139,148 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV268272
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BYJ 00099		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,660 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105W	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	235/55 R19 105W	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R17 104H	Winter tyres on Light alloy	Continental	4mm / 3mm
2)	235/65 R17 104H	Winter tyres on Light alloy	Continental	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit			

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Acoustic vehicle warning system
- "quattro" all-wheel drive with ultra technology (permanently available all-wheel drive with actively controlled torque distribution, ultra technology and wheel-selective torque control. The system includes an electronically controlled all-wheel drive coupling, a friction clutch integrated into the rear axle differential and an electronic differential lock (EDS) for all driven wheels. The ultra technology allows for a reduction in drag losses in the all-wheel drive system by opening both couplings.)
- Fabric headliner
- Black roof rails with roof rack recognition
- Tachometer
- Rear parking sensors
- Door sill trims with aluminum inlay at the front
- Electromechanical parking brake
- Electronic Differential Lock (EDS)
- Electronic Stability Control (ESC)
- Electric windows front and rear
- Remote key (without Safe-Lock)
- front and rear floor mats
- Cruise control system including speed limiter
- Household plug type E/F (mains connection cable (length 1.6 m, current 10 A) with angled household plug type E/F for the e-tron compact charging system)
- Industrial plug CEE 16A / 400V / long+straight
- Interior mirror dimming
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Rear headrests (3)
- Front headrests
- Mode 3 charging cable (charging cable for charging at public AC charging stations (Type 2). The cable connects the charging station to the vehicle's AC charging port and enables a charging capacity of up to 22 kW (requires additional optional equipment). A current of up to 32 A can be transmitted per phase.)
- Stainless steel loading sill protector
- Light/rain sensor
- Model designation according to new performance labeling
- Otto particulate filter
- Wheel: Tire pressure monitoring system
- Radio: MMI Radio plus
- Radio accessories: Data module Europe
- Electromechanical power steering
- Fabric seat covers (synonym)
- Seats: Rear bench seat plus
- Sun visor on driver and passenger side
- Start-stop system
- Separation net
- Glazing: Windscreen in heat-insulating and acoustic glazing
- thermal insulation glazing
- Airbag: Front side airbags and head airbag system
- Accent areas matte black
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Audi connect emergency call & service with Audi connect Remote & Control
- Audi drive select
- Audi pre sense city
- Electrically adjustable and heated exterior mirrors
- Exterior mirror housings in body color
- Hill descent control
- Roof edge spoiler
- Decorative inlays Micrometallic silver
- e-tron compact charging system (designed for charging at wall sockets, a so-called Mode 2 charging system. It consists of a control unit including a vehicle connection cable and two different mains connection cables (with household and industrial plugs). - Manual switching between 100% and 50% charging power - LEDs indicate the status of the charging system and the charging process. - Charging power at your vehicle up to 7.4 kW.)
- Luggage compartment lid, electrically opening and closing
- Transmission: S tronic 7-speed
- Heated rear window
- rear window wiper
- PHEV hybrid drive system
- Interior lighting
- Manual child lock
- 3-zone automatic climate control (climate control unit with large TFT display and capacitive rocker switches - electronically regulates the air temperature and distribution individually for driver and front passenger - additional climate control unit for setting the rear passenger compartment temperature in the rear center console - automatic recirculation control - dust and odor-removing cabin air filter - residual heat utilization - buttons for defrosting the front and rear windows - with key recognition and humidity sensor)
- LED taillights
- front center armrest
- Non-smoking version
- Wheel: On-board tools (excluding jack)
- Wheel: Tire repair kit (with 12-volt compressor and tire sealant in the luggage compartment, maximum permissible speed 80 km/h)
- Seat belts
- Seats: Standard front seats
- Seats: Front seats manually adjustable
- Stationary air conditioning
- Phone: Bluetooth interface
- First aid kit with warning triangle
- Glazing: Clear glass
- Electronic immobilizer
- black decorative trim

Extra equipment

- Airbag: Front and rear side airbags and head airbag system (Front and rear side airbags and the head airbag system offer additional protection for the occupants)
- Aluminum satellite silver decorative inserts (for instrument panel, door panels and center console)
- Audi virtual cockpit (12.3-inch display with HD resolution - displays: speed, engine speed, map, Audi connect services, radio and media information and much more - specific displays for plug-in hybrid models - operation via the multifunction steering wheel - configuration of on-board computer values - display of the navigation map as a 3D terrain model - permanent display of navigation information - break recommendation)
- Business package (Audi phone box - MMI Navigation plus (incl. driver information system with color display) - Audi virtual cockpit - Heated front seats - Automatically dimming interior mirror - Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides incl. curb view function for the passenger mirror - High beam assist - Manual sunshade for rear door windows)
- Chassis: adaptive air suspension (electronically controlled air suspension with continuously adaptive damping system at all 4 wheels, automatically regulates vehicle level and damping, including level control and manual lift function - setting of various modes via Audi drive select - with 5-link lightweight front axle; controlled shock absorbers and air springs; stabilizer; front axle carrier rigidly bolted to the body - with 5-link lightweight rear axle with independent wheel suspension; controlled shock absorbers and air springs, rear axle carrier)
- Comfort center armrest at the front (adjustable in tilt and longitudinally sliding or completely foldable)
- Comfort key with sensor-controlled luggage compartment unlocking including anti-theft alarm system (The comfort key offers convenient control for access and engine start authorization without having to actively use the vehicle key. With the electronic access and drive authorization system, all doors and the luggage compartment lid can be opened via wireless communication between the key and the vehicle. The engine is started and stopped using the engine start/ stop button.)
- Deletion of model designation and performance/technology lettering
- Front seat heating (for driver and front passenger side, individually adjustable in 3 stages via direct selection button on the climate control unit)
- Glazing: Privacy glazing (tinted windows) for acoustic glazing (tinted rear window, rear door and side windows)
- Industrial plug CEE 16A / 400V (for the e-tron charging system, mains connection cable (length 0.9 m) with industrial plug CEE 16 A, three-phase, red, angled design, for the e-tron compact charging system)
- Paint finish: Metallic
- Camera-based traffic sign recognition (Supports the driver by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions, which are within the detection range of the front camera. The traffic sign recognition is displayed automatically in the digital instrument cluster or in the optional Audi virtual cockpit.)
- Electrically adjustable, heated, and folding exterior mirrors with automatic dimming on both sides (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, convex, flat, or aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb).
- Head-up Display (On request, the speed and other driver-relevant information from optional equipment such as assistance systems and navigation, as well as warning messages, are projected into the driver's direct field of vision - The multi-color display enables a high-contrast presentation - The projection surface of the discreetly integrated head-up display in the instrument panel is adjustable in height and brightness - Includes acoustically coated windshield)
- Headrests: variable headrests for front seats (with manual adjustment of headrest height and distance)
- Hold assist (holds the vehicle indefinitely after stopping on inclines and declines typical in road traffic.)
- Interior design selection package (standard front seats including seat covers in leather/artificial leather mono.pur 550 combination with contrast stitching - 3-spoke leather steering wheel with multifunction plus - aluminum satellite silver decorative inlays - illuminated front door sill trims with aluminum inlays - interior elements in artificial leather, color-coordinated with the respective interior color - ambient lighting package plus - front and rear velour floor mats in black)
- LED headlights: Matrix LED headlights with dynamic light display and dynamic turn signals (multifunction camera - headlight cleaning system). Front and rear LED headlights with the following functionalities: - visually enhanced daytime running lights - low beam - high beam - position lights - turn signals - cornering lights - all-weather lights - maneuvering lights - motorway lights - automatic dynamic headlight range control - static cornering lights - dynamic light display for coming home/leaving home functions.
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound (19 speakers (including center speaker/subwoofer and additional 3D sound tweeters and midrange drivers) - 16-channel amplifier with 755 watts - illuminated front speaker grilles - speed-dependent volume adjustment - spatial sound reproduction thanks to the new 3D sound feature. This is created by additional speakers in the A-pillar, by the midrange drivers and by Fraunhofer Symphoria technology.)
- Seats: Front seats electrically adjustable (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt)

- Proactive occupant protection front, reversing camera and parking aid plus (Audi pre sense basic - reversing camera - parking aid plus)
- Radio accessories: USB charging ports for rear passengers (two USB-A charging ports for rear passengers in the rear center console)
- Seat covers in fine nappa leather design selection (seat center panel, seat side bolsters, headrests and center armrest in fine nappa leather with contrasting stitching and piping in contrasting color - floor mats in granite grey)
- Seats: Front sports seats
- Seats: Lumbar support for the front seats, electric (4-way) (horizontally and vertically adjustable)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction plus (with 14 multifunction buttons for convenient operation of the available infotainment features such as audio skip, telephony, NAV button or the freely programmable button - adjustable in height and distance - with full-size airbag - shift paddles for manual changing of the driving modes)
- Telephone: Audi Phone Box (features as Audi phone box light; additional functions: The Audi phone box includes: - Bluetooth interface - Hands-free system - Coupling antenna for connecting the mobile phone to the external antenna for improved reception quality and reduced mobile phone radiation in the vehicle interior - LTE support - Charging option via USB port or wireless charging (Qi standard) - Forgetfulness warning - Charging status display in the MMI touch display - Connection of 2 mobile phones)
- Tour Assistance Package (adaptive cruise control - traffic jam assist - Audi active lane assist - predictive efficiency assist - Audi pre sense front - evasive steering assist - left turn assist - high beam assist - camera-based traffic sign recognition)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheel: Winter wheels with light alloy rims, 17" 10-spoke (7.0 J x 17, winter tires 235/65 R 17 suitable for snow chains, maximum permissible speed 210 km/h)
- Stationary climate control (comfort) (it cools or heats the interior to a desired temperature before driving, ensuring a very high level of climate comfort right from the moment you enter the vehicle. Seat heating and ventilation, as well as glass surface heating, can also be activated before driving if these optional features have been selected. The comfort stationary climate control, including the desired temperature, can be programmed or activated via the MMI and can also be conveniently switched on using a smartphone app, ...)
- Storage and luggage compartment package (flexible transport of items and comfort while traveling; consisting of: - storage net on the back of the front seatbacks - cup holder in the rear center armrest - storage compartment on the driver's side - lockable glove compartment in the luggage compartment: - luggage compartment net - net in the recess on the left - tension strap on the trunk side (not available for SQ5 Sportback))
- Telephone: Audi Smartphone Interface in conjunction with Business Package or MMI Navigation (The Audi smartphone interface (Android Auto and Apple CarPlay) connects your smartphone to your Audi and seamlessly displays your smartphone content directly on the MMI display via USB. Navigation, telephony, music, and selected third-party apps can be conveniently controlled via the MMI touchscreen and voice control on your smartphone.)
- Towbar (ball head mechanically swiveling with electric release - ball rod and head made of forged steel - operation via push button in the luggage compartment - trailer stabilization via the electronic stability control (ESC) The integrated swiveling system socket allows continuous operation of electrical devices in the trailer or caravan while driving and can be swivelled invisibly behind the bumper apron when not in use)
- Wheel: Light alloy wheels, 19" 5-spoke V, graphite grey, polished (8.0 J x 19, tires 235/55 R 19)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Roof	Roof rail - right side - Scratched - Smart repair
3	Rear bumper	Rear bumper - Scratched - Smart repair
4	Rear bumper	Spoiler - Scratched - Smart repair
5	2nd wheel set	1 tyre - Does not meet the leasing specifications - Replace
6	2nd wheel set	1 tyre - Does not meet the leasing specifications - Replace
7	Wing mirror - left side	Mirror bracket - Scratched - Loss in value

Wear and tear

No.	Component group	Description
1	Door - front right side	Door edge - Scratch(es) - No deduction
2	Door - front left side	Door edge - Scratch(es) - No deduction
3	Door - rear left side	Door edge - Scratch(es) - No deduction
4	Side panel - rear left side	Side panel - Scratch(es) - No deduction
5	Bonnet	Bonnet - dent(s) - No deduction
6	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit filler

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Das Fahrzeug weißt im ganzen erhöhte Lackschichtendicke Werte auf.

- Bei dem Fahrzeug lag nur eine Zulassungsbescheinigung Teil II vor die nach Zulassung im Ausland ausgestellt wurde, die Halteranzahl des Fahrzeugs kann nicht eindeutig ermittelt werden



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 2: Roof: Roof rail - right side - Scratched - Smart repair




Damage 2: Roof: Roof rail - right side - Scratched - Smart repair



Damage 2: Roof: Roof rail - right side - Scratched - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 4: Rear bumper: Spoiler - Scratched - Smart repair



Damage 4: Rear bumper: Spoiler - Scratched - Smart repair




Damage 5: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 5: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 6: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 6: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 6: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 6: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 6: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 7: Wing mirror - left side: Mirror bracket - Scratched - Loss in value



Damage 7: Wing mirror - left side: Mirror bracket - Scratched - Loss in value



Missing part 1: Equipment: Tirefit filler - Missing - Replace