ARVAL
BNP PARIBAS GROUP

2EDS491

INSPECTION REPORT



End of contract

GENERAL INFO

File	323186
License plate	2EDS491
Vehicle identification number	ZFA3120000JD18733
Dossier	2019301233
Make	Fiat 500 0.9T 85pk Lounge
Mileage	106550
First registration	27/01/2020
client availability date	30/09/2026
inspectionDate	12/10/2026






CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	


0
Cruise Control
désarmé


2-EDS-491
KEURING
BELCAR

DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
265	Foglight Front Right // Replace	N
801	See External Expertise	N
801	See External Expertise	N
136	Bumper Rear // Polish	Y
181	Wing Rear Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y


Damage Pictures




Wing Rear Right // Smart Repair Medium-dent




Door Front Right // Painting-scratch






Side View Mirror Right // Painting-scratch






Bumper Rear // Polish-scratch

Wheel Alloy Front Left // Repair-scratch




Wheel Alloy Front Right // Repair-scratch





Dashboard / Steering Wheel / Replace-scratch









Bumper Front // Painting-scratch

Foglight Front Right // Replace-scratch













See External Expertise-dent











See External Expertise-dent