APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	ASSE I
Make:	AUDI
Model / version:	A6 FRONT
Wine:	WAUZZZF27PN025689
Plate:	2CTQ849
Mileage:	174043
SOH:	
First registration:	23/11/2022
Color:	FIRMAMENT BL

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓


PICTURES























































WINE INFORMATION

10 Speakers	Sequential transmission	7 reports
5 doors	Break	Material: alloy
Reference letter (J)	Front diameter 18	Rear diameter 18
Front width 8.0	Rear width 8.0	Front diameter 18
Rear diameter 18	Front height 55	Rear height 55
Forward speed index H	Rear speed rating H	Front width 225
Rear width 225	Air conditioning refrigerant 1234YF	Front center armrest
Metallic varnished	Front disc brakes	Rear disc brakes
Electrically adjustable left-side mirror	Electrically adjustable right-side mirror	Left-hand rearview mirror with memory setting
Right-hand rearview mirror with memory setting	Convex left-hand rearview mirror	Convex right-hand rearview mirror

Left rearview mirror aspherical	Right-hand aspherical rearview mirror	Electrically folding mirrors
Automatic day/night interior rearview mirror	Electrically adjustable front left seat	Electrically adjustable front seats
Front left seat with memory settings	Front left seat with lumbar adjustment	Front seats with lumbar adjustment
Leather and imitation leather trim	Front parking assistance	Rear parking assistance
Front camera	Rearview camera	Cruise control and speed limiter
Displaying and reading road signs	Hands-free card	Electrically operated trunk opening
Emergency call	Passenger airbag	Passenger airbag can be deactivated
Pedestrian protection	Lane departure warning (LDW)	Exhaust gas treatment with SCR catalyst (AdBlue)
since 10.22	black window moldings	radio with digital receiver
heated front seats	separate files	lighting pack
Euro 6 AP anti-pollution standard	1968 cc (2.0 L) 120 KW	M-HEV hybrid transmission

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	3 mm			Summer	Aluminum	?
Front right	3 mm			Summer	Aluminum	?
Rear left	3 mm			Summer	Aluminum	?
Rear right	3 mm			Summer	Aluminum	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
2	Bumper F	Scratches
3	Outside rear-view mirror housing L	Scratches
4	Alloy rim RL	Scratches
5	Boot lid covering R	Dirty
6	Bumper R	Scratches
7	Outside rear-view mirror housing R	Scratches

Total: 6

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Damaged	✓	✗	✗


Total: 1

DAMAGE DETAILS

2 - Bumper F - Scratches




3 - Outside rear-view mirror housing L - Scratch(es)

4 - Alloy rim RL - Scratch(es)






5 - Boot lid covering R - Dirty





6 - Bumper R - Scratches






7 - Outside rear-view mirror housing R - Scratch(es)





1 - Bodywork - Damaged - Renta®










SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

03/11/2026 13:30