TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum: 21.10.2026
Protokollnummer: 48394203
Erstellt durch: Markus Böttcher
Besichtigt durch: Canziba

ZFAEFAG45PX136894

Angaben zum Fahrzeug

Halter		**Besichtigungszustand**	bedingt: Licht/Nässe/Schmutz
Kennzeichen		**Laufleistung (abgelesen)**	17.095 km
Hersteller	Fiat	**Restlauf bis Service**	0 Tag(e)
Typ/Modell	500	**HU (Bericht lag vor)**	11/2027
Fahrgestellnummer	ZFAEFAG45PX136894	**Leistung**	43 kW
Erstzulassung	30.03.2023	**Polster/Farbe**	Stoff / Schwarz
Letzte Wartung	05/2025, 9.414 km	**Lackierung**	Weiß
Kraftstoffart	Elektro	**Getriebe**	Automatik

Zustandsbericht

Wertmindernde Faktoren

Nr.	Bauteilgruppe	Beschreibung
1	Rad/Reifen	Leichtmetallfelge vorn rechts - Kratzer - Wertminderung
2	Instrumententafel	Kombiinstrument (SOS Sytsem) - leuchtet - Diagnose durchführen
3	Sonstiges	Inspektion/Wartung (Intervall 1Jahr/15tkm - 1. service) - kein Nachweis - Wertminderung
4	Sonstiges	Inspektion/Wartung - fällig - durchführen

Gebrauchsspuren

Nr.	Bauteilgruppe	Beschreibung
Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.		

Fehlteile

Fehlteil

Vorschäden

Nr.	Vorschaden
1	Seite rechts, augenscheinlich nicht erkennbar, Reparaturrechnung nicht vorhanden

Festgestellte Nachlackierungen

Nr.	Ort
1	Dachholm rechts, Kotflügel rechts, Seitenwand rechts, Tür vorne rechts, fachgerecht ausgeführt, Reparaturrechnung nicht vorhanden

Hauptbereifung

Achse	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Verktgl.	Zul.
1	195/55 R16 91V	Goodyear	Sommerreifen	7mm - 7mm	i.O.	i.O.
2	195/55 R16 91V	Goodyear	Sommerreifen	7mm - 7mm	i.O.	i.O.

Der Verschleißzustand sowie evtl. Schäden an der Bereifung sind wertmäßig berücksichtigt.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum:	21.10.2026
Protokollnummer:	**48394203**
Erstellt durch:	Markus Böttcher
Besichtigt durch:	Canziba

Angaben zum Fahrzeug

Hersteller	Fiat	**Besichtigungszustand**	bedingt: Licht/Nässe/Schmutz
Typ/Modell	500	**Laufleistung (abgelesen)**	17.095 km
Fahrgestellnummer	ZFAEFAG45PX136894	**Erstzulassung**	30.03.2023

Angaben zum Auftrag:
Auftragsgemäß erfolgte die Fahrzeugzustandsbewertung in demontagefreien Zustand.

Grundlage dieses Produktes stellt der Leitfaden für Fahrzeugrücknahmen und Bewertungen gemäß des Schadengrenzmusterkatalog des Auftraggebers dar. Die expliziten Feststellungen im Einzelfall trifft der Sachverständige objektiv im Rahmen der vorgegebenen Standards aufgrund eigener Sachkunde.

Fahrzeug-Identifizierung:
Die Fahrzeug-Identifizierungsnummer (FIN) wurde am Fahrzeug abgelesen und die Übereinstimmung im Verlauf der Besichtigung durch den Unterzeichner mit den vorgelegten Unterlagen festgestellt.

Besichtigungsbedingungen:
Eine ordnungsgemäße Sichtprüfung der Lackierung und der Karosserie war wegen unzureichender Lichtverhältnisse/ Nässe oder Verschmutzung nur eingeschränkt möglich.

Allgemeinzustand:
Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.



Unterschrift Sachverständiger (Markus Böttcher)

Vorliegendes Druckexemplar wurde auf elektronischem Wege erzeugt. Der benannte Sachverständige versichert, dass der Inhalt die von ihm getroffenen Feststellungen korrekt wiedergibt. Es ist ohne Originalunterschrift gültig.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum:	21.10.2026
Protokollnummer:	**48394203**
Erstellt durch:	Markus Böttcher
Besichtigt durch:	Canziba

Übersichtsfotos




Abbildung 1: FIN



Abbildung 2: Schräg vorne



Abbildung 3: Schräg vorne



Abbildung 4: Schräg hinten



Abbildung 5: Schräg hinten



Abbildung 6: Montierte Bereifung



Abbildung 7: Innenraum vorne



Abbildung 8: Laderaum



Abbildung 9: Kombiinstrument



Abbildung 10: Kombiinstrument



Abbildung 11: Instrumententafel



Abbildung 12: Instrumententafel



Abbildung 13: Dokumente



Abbildung 14: Sonstiges

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum: 21.10.2026
Protokollnummer: 48394203
Erstellt durch: Markus Böttcher
Besichtigt durch: Canziba

Beschädigungsfotos




Beschädigung #1: Rad/Reifen: Leichtmetallfelge vorn rechts - Kratzer - Wertminderung



Beschädigung #1: Rad/Reifen: Leichtmetallfelge vorn rechts - Kratzer - Wertminderung



Beschädigung #2: Instrumententafel: Kombiinstrument (SOS Sytsem) - leuchtet - Diagnose durchführen



Beschädigung #3: Sonstiges: Inspektion/Wartung (Intervall 1Jahr/15tkm - 1. service) - kein Nachweis - Wertminderung



Beschädigung #4: Sonstiges: Inspektion/Wartung - fällig - durchführen

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum:	21.10.2026
Protokollnummer:	**48394203**
Erstellt durch:	Markus Böttcher
Besichtigt durch:	Canziba

Nachlackierungfotos



Nachlackierung 1: Dachholm rechts, Kotflügel rechts, Seitenwand rechts, Tür vorne rechts



Nachlackierung 1: Dachholm rechts, Kotflügel rechts, Seitenwand rechts, Tür vorne rechts



Nachlackierung 1: Dachholm rechts, Kotflügel rechts, Seitenwand rechts, Tür vorne rechts



Nachlackierung 1: Dachholm rechts, Kotflügel rechts, Seitenwand rechts, Tür vorne rechts

4. OVC hybrid electric vehicles: WLTP values

CO_2 emissions:

charge-sustaining					charge-depleting	
Low	Medium	High	Extra High	Combined	Combined	
-	-	-	-	-	-	g/km

Fuel consumption:

charge-sustaining					charge-depleting	
Low	Medium	High	Extra High	Combined	Combined	
-	-	-	-	-	-	-

Electric Consumption (EC):

Low	Medium	High	Extra High	City	Combined	
-	-	-	-	-	-	Wh/km

Weighted combined values:

	CO_2 emissions	Fuel consumption	Electric Consumption (EC_{AC})
-	- g/km	- -	- Wh/km

5. Electric range of OVC hybrid electric vehicles

Equivalent All Electric Range (EAER):	-	km
Equivalent All Electric Range city (EAER city):	-	km
All Electric Range (AER):	-	km
All Electric Range city (AER city):	-	km

Miscellaneous

51. For special purpose vehicles: designation in accordance with Annex II Section 5 of 2007/46/EC / point 5 of Part A of Annex I to Regulation (EU) 2018/858 of the European Parliament and of the Council:
-

52. Remarks:
-

Additional tyre/wheel combinations: technical parameters (no reference to RR)

Axle1: 185/65R15 88T 6Jx15-40 -	Axle2: 185/65R15 88T 6Jx15-40 -	; or
Axle1: 205/45R17 88V 6,5Jx17-41 -	Axle2: 205/45R17 88V 6,5Jx17-41 -	

Protocol Number
F: M10FATVP300R722
00 291

D: AVN000378

808a8a6096a330966c0e93583eb3236155cabe88

FCA
FIAT CHRYSLER AUTOMOBILES

046CC0146582

www.PS-Team.de

EC CERTIFICATE OF CONFORMITY

3110/91717690 0122034

2023-VHS-000593286

The undersigned **ENRICO BECCHIO PRODUCTION MANAGER** hereby certifies that the vehicle:

0.1. Make: **FIAT**
0.2. Type: **FA1** Variant: **1AEA0000A0** Version: **1D2B0**
0.2.1. Commercial name: **500**
0.2.2.1. Allowed Parameter Values for multistage type approval to use the base vehicle emission values:

Final Vehicle actual mass:	-	kg
Final Vehicle technically permissible maximum laden mass:	-	kg
Frontal area for final vehicle:	-	cm^2
Rolling resistance:	-	kg/t
Cross-sectional area of air entrance of the front grille:	-	cm^2

0.2.3. Identifiers: -
0.2.3.1. Interpolation family's identifier: **IP-03_FA1_0234-ZFA-1**
0.2.3.2. ATCT family's identifier: -
0.2.3.3. PEMS family's identifier: -
0.2.3.4. Roadload family's identifier: **RL-03_FA1_0093-ZFA-1**
0.2.3.5. Roadload Matrix family's identifier: -
0.2.3.6. Periodic regeneration family's identifier: -
0.2.3.7. Evaporative test family's identifier: -
0.4. Vehicle category: **M1**
0.5. Company name and address of manufacturer:
FCA Italy S.p.A. C.so G. Agnelli 200 - 10135 - Turin - Italy
0.6. Location and method of attachment of the statutory plates:
ON B PILLAR, LEFT VEHICLE SIDE ADHESIVE
Location of the vehicle identification number: **ON THE RIGHT SIDE OF THE FLOOR. IN THE FRONT PART OF THE PASSENGER COMPARTMENT**
0.9. Name and address of the manufacturer's representative (if any):
- -
0.10. Vehicle identification number: **ZFAEFAG45PX136894**
0.11. Date of manufacture of the vehicle: **03/02/2023**

conforms in all respects to the type described in approval **e3*2018/858*00001*09** granted on: **21/11/2022**
and can be permanently registered in Member States having **RIGHT** hand traffic and using **METRIC** units for the speedometer and **METRIC** units for the odometer.

Place: **TURIN** Date: **03/02/2023**

Enrico Becchio

Signature

Für dieses Dokument wurde eine Zulassungsbescheinigung Teil II (GQ249462) ausgegeben. Landratsamt München

General construction characteristics

1. Number of axles: **2**
   and wheels: **4**
3. Powered axles (number, position, interconnection):

1 FRONT -

3.1. Specify if the vehicle is: **non-automated**

Main dimensions

4. Wheelbase: **2322** mm
4.1 Axle spacing:
   1-2: **2322** mm
5. Length: **3631** mm
6. Width: **1683** mm
7. Height: **1529** mm

Masses

13. Mass in running order: **1405** kg
13.2. Actual mass of the vehicle: **1429** kg
16. Technically permissible maximum masses:
16.1. Technically permissible maximum laden mass: **1730** kg
16.2. Technically permissible mass on each axle:
   1. **920** kg
   2. **840** kg
16.4. Technically permissible maximum mass of the combination: **1730** kg
18. Technically permissible maximum towable mass in case of:
18.1. Drawbar trailer: - kg
18.3. Centre-axle trailer: - kg
18.4. Unbraked trailer: - kg
19. Technically permissible maximum static vertical mass at the coupling point: - kg

Power plant

20. Manufacturer of the engine:

GKN

21. Engine code as marked on the engine:

46348460

22. Working principle:

- -

23. Pure electric: **YES**
23.1. Class of Hybrid [electric] vehicle: -
24. Number and arrangement of cylinders:

- -

25. Engine capacity: - cm^3
26. Fuel: -
26.1. -
26.2. (Dual-fuel only) Type -
27. Maximum power
27.1. Maximum net power: (internal combustion engine)

- - kW at - min^{-1}

27.3. Maximum net power: (electric motor) **87** kW
27.4. Maximum 30 minutes power: (electric motor) **43** kW
28. Gearbox (type):

AUTOMATIC SINGLE SPEED

28.1. Gearbox ratios

1st gear	**1**
2nd gear	-
3rd gear	-
4th gear	-
5th gear	-
6th gear	-
7th gear	-
8th gear	-
9th gear	-

28.1.1. Final drive ratio: **1:9,559**
28.1.2. Final drive ratios

1st gear	**1:9,559**
2nd gear	-
3rd gear	-
4th gear	-
5th gear	-
6th gear	-
7th gear	-
8th gear	-
9th gear	-

Maximum speed

29. Maximum speed: **150** km/h

Axles and suspension

30. Axle(s) track:
   1. **1470** mm
   2. **1460** mm
35. Fitted tyre/wheel combination/ energy efficiency class of rolling resistance coefficients (RRC) and tyre category used for CO_2 determination:

Axle1: 195/55R16 91V 6Jx16-41 - A C1

Axle2: 195/55R16 91V 6Jx16-41 - A C1

Brakes

36. Trailer brake connections: -

Bodywork

38. Code for bodywork: **AB - Hatchback**
40. Colour of vehicle: **WHITE**
41. Number and configuration of doors: **2**

2 FRONT SIDE

42. Number of seating positions (including the driver): **4**
42.1. Seat(s) designated for use only when the vehicle is stationary: -
42.3. Number of wheelchair user accessible position: -

Environmental performances

46. Sound level

Stationary:	at engine speed:	Drive-by:
- dB(A)	- min^{-1}	**69** dB(A)

47. Exhaust emission level: **EURO 6 AX**
47.1. Parameters for emission testing of V_{ind}
47.1.1. Test mass, kg: **1494**
47.1.2. Frontal area, m^2: -
47.1.2.1. Projected frontal area of air entrance of the front grille, cm^2: -
47.1.3. Road load coefficients
47.1.3.0. f0, N: **93**
47.1.3.1. f1, N/(km/h): **0.227**
47.1.3.2. f2, N/(km/h)²: **0.03383**
47.2. Driving cycle:
47.2.1. Driving Cycle class: **3B**
47.2.2. Downscaling factor (f_{dsc}): -
47.2.3. Capped speed: -
48. Exhaust emissions:

Number of the base regulatory act and latest amending regulatory act applicable:

715/2007*2018/1832AX

1.2. Test procedure: **ELE WLTP**

	-	
CO	-	-
THC	-	-
NMHC	-	-
NO_x	-	-
$THC+NO_x$	-	-
NH_3	-	-
Particulates (mass)	-	-
Particles (number)	-	n./km

48.1. Smoke corrected absorption coefficient: - - m^{-1}
48.2. Declared maximum RDE values:

	-	
Complete RDE trip: NO_x :	-	mg/km
Particles (number) :	-	n./km
Urban RDE trip: NO_x :	-	mg/km
Particles (number) :	-	n./km

49. CO_2 emissions/fuel consumption/electric energy consumption:

1. All powertrains, except OVC hybrid electric

CO_2 emissions:

	-	
Low	-	g/km
Medium	-	g/km
High	-	g/km
Extra High	-	g/km
Combined	-	g/km

Fuel consumption:

	-
Low	-
Medium	-
High	-
Extra High	-
Combined	-

Electric Consumption (EC_{AC}):

Low	**95**	Wh/km
Medium	**97**	Wh/km
High	**115**	Wh/km
Extra High	**176**	Wh/km
Combined	**146**	Wh/km

2. Electric range of pure electric vehicles

Electric range: **305** km

Electric range city: **429** km

3. Vehicle fitted with eco-innovation(s): **NO**

3.1. General code of the eco-innovation(s): -

3.2. Total CO_2 emissions savings due to the eco-innovation(s):

3.2.2. WLTP saving: -
- g/km

MOBILITY CONCEPT

LVV Nr	505624
Hersteller	Fiat
Model	500
Variante	null
Listenpreis	16.898,17
VIN	ZFAEFAG45PX136894
Erstzulassungsdatum	30.3.2023
Kennzeichen	STA-B 892E

Schadensfälle der int. Belegnummer: 5567313 04.11.2026

Schadennummer	Unfalldatum	Beschädigung	Schadenhöhe in EUR
2023117855	07.12.2023	| Beifahrerseite Seitenteil hinten| Beifahrerseite Tür vorne	6.230,56

Mobility Concept GmbH
Grünwalder Weg 34
D-82041 Oberhaching
Telefon +49 89 63266-0
Telefax +49 89 63266-266

E-Mail:leasing@mobility-concept.de
Internet: www.mobility-concept.de
Geschäftsführer:
Rudolf Rizzolli, CEO (Vorsitzender)
Marc-Oliver Bucksch, CFO

Sitz der Gesellschaft: Oberhaching
Amtsgericht München HR B 130788
Bankverbindung: UniCredit Bank AG
IBAN: DE29 7002 0270 0002 4960 11
Swift (BIC): HYVEDEMMXXX

Steuer-Nr.: 143/163/41358
USt-IdNr.: DE 813336066
Aufsichtsbehörde: Bundesanstalt für
Finanzdienstleistungsaufsicht
Graurheindorfer Str. 108, 53117 Bonn