TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48419138
Order No. / Reference: 27162698
Inspection date: 30 Oct 2026

Manufacturer: Peugeot

Model: 508 SW Plug-In Hybrid 360 e-EAT8 PEUGEOT SPORT ENGINEERED

VIN: VR3F45GBTPY590775





Vehicle details

Manufacturer / Type / Model / Equipment	
Peugeot 508 SW Plug-In Hybrid 360 e-EAT8 PEUGEOT SPORT ENGINEERED	
Vehicle Identification number	VR3F45GBTPY590775
Mileage (Read)	87,628 km
First registration	11 Oct 2023
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,598 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Okenit Weiß Metallic
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	11 Monat(e)
Last service on / at	09/2026 at 86,149 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ770057
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADV 00018		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,340 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/35 R20 95Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	245/35 R20 95Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/35 R20 95W	Winter tyres (Without wheel rim)	Hankook	7mm / 7mm
2)	245/35 R20 95W	Winter tyres (Without wheel rim)	Hankook	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS (Anti-lock Braking System)
- Airbag for driver and front passenger
- Airbag: Curtain airbags front and rear
- Alarm system
- ACC automatic cruise control with STOP & GO function
- Electrically adjustable, heated and folding exterior mirrors
- Illuminated glove compartment
- Turn signals with lane change indicator function
- third brake light
- Roof rails in high-gloss black
- Digital instrument cluster with high-resolution 12.3" screen, adjustable and customizable
- Rear parking aid, acoustic and visual
- Entry sills in black anodized aluminum
- Chassis: Active Suspension Control (adaptive chassis control)
- electric parking brake
- Front collision warning
- Guide rails in the trunk
- Transmission: 8-speed automatic transmission EAT8
- Seat belts: 3-point safety belts in all seats
- Heated rear window
- Rear apron with diffuser look in black
- Interior mirror automatically dimming
- Map pockets on the front seatbacks
- Manual child lock
- Height-adjustable headrests
- Paint finish: Metallic Selenium Grey
- LED ambient lighting in the front footwell
- Blue LED ambient lighting on the dashboard
- LED lighting in the front footwell
- LED taillights with dynamic illumination of the three claws
- LED daytime running lights
- Steering wheel: Paddle shifters on the steering wheel
- makeup mirror
- Front center armrests with illuminated storage compartment
- Fatigue warning system with fatigue detection
- Night Vision
- On-board charger 7.4 kW, 1-phase
- Aluminum pedals and stainless steel door sills
- Peugeot i-Connect Advanced:
- Upholstery: Decorative stitching in Kryptonite and Tramontane Grey on the dashboard, steering wheel and floor mats
- Tire pressure monitoring system
- Wheels: 20" "Exxar" alloy wheels, two-tone
- Reversing camera with 360° surround view
- Seats: Passenger seat height adjustable
- Seats: Driver's seat height adjustable
- Seats: Rear seats
- Seats: Front seats
- Lane keeping assist with steering intervention
- Active Safety Brake Plus
- Airbag: Side airbag
- Active Blind Spot Assist
- Permanent all-wheel drive
- Automatically dimming exterior mirror, driver's side
- Exterior mirrors in Perla Nera Black
- Hill start assist
- On-board computer
- Black headliner
- Decorative inlays made of real wood "Zebrano"
- Dual exhaust with chrome-plated tailpipes
- EBV (Electronic Brakeforce Distribution)
- Front parking aid, acoustic and visual
- Electronic Stability Program (ESP)
- Electric windows front and rear
- High beam assist
- Follow-me-home function (automatic)
- front and rear floor mats
- luggage compartment roller blind
- Cup holder in the center console
- electric tailgate
- rear window wiper
- Inductive charging station (15W)
- Frameless interior mirror
- Keyless system
- Automatic climate control (2-zone)
- Radiator grille with floating louvers
- Charging cable: Mode 2 charging cable (Type 2, up to 2.3 kW), 6 meters long
- Blue LED ambient lighting on the front door panels
- LED ceiling lighting at the front
- LED matrix headlights
- Steering wheel: Multifunction leather steering wheel
- light sensor
- Rear center armrest with pass-through flap
- Multifunctional touchscreen with 10-inch HD color display
- Multimedia: Mirror Screen
- Navigation system: 3D navigation system NAC
- Emergency brake assist
- Particle filter: OPF (Otto particulate filter)
- Peugeot Connect Box
- Upholstery: Full leather/fabric/Alcantara Black
- PSE monogram on the hood
- Radio accessories: FOCAL sound system
- Rain sensor
- Wheels: Anti-theft wheel bolts
- Wheels: Tire repair kit (compressor + tire sealant spray)
- Electric power steering
- Seats: Ergonomic comfort seats with AGR seal of approval
- Seats: Rear bench seat and backrest 40/60 split folding

- 12-volt socket
- Glazing: Laminated glass windshield, noise-reducing
- Pre-installation for luggage compartment partition net
- Central locking can be activated from inside using a remote control.
- Seats: Heated front seats
- Sport mode
- Lane Positioning Assistant
- Technical Plug-In Hybrid Version
- Traffic sign recognition
- Immobiliser
- Decorative trim in high-gloss black on the side windows

Extra equipment

- Trailer hitch
- Package: Holiday Package (panoramic tilt/slide sunroof with electric blind - heated windscreen)
- Paint finish: Metallic

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
2	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
3	Wheel / tyres	Alloy rim - front left side - Scratched - Replace
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Body	A-pillar - right side - Stone chips - No deduction
3	Door - rear left side	Door handle - outside - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 6 Dec 2023	8.901,34 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Winter - Radsatz ist kein Bestandteil des Lieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Wear and tear 3: Door - rear left side: Door handle - outside - Scratch(es) - Cover / polish



Wear and tear 3: Door - rear left side: Door handle - outside - Scratch(es) - Cover / polish